Truck Service Summary – Unit U13631

2017 Landoll 930D

Inspection & Preparation

- Completed Charter trailer 90-day inspection
- Greased chassis during inspection

Mechanical Repairs

- Replaced all four worn, leaking oil hubcaps
- Repaired broken dock lift-arm air lines
- Refilled hydraulic reservoir

Electrical & Lighting

- Repaired license plate light wiring
- Installed a new license plate light
- Replaced burned-out rear ICC 3/4-in. LED

Cab & Interior

Exterior & Visibility

- Installed new Charter mudflaps
- Washed trailer
- Removed exterior stickers

Add-Ons & General Service

- Installed chrome kit
- Replaced stainless flanged hardware
- Installed eight new valve stems
- Installed eight flow-through valve caps

Additional Work Performed

- Installed eight new Rovelo 235/75R17.5 tires

Final Service

- Completed hydraulic remote testing
- Completed tire and valve hardware service
- Finished wash and sticker removal
- Documented all completed service work

Vehicle Details

- Unit: U13631
- Equipment: trailer
- 2017 Landoll 930D

Summary

U13631 received a 90-day trailer inspection, chassis lubrication, hubcap/air-line repairs, lighting and mudflap replacement, eight new tires with valve hardware, hydraulic checks, chrome/hardware updates, and wash/detail service with sticker removal.

Eliminate downtime. If the wheels aren't turning, you're not earning.

Total Reconditioning Investment: **$4,797.29**

Source: scanned invoice packet, all 8 pages reviewed visually.

Truck Service Summary - Unit U13631

2017 Landoll 930D

Inspection & Preparation

- Completed Charter trailer 90-day inspection
- Greased chassis
- Completed wash and removed stickers
- Prepared unit for sale-ready presentation

Electrical & Lighting

- Repaired license-plate light wiring and lamp
- Replaced four work lights
- Replaced rear ICC 3/4-inch LED light
- Replaced button lights around trailer

Exterior & Visibility

- Replaced trailer mudflaps with Charter flaps
- Installed chrome kit

Additional Work Performed

- Verified hydraulic remote operation

Vehicle Details

Mechanical Repairs

- Repaired trailer frame with new material
- Repaired broken dock-lift arm air lines
- Tested trailer hydraulic remotes

Cab & Interior

- Not provided

Add-Ons & General Service

- Replaced eight 235/75R17.5 trailer tires
- Replaced tire valve stems and flow-through caps
- Installed replacement hardware as needed

Final Service

- Completed final lighting replacements
- Completed tire and chassis service
- Confirmed hydraulic system operation
- Returned unit to sale-ready condition

Summary

U13631 received a 90-day inspection, chassis grease service, frame and air-line repairs, extensive trailer lighting repairs, hydraulic checks, eight replacement tires , mudflaps, chrome hardware, and a full wash/detail with sticker removal.

Total Reconditioning Investment: **$6,241.29**

Source: scanned invoice packet, pages reviewed visually.