Truck Service Summary - Unit U13663

2017 Landoll 930C

Inspection & Preparation

- Completed trailer 90-day inspection
- Connected air, electrical and hydraulic lines
- Verified lights, hydraulics and air operation
-

Mechanical Repairs

- Not provided in invoice packet

Electrical & Lighting

- Repaired broken license-plate-light wiring
- Installed 26 button lights
- Rewired front R/S light cable
- Verified trailer lights during inspection

Cab & Interior

- Not provided in invoice packet

Exterior & Visibility

- Completed exterior detail
- Removed decals where applicable

Add-Ons & General Service

- Greased trailer during 90-day inspection
- Checked tire air pressures

Additional Work Performed

- Connected and checked trailer operating systems
-

Final Service

- 90-day inspection completed
- License plate light repair verified OK
- Lighting installation/rewire completed
- Exterior prepared for sale-ready presentation

Vehicle Details

- VIN: 1LH930VH7H1D24114

Summary

U13663 received a trailer 90-day inspection, exterior detail and decal removal, license-plate-light wiring repair, and additional lighting installation/rewiring. Trailer air, electrical, hydraulic, lighting and operating systems were checked as documented, with final repairs verified and the unit prepared for presentation.

Total Reconditioning Investment: **$2,183.05**

Source: scanned invoice packet, all 6 pages reviewed visually.

CCTE

Retail T

PREVENTIVE MAINTENANCE SERVICE & INSPECTION - Trailer

T - Service & Inspection

CUSTOMER / FLEET NAME	DATE	HUBODOMETER / ENGINE HOURS / FUEL	REPAIR ORDER #
Charter	8/28/26		91540

ADDRESS	UNIT NO	VIN # (LAST 7 DIGITS)	TRAILER MAKE & MODEL
	413663	H1D24114	

CITY, STATE / PROVINCE, ZIP / POSTAL CODE	PHONE	DEALER NAME & CODE
		CCTE Windsor C506


COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

√ = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = Not Applicable

CIRCLE INSPECTION		HUBS, TIRES & WHEELS	
Inspect SAE J560 Seven-Pin Connector Receptacle	√	Check Hubcap for Leaks	√
Inspect Glandhands	√	Check Axle Lubricant Level	√
Check Operation of All Lights and Reflectors	√	Check for Missing Valve Caps / Tighten Stem Locks	√
Inspect Wiring Harness(es)	√	Inspect for Cracked or Damaged Wheels	√
Check All Rivets and Fasteners on Bottom Rail	√	Check for Loose or Missing Wheel Lugs / Nuts	√
Inspect Rear Bumper / Underride	√	Check Hub Odometer Reading (Record Above)	N
Inspect Mud Flaps and Brackets / Serviceable	√	Check for Irregular Wear Patterns, Flat Spots	√
Check License Plate and Mounting	√	Check for Cuts, Gouges, Cracks & Sidewall Damage	√
Inspect Pintle Hook	N	Check Tandem Mating	√
Inspect SAE J560 Seven-Pin Connector Receptacle (Double, Triples)	N	Check Tread Design Match	√
Inspect Glandhands (Doubles, Triples)	N	Tire Pressure (Record Below)	√
UNDERCARRIAGE & SUSPENSION		Remaining Tread (Record Below)	√
Inspect Upper 5th Wheel Plate and Kingpin	√		
Inspect Wiring Harness(es) and Air Lines	√		
Inspect Trailer Landing Gear (Legs, Braces & Supports)	√		
Inspect Trailer Landing Gear (Crank Handle & Retaining Clip)	√		
Inspect Spare Tire & Carrier ____ PSI ____ 32's	N		
Test Landing Gear for Operation in High Gear	√		
Test Landing Gear for Operation in Low Gear	√		
Inspect Cross Members and Under Structure	√		
Inspect Springs and Hangers	√		
Torque U-Bolts	√		
Inspect Torque Rods, Radius Rods and Bushings	√		
Inspect Tandem Slide and Lock Mechanism (If Equipped)	√		
Inspect Inner Hubs for Leaks	√		
Check Air Bags for Leaks, Wear or Damage (If Equipped w/Air Suspension)	√		
Check Leveling Valve(s) and Linkage(s) (If Equipped w/Air Suspension)	√		

TIRE INSPECTION

Enter Air Pressure Before Adjustment



Air Pressure Adjusted to: 120

Brakes: Lining Remaining – Estimate of thickness – NO DISASSEMBLY

Check 1 Box per column

	(If equipped) 3rd Axle Left	(If equipped) 3rd Axle Right	Front Tandem Left	Front Tandem Right	Rear Most Axle Left	Rear Most Axle Right
½ " or more			☑	☑	☑	☑
¼ " to ½ "						
Less than ¼	☒	☒				

Drum Condition – Visual Inspection: (Good, Fair, Bad) – NO DISASSEMBLY

Check 1 Box per column

	(If equipped) 3rd Axle Left	(If equipped) 3rd Axle Right	Front Tandem Left	Front Tandem Right	Rear Tandem Left	Rear Tandem Right
Good			☑	☑	☑	☑
Fair						
Bad	☒	☒				

Inspect Brake Chambers	√
Check Air Brake System for Leaks	√
Check Operation of Automatic Slack Adjusters	√
Adjust All Brakes	√
Test Trailer Relay Valve Emergency Operation	√
Inspect and Drain Air Tanks	√

LUBRICATION	
Lubricate Door Hinges and Latch	√
Lubricate SAE J560 Seven-Pin Connector w/Dielectric Lube	√
Lubricate Suspension	√
Lubricate Landing Gear	√
Fill Landing Gear- Gear Box to level with Lubricant	√
Lubricate Brake Slack Adjusters	√

FOR DEALERSHIP USE ONLY

☐ This Inspection has been completed and complies with FMCSR49CFR, 396.17-23

VIN # H1D24114 Last 7 Digits Required

INSPECTED BY: Jesus

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC and PACCAR Inc., their officers, directors, and employees, from and against any and all claims suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component or system.

APPROVED BY: _____

CUSTOMER SIGNATURE REQUIRED HERE

This Inspection complies with the DOT Federal Annual Inspection requirements