Truck Service Summary – Unit U13549

2014 Ford F-550 Super Duty XL

Inspection & Preparation

- Completed multi point PM inspection
- Performed clean truck check & passed
- Topped fluids and greased chassis
- ECM report

Mechanical Repairs

- Replaced turbocharger
- Installed related oil/coolant tubes and hardware
- Changed oil/filter and replenished coolant
- Road-tested with no concerns after repair

Electrical & Lighting

- Protected exposed negative battery cable
- Installed electrical tape and heat-shrink
- All lights working during inspection

Cab & Interior

- Verified horn, A/C, wipers, and seat
- Two keys and cab safety items noted
- Fire extinguisher and road flare kit present
-

Exterior & Visibility

- Replaced all 6 tires 4 new wheels and valve hardware.
- Completed wash/detail
- Removed decals
-

Add-Ons & General Service

- Installed Charter mudflaps and mounting kits
- Added Ford power-steering fluid
-

Cooling System

- Topped off low coolant during inspection
- No coolant leak found after check
- Replaced water outlet tube during repair
- Refilled anti-freeze/coolant as needed

Final Service

- Completed DPF cleaning service
- Replaced both NOx sensors
- Performed manual regeneration and resets
- Returned unit to sale-ready condition

Vehicle Details

- VIN: 1FDUF5GT8EEA74558
- Mileage: 54,601

Summary

U13549 received detail and decal removal, clean-truck/work-ready inspections, tire/wheel replacement, turbocharger repair, battery-cable protection, coolant service, Charter mudflaps, DPF cleaning, NOx sensors, manual regeneration, resets, and road-test verification.
Eliminate downtime. If the wheels aren't turning, you're not earning.

Total Reconditioning Investment: **$13,509.28**

Source: scanned invoice packet, pages 1-14 reviewed visually.

COAST COUNTIES Peterbilt Since 1949

PREVENTATIVE MAINTENANCE SERVICE & INSPECTION

Silver Level Inspection

CUSTOMER NAME: CHARTER SALES COMPANY	DATE 4-16-2026	ODOMETER / ENGINE HOURS / FUEL 54,651	REPAIR ORDER # 90749
ADDRESS: 27000 ASTI RD. CLOVERDALE, CA 95425	UNIT NO. V13549	VIN # (LAST 7 DIGITS) FEA74558	VEHICLE MAKE & MODEL Ford F550
	PHONE: 707.669.6202	DEALER NAME & CODE Coast Counties Peterbilt C506	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

V = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:		REAR FRAME	
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	✓	Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	✓
Air Leaks	NA	5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	NA
Headlights - High & Low Beams	✓	Air Lines & Glad-hands	NA
Road Lights	✓	Trailer Light Cord & Connectors	✓
Clearance Lights / Reflectors	⊘	Pintle - Hook / Eye Mounting & Condition	NA
Turn Lights	✓	Inner & Outer Hub Seals Leaks	✓
Brake Lights	✓	Spring Shackles & Hanger Brackets	✓
Emergency Flasher	✓	Spring Leaves / Bushings / Shocks / Air Bags	✓
Backup / Load Lights	✓	Radius Rods / Torque Arms	✓
License Plates, Permits & Mounting	✓	**TIRES & WHEELS:**	
Mud Flaps / Serviceable	✓	Missing Valve Caps / Tighten Stem Locks	⊘
Fuel Tank Mounting / Filler Cap in Place	✓	Cracks or Loose Wheel Lugs	✓
Fuel Crossover Line (Droop, Damage) If equipped	NA	Tire Pressure (Record Below)	✓
Exhaust System-Condition, Leaks & Mounting Bolts	✓	Remaining Tread (Record Below)	✓
INITIAL DRIVE IN:		**TIRE INSPECTION**	
Clutch Pedal Free Travel	NA	**Enter Air Pressure Before Adjustment**	
Parking Brake - Brakes applied upon activation of control	✓	Front Axle Driver Side: PSI: 97	
Glass for Cracks or Chips	✓	32nd's: 15	
Steering Wheel Free Play & Column Mounting	✓	Front Tandem Driver Side: PSI: NA PSI: NA	
Door Window Operation	✓	32nd's: NA 32nd's: NA	
Interior Lights	✓	Rear Tandem Driver Side PSI: 107 PSI: 108	
Cranking System Operation	✓	32nd's: 16 32nd's: 16	
Gauges / Warning Lights - Illumination / Operational:	✓	Front Axle Pass. Side: PSI: 98	
Maintain Low Idle	✓	32nd's: 15	
Oil Pressure	✓	Front Tandem Pass. Side: PSI: NA PSI: NA	
Low Air Pressure Warning Devices	NA	32nd's: NA 32nd's: NA	
Air Cleaner Restriction Gauge	✓	Rear Tandem Pass. Side: PSI: 106 PSI: 106	
Electronic Warning Module / A&B Cluster Lights On/Off	✓	32nd's: 16 32nd's: 16	
Governed Air Pressure:_____PSI - KpA	NA	Air Pressure Adjusted to Front Tires: 95 Rear Tires: 110	
Air Pressure Drop-Brakes Not Applied:_____(PSI - KpA/min.)	NA	**CHASSIS LUBE - BEGIN:**	
Air Pressure Drop-Brakes Applied:_____(PSI - KpA/min.)	NA	Lubricate Door Hinges & Latches	✓
Windshield Wiper / Washer Condition & Operation	✓	Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	✓
Horns (Electric & Air)	✓	**UNDER VEHICLE:**	
Mirrors / Heated / Motorized Operation	✓	Rear Axle Leaks & Lubricant Level	✓
Drain Water from Air Tanks	NA	Rear Axle Breathers - Clear	✓
Air Tank Check Value	NA	Drive Lines - U-Joints & Slip Yokes	✓
Emergency Operation of Spring Brakes	NA	Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	✓
Tractor Protection Valve Breakaway Test	NA	Adjust Brakes - Check Auto Slack Adjusters	NA
Fire Extinguisher Charge	✓	Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY	
Flare Kit / Reflectors - Readily Accessible	✓		
BATTERIES:			
Hold-Down & Box-Mounting Bolts	✓		
Signs of Over-Charging - Visual Inspection	✓		

Sealed Type - Condition:

Color of Charge Indicator for Each Battery

1.) Green 2.) Green 4.)

Circle one for each:

Front Axle L:	1/2" or more	(1/4" to 1/2")	Less than 1/4"
Front Axle R:	1/2" or more	(1/4" to 1/2")	Less than 1/4"
Front Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	1/2" or more	(1/4" to 1/2")	Less than 1/4"
Rear Tandem R:	1/2" or more	(1/4" to 1/2")	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

UNDER VEHICLE (continued):	
Drum Condition - Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY	
Front Axle L: NA	
Front Axle R: NA	
Front Tandem L: NA	
Front Tandem R: NA	
Rear Tandem L: NA	
Rear Tandem R: NA	
Transmission Leaks & Lubricant Level	✓
Engine & Transmission Mounts	✓
Engine Oil Pan Plug - Reinstall	✓
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	✓
Steering Shaft Splines & Joint(s)	✓
Pitman Arm	✓
Drag Link	✓
Steering Arms	✓
Tie Rod Arms	✓
Tie Rod Ends	✓
Radius Rods / Torque Arms	✓
Spring Shackles & Hanger Brackets	✓
King Pin Wear	✓
Spring Leaves / Shocks / Air Bags	✓
Front Axle Beam for Cracks or Obvious Welded Repairs	✓
Wheel Bearing Play	✓
Front Hub Lubricant Level / Leaks	✓
ENGINE COMPARTMENT:	
Engine Oil Level	✓
Cranking System: Visual Inspection Loose Connections	✓
Cab, Chassis Grounds	✓
Steering Gear - Fluid Level	✓
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	✓
Drive Belt(s) Condition	✓
Drive Belt(s) Adjustment	✓
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	NA
Fan Assembly & Idler Pulley	✓
Fan Clutch & Over-Ride Operation	✓
Radiator - Exterior Condition	✓
Radiator Mounting	✓
Hose Condition & Connections	✓
Air Conditioning Compressor / Condenser Mounts / Leaks	✓
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec	
SCA's OK ✓ Undercharged_____ Overcharged_____	
Coolant Level	✓
Coolant Protection (Freeze Point): -32° (degrees Fahrenheit / Celcius)	✓
Pressure Test / Check Leaks	✓
Air Cleaning Mounting / Interference	✓
Contaminent Accumulation	✓
Vacuator Valve - Operation & Condition	NA

DRIVER'S COMMENTS:

CHARTER REQUIREMENTS:

One Spare Key	✓
Top off all Fluids	✓
A/C Works	✓
Air Blows Out of all Vents	✓
Clean RH View Window	NA
Chrome Kit	NA
Order Clean Idle Stickers if not there	✓
Repair all Air Leaks	NA
Replace Red & Yellow Brake Knob if faded	NA
New Charter Flaps w/ Straight Hangers	✓
Operate all attached equipment	✓

FOR DEALERSHIP USE ONLY

✓ This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection

VIN # EEA74558

(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: Jose Perez

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

APPROVED BY:_____

CUSTOMER SIGNATURE REQUIRED HERE

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

This inspection complies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: May 14, 2026 11:41 AM
Print Date: May 14, 2026 11:41 AM

VIN	1FDUF5GT8EEA74558
Vehicle Make	Ford
Model	F-550
Series	
Model Year	2014
Unit Number	U13549

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Powertrain Control Module	Ford 6.7L V-8 Diesel	DDCM4DF.H32	DA404043	HSCAN
Transmission Control Module	Transmission Control Module	TVDD0FY.H32	2675CA2B	HSCAN
Anti-Lock Brake / Traction Control Module	Anti-Lock Brake / Traction Control Module	N/A	N/A	HSCAN
Instrument Cluster	Instrument Cluster	N/A	N/A	HSCAN
GEM/SJB,BdyCM	GEM/SJB,BdyCM	N/A	N/A	HSCAN
Restraint Control Module	Restraint Control Module	N/A	N/A	HSCAN
Trailer Brake Control Module	Trailer Brake Control Module	N/A	N/A	HSCAN
Global Positioning System Module	Global Positioning System Module	N/A	N/A	MSCAN
Audio Control Module	Audio Control Module	N/A	N/A	MSCAN
SOBDM,CDIM	SOBDM,CDIM	N/A	N/A	MSCAN
Steering Column Control Module	Steering Column Control Module	N/A	N/A	HSCAN
Accessory Protocol Interface Module	Accessory Protocol Interface Module	N/A	N/A	HSCAN
Heating Ventilation Air Conditioning	Heating Ventilation Air Conditioning	N/A	N/A	MSCAN

JPRO ® DIAGNOSTIC REPORT

LENOX MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: May 14, 2026 11:41 AM
Print Date: May 14, 2026 11:41 AM

Vehicle Key Data Points

Description	Parameter Value
Engine Coolant Temp	127.40 °F
Manifold Pressure	14.60 psi
Malfunction Indicator Lamp	Off

Description	Parameter Value
Intake Air Temp	84.20 °F
Mass Air Flow Rate	2.70 kHz
Engine RPM	609.50

No Active Faults

Status	Component	Lookup Code	Description

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____

Date _____