Truck Service Summary – Unit U13452

2015 Freightliner 114SD

Inspection & Preparation

- Completed full detail, wash, and decal/glue removal
- Performed CARB Clean Truck Check; passed
- Completed multi point PM inspection

Mechanical Repairs

- Diagnosed and repaired air leaks; replaced electric-over-air solenoid
- Repaired engine oil leaks, injector seals, wiring harness, and pressure sensor
- Repaired transmission/PTO leak and replaced transmission fluid
- Replaced brake valve air fittings and serviced related air system leaks
- Replaced airbag/leveling valve and front brake valve fittings

Cooling System

- Diagnosed and repaired coolant leaks
- Replaced upper and lower radiator hoses
- Replaced thermostat housing hose, coolant filter, and coolant

Electrical & Lighting

- Replaced failed left-side headlight module
- Removed dashcam and related harnesses

Cab & Interior

- Installed driver seat cushion
- Replaced sunvisor clips and missing fire extinguisher
- Made extra key and replaced forward HVAC event louvers

Exterior & Visibility

- Installed new license plate frames
- Straightened right-side lower step and brackets
- Replaced outside visor.

Add-Ons & General Service

- Removed crane arms and aluminum flatbed deck
- Removed main crane base assembly and subframe
- Disconnected and capped hydraulic lines
- Cleaned affected work areas

Additional Work Performed

- Sent truck to spartan trucks for roll-off body to be installed

Final Service

- Cleaned work areas and confirmed unit was ready for sales.

Summary

PM inspection, detailing, emissions check, cab/interior repairs, lighting, air/coolant/oil/transmission leak repairs, and exterior/flatbed removal were completed to prepare Unit U13452 for sale-ready presentation.

Eliminate downtime. if the wheels aren't turning, you're not earning.

Total Reconditioning Investment: **$63,077.18**

LENOX
MOBILE TRUCK REPAIR

Retail B

PM SERVICE & INSPECTION

B - Service & Inspection

CUSTOMER / FLEET NAME	DATE.	ODOMETER / ENGINE HOURS	REPAIR ORDER #
Charter Trucks	1/27/26	233,245	3825
ADDRESS	**UNIT NO.**	**VIN # (LAST 7 DIGITS)**	**VEHICLE MAKE & MODEL**
27000 Asti Road	U13452	HGB1968	Freightliner / 114SD
CITY, STATE / PROVINCE, ZIP / POSTAL CODE	**PHONE:**	**Inspection Location:**	
Cloverdale, CA 95425	(707) 893-6428	Cloverdale, CA.	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

√ = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:	B
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	√
Air Leaks	√
Headlights - High & Low Beams	√
Road Lights	√
Clearance Lights / Reflectors	√
Turn Lights	√
Brake Lights	√
Emergency Flasher	√
Backup / Load Lights	√
License Plates, Permits & Mounting	√
Mud Flaps / Serviceable	√
Fuel Tank Mounting / Filler Cap in Place	√
Fuel Crossover Line (Droop, Damage) If equipped	√
Exhaust System-Condition, Leaks & Mounting Bolts	√
CAB - COE: Hold Down Latches	N
Inspect Clutch Cable (If Applicable)	N
Mounts	√
Front Pivot Assembly	√
Jack Operation & Leaks	N
Safety Locks, Tip-Over Stop (Visual Inspection)	√
INITIAL DRIVE IN:	**B**
Clutch Pedal Free Travel	N
Parking Brake - Brakes applied upon activation of control	√
Glass for Cracks or Chips	√
Steering Wheel Free Play & Column Mounting	√
Door Window Operation	√
Interior Lights	√
Cranking System Operation	√
Gauges / Warning Lights - Illumination / Operational:	√
Maintain Low Idle	√
Oil Pressure	√
Low Air Pressure Warning Devices	√
Air Cleaner Restriction Gauge	√
Electronic Warning Module / A&B Cluster Lights On/Off	√
Governed Air Pressure: 130 PSI - KpA	√
Air Pressure Drop-Brakes Not Applied: 0 (PSI - KpA/min.)	√
Air Pressure Drop-Brakes Applied: 0 (PSI - KpA/min.)	√
Windshield Wiper / Washer Condition & Operation	√
Horns (Electric & Air)	√
Mirrors / Heated / Motorized Operation	√
Drain Water from Air Tanks	√
Air Tank Check Value	√
Emergency Operation of Spring Brakes	√
Tractor Protection Valve Breakaway Test	√
Fire Extinguisher Charge	√
Flare Kit / Reflectors - Readily Accessible	√
BATTERIES:	**B**
Hold-Down & Box-Mounting Bolts	√
Signs of Over-Charging - Visual Inspection	√

Sealed Type - Condition:

Color of Charge Indicator for Each Battery

1.) green 2.) green 3.) green 4.) N/A

REAR FRAME	B
Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	√
5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	N
Air Lines & Glad-hands	√
Trailer Light Cord & Connectors	√
Pintle - Hook / Eye Mounting & Condition	√
Inner & Outer Hub Seals Leaks	√
Spring Shackles & Hanger Brackets	√
Spring Leaves / Bushings / Shocks / Air Bags	√
Radius Rods / Torque Arms	√
TIRES & WHEELS:	**B**
Missing Valve Caps / Tighten Stem Locks	√
Cracks or Loose Wheel Lugs	√
Tire Pressure (Record Below)	√
Remaining Tread (Record Below)	√

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle Driver Side:	PSI: 107	
	32nd's: 14	
Front Tandem Driver Side:	PSI: 94	PSI: 93
	32nd's: 14	32nd's: 15
Rear Tandem Driver Side	PSI: 92	PSI: 93
	32nd's: 12	32nd's: 11
Front Axle Pass. Side:	PSI: 105	
	32nd's: 15	
Front Tandem Pass. Side:	PSI: 93	PSI: 95
	32nd's: 10	32nd's: 11
Rear Tandem Pass. Side:	PSI: 89	PSI: 94
	32nd's: 12	32nd's: 13

Air Pressure Adjusted to Front Tires: 115 Rear Tires: 100

CHASSIS LUBE - BEGIN:	B
Lubricate Door Hinges & Latches	√
Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	√
UNDER VEHICLE:	**B**
Rear Axle Leaks & Lubricant Level	√
Rear Axle Breathers - Clear	√
Drive Lines - U-Joints & Slip Yokes	√
Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	√
Adjust Brakes - Check Auto Slack Adjusters	√

Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY

Circle one for each:

Front Axle L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Axle R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

LENOX
MOBILE TRUCK REPAIR

B LEVEL SERVICE & INSPECTION

UNDER VEHICLE (continued):	B
Drum Condition - Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY	
Front Axle L: Good	
Front Axle R: Good	
Front Tandem L: Good	
Front Tandem R: Good	
Rear Tandem L: Good	
Rear Tandem R: Good	
Transmission Leaks & Lubricant Level	√
Engine & Transmission Mounts	√
Engine Oil Pan Plug - Reinstall	√
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	√
Steering Shaft Splines & Joint(s)	√
Pitman Arm	√
Drag Link	√
Steering Arms	√
Tie Rod Arms	√
Tie Rod Ends	√
Radius Rods / Torque Arms	√
Spring Shackles & Hanger Brackets	√
King Pin Wear	√
Spring Leaves / Shocks / Air Bags	√
Front Axle Beam for Cracks or Obvious Welded Repairs	√
Wheel Bearing Play	√
Front Hub Lubricant Level / Leaks	√
ENGINE COMPARTMENT:	**B**
Engine Oil Level	√
Cranking System: Visual Inspection Loose Connections	√
Cab, Chassis Grounds	√
Steering Gear - Fluid Level	√
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	N
Drive Belt(s) Condition	√
Drive Belt(s) Adjustment	√
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	√
Fan Assembly & Idler Pulley	√
Fan Clutch & Over-Ride Operation	√
Radiator - Exterior Condition	√
Radiator Mounting	√
Hose Condition & Connections	√
Air Conditioning Compressor / Condenser Mounts / Leaks	√
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec	
SCA's OK ✔ Undercharged_____ Overcharged_____	
Coolant Level	√
Coolant Protection (Freeze Point): -34 ° (degrees Fahrenheit / Celcius)	√
Pressure Test / Check Leaks	√
Air Cleaning Mounting / Interference	√
Contaminent Accumulation	√
Vacuator Valve - Operation & Condition	√

DRIVER'S COMMENTS:	

CHARTER REQUIREMENTS:	
One Spare Key	√
Replace Red & Yellow Brake Knobs if Faded	√
Top-off all Fluids	√
A/C Works	√
Air Blows Out of all Vents	√
Clean RH View Window	N
New Charter Flaps w/ Straight Hangers	√
Replace Door Seal if Damaged	√
Replace Q-Fenders if Damaged or Plastic	N
Replace Stack if Damaged or Rusty	√
Operate all Attached Equipment	√
Chrome Kit	√
Order Clean Idle Stickers if not there	√
Plug all Holes in Dash	√
Plug all Holes in Frame with Painted Bolt	√
Repair all Air Leaks	√

FOR DEALERSHIP USE ONLY

✔ This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection

VIN # HGB1968
(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: Rodney

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

APPROVED BY: JR
CUSTOMER SIGNATURE REQUIRED HERE

This inspection complies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: December 02, 2025 9:29 AM
Print Date: December 02, 2025 9:29 AM

VIN	1FVHG3DV7FHGB1968
Vehicle Make	Freightliner
Model	114SD
Series	
Model Year	2015
Unit Number	U13452

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine/CPC	Detroit DD13 CPC04T	S0230473	App_040A	J1939 (High) /15765 (CAN)
Transmission	Eaton Gen III UltraShift PLUS	K1032817	5569976 E245.e002	J1939 (High)
Brakes	WABCO E Cab(12V) 4S/4M	??86??	E442	J1939 (High) /J1587 (Low)
Instrument Cluster	DTNA ICU3X-2013	N/A	11/42/00 04_3.2 60	J1939 (High)
Single SAM	Freightliner BHM_L	113228	U.r.2.A0.07.30	J1939 (High) /J1587 (Low)
Switch Hub Module	Freightliner SHM	145379	U.r.1.C1.01.00	J1939 (High)
Aftertreatment Control Module	Detroit DD13 ACM21T	N/A	acm_0x0221	J1939 (High) /15765 (CAN)
Chassis Module	Freightliner CHM_L	N/A	U.r.2.A0.04.20	J1939 (High)
Switch Expansion Module #1	Freightliner SEM	00153564	U.r.1.B1.01.00	J1939 (High)
Motor Control Module	Detroit DD13 MCM21T	N/A	mcm_0x06C1	J1939 (High) /15765 (CAN)
Communications Unit, Cellular	Freightliner Communications Unit, Cellular	N/A	21/43/01 010221 0308000000000 0129	J1939 (High)

LENOX
MOBILE TRUCK REPAIR

JPRO ® DIAGNOSTIC REPORT

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: December 02, 2025 9:29 AM
Print Date: December 02, 2025 9:29 AM

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	Not Available
Battery Potential	12.70 volts
Total Idle Hrs	1,731.80 hrs
Idle Shutdown	5.00 min
Road Speed Limit	75.00 mph
PTO Status	Off/Disabled
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	0 rpm
Exhaust System High Temperature Lamp Command	Off
ABS Control Status, Trailer	Not Available
Engine Odometer	40,464.22 mi
Fuel	18%
Diesel Exhaust Fluid	58%

Description	Parameter Value
Idle Fuel Used	1,820.40 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	14,027.90 hrs
Cruise Spd Limit	75.00 mph
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Off
ABS Control Status	On
Odometer	233,241.44 mi
Instrument Cluster Odometer	233,241.44 mi
Coolant	Normal

Vehicle Issues

No Active Fault(s) Present

Faults

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____ Date _____