Truck Service Summary – Unit U13445

2015 Freightliner M2

Inspection & Preparation

- Completed multi point Pm inspection
- Checked fluids, chassis greased and ECM report.
- Completed CARB Clean Truck Check - passed
- Full interior/exterior detail with decal/glue removal

Mechanical Repairs

- Repaired front engine cover leak with new seals/gaskets
- Replaced belt tensioner and alternator/serpentine belt
- Repaired air leaks with new fittings behind dash

Cooling System

- Drained/refilled coolant during front-cover repair
- Reinstalled cooling module, fan, shroud and hoses
- Tightened leaking lower coolant hose clamp

Electrical & Lighting

- Repaired inoperative license plate light and wiring
- Confirmed exterior lighting operated during inspection

Cab & Interior

- Replaced broken visor clip
- Replaced cabin air filter
- Verified HVAC vent airflow

Exterior & Visibility

- Replaced windshield
- Replaced mud flap brackets/hangers and rear flaps
- Repainted cab steps, bumper and exterior plates
- Resurfaced fuel tank and painted straps
- Installed new/chrome license plate frames

Add-Ons & General Service

- Filled open frame holes with new bolts
- Cut spare key

Additional Work Performed

- Replaced engine air filter

Final Service

- Ran truck and verified no leaks after repairs
- Confirmed lighting, air-system and inspection items
- Returned truck to sale-ready condition

Summary

2015 Freightliner M2 was inspected, repaired, detailed and verified sale-ready, with mechanical, air-system, lighting, windshield, cosmetic and clean-truck services completed.

Eliminate downtime. if the wheels aren't turning, you're not earning.

Total Reconditioning Investment: **$9,397.94**

COAST COUNTIES Peterbilt

Retail B

PREVENTATIVE MAINTENANCE SERVICE & INSPECTION

Silver Level Inspection

CUSTOMER NAME: CHARTER SALES COMPANY	DATE 11-17-25	ODOMETER / ENGINE HOURS / FUEL 96,607	REPAIR ORDER # 898944
ADDRESS: 27000 ASTI RD. CLOVERDALE, CA 95425	UNIT NO. V13445	VIN # (LAST 7 DIGITS) FDFS1372	VEHICLE MAKE & MODEL freightliner / M2
	PHONE: 707.669.6202	DEALER NAME & CODE CCTC C506	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:
V = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:	B
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	✓
Air Leaks	✓
Headlights - High & Low Beams	✓
Road Lights	✓
Clearance Lights / Reflectors	✓
Turn Lights	✓
Brake Lights	✓
Emergency Flasher	✓
Backup / Load Lights	✓
License Plates, Permits & Mounting	✓
Mud Flaps / Serviceable	✓
Fuel Tank Mounting / Filler Cap in Place	✓
Fuel Crossover Line (Droop, Damage) If equipped	✓
Exhaust System-Condition, Leaks & Mounting Bolts	✓

INITIAL DRIVE IN:	B
Clutch Pedal Free Travel	N/A
Parking Brake - Brakes applied upon activation of control	✓
Glass for Cracks or Chips	✓
Steering Wheel Free Play & Column Mounting	✓
Door Window Operation	✓
Interior Lights	✓
Cranking System Operation	✓
Gauges / Warning Lights - Illumination / Operational:	✓
Maintain Low Idle	✓
Oil Pressure	✓
Low Air Pressure Warning Devices	✓
Air Cleaner Restriction Gauge	✓
Electronic Warning Module / A&B Cluster Lights On/Off	✓
Governed Air Pressure: 125 PSI - KpA	✓
Air Pressure Drop-Brakes Not Applied: 3 (PSI - KpA/min.)	✓
Air Pressure Drop-Brakes Applied: 5 (PSI - KpA/min.)	✓
Windshield Wiper / Washer Condition & Operation	✓
Horns (Electric & Air)	✓
Mirrors / Heated / Motorized Operation	✓
Drain Water from Air Tanks	✓
Air Tank Check Value	✓
Emergency Operation of Spring Brakes	✓
Tractor Protection Valve Breakaway Test	✓
Fire Extinguisher Charge	✓
Flare Kit / Reflectors - Readily Accessible	✓

BATTERIES:	B
Hold-Down & Box-Mounting Bolts	✓
Signs of Over-Charging - Visual Inspection	✓

Sealed Type - Condition:

Color of Charge Indicator for Each Battery

1.) Good 2.) Good 3.) Good 4.) NA

REAR FRAME	B
Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	✓
5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	✓
Air Lines & Glad-hands	✓
Trailer Light Cord & Connectors	✓
Pintle - Hook / Eye Mounting & Condition	✓
Inner & Outer Hub Seals Leaks	✓
Spring Shackles & Hanger Brackets	✓
Spring Leaves / Bushings / Shocks / Air Bags	✓
Radius Rods / Torque Arms	✓

TIRES & WHEELS:	B
Missing Valve Caps / Tighten Stem Locks	✓
Cracks or Loose Wheel Lugs	✓
Tire Pressure (Record Below)	✓
Remaining Tread (Record Below)	✓

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle Driver Side:	PSI: 100	
	32nd's: 13	
Front Tandem Driver Side:	PSI: 100	PSI: 100
	32nd's: 12	32nd's: 14
Rear Tandem Driver Side	PSI: 95	PSI: 95
	32nd's: 14	32nd's: 15
Front Axle Pass. Side:	PSI: 100	
	32nd's: 13	
Front Tandem Pass. Side:	PSI: 100	PSI: 100
	32nd's: 14	32nd's: 15
Rear Tandem Pass. Side:	PSI: 100	PSI: 100
	32nd's: 12	32nd's: 13

Air Pressure Adjusted to Front Tires: 100 Rear Tires: 100

CHASSIS LUBE - BEGIN:	B
Lubricate Door Hinges & Latches	✓
Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	✓

UNDER VEHICLE:	B
Rear Axle Leaks & Lubricant Level	✓
Rear Axle Breathers - Clear	✓
Drive Lines - U-Joints & Slip Yokes	✓
Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	✓
Adjust Brakes - Check Auto Slack Adjusters	✓

Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY

Circle one for each:

Front Axle L:	(1/2" or more)	1/4" to 1/2"	Less than 1/4"
Front Axle R:	(1/2" or more)	1/4" to 1/2"	Less than 1/4"
Front Tandem L:	(1/2" or more)	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	(1/2" or more)	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	(1/2" or more)	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	(1/2" or more)	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

UNDER VEHICLE (continued):	B
Drum Condition - Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY	
Front Axle L: Good	
Front Axle R: Good	
Front Tandem L: Good	
Front Tandem R: Good	
Rear Tandem L: Good	
Rear Tandem R: Good	
Transmission Leaks & Lubricant Level	✓
Engine & Transmission Mounts	✓
Engine Oil Pan Plug - Reinstall	✓
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	✓
Steering Shaft Splines & Joint(s)	✓
Pitman Arm	✓
Drag Link	✓
Steering Arms	✓
Tie Rod Arms	✓
Tie Rod Ends	✓
Radius Rods / Torque Arms	✓
Spring Shackles & Hanger Brackets	✓
King Pin Wear	✓
Spring Leaves / Shocks / Air Bags	✓
Front Axle Beam for Cracks or Obvious Welded Repairs	✓
Wheel Bearing Play	✓
Front Hub Lubricant Level / Leaks	✓

ENGINE COMPARTMENT:	B
Engine Oil Level	✓
Cranking System: Visual Inspection Loose Connections	✓
Cab, Chassis Grounds	✓
Steering Gear - Fluid Level	✓
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	✓
Drive Belt(s) Condition	✓
Drive Belt(s) Adjustment	✓
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	✓
Fan Assembly & Idler Pulley	✓
Fan Clutch & Over-Ride Operation	✓
Radiator - Exterior Condition	✓
Radiator Mounting	✓
Hose Condition & Connections	✓
Air Conditioning Compressor / Condenser Mounts / Leaks	✓
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec	
SCA's OK ✓ Undercharged_____ Overcharged_____	✓
Coolant Level	✓
Coolant Protection (Freeze Point): -34 ° (degrees Fahrenheit / Celcius)	✓
Pressure Test / Check Leaks	✓
Air Cleaning Mounting / Interference	✓
Contaminent Accumulation	✓
Vacuator Valve - Operation & Condition	✓

DRIVER'S COMMENTS:

CHARTER REQUIREMENTS:

One Spare Key	✓
Replace Red & Yellow Brake Knobs if Faded	✓
Top-off all Fluids	✓
A/C Works	✓
Air Blows Out of all Vents	✓
Clean RH View Window	✓
New Charter Flaps w/ Straight Hangers	✓
Operate all Attached Equipment	✓
Chrome Kit	✓
Order Clean Idle Stickers if not there	✓
Plug all Holes in Dash	✓
Plug all Holes in Frame with Painted Bolt	✓
Repair all Air Leaks	✓

FOR DEALERSHIP USE ONLY

This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection

VIN # FDFS 1372
(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: Chris

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

APPROVED BY: _____
CUSTOMER SIGNATURE REQUIRED HERE

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

ection complies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: December 19, 2025 11:53 AM
Print Date: December 19, 2025 11:53 AM

VIN	3ALHCYCY8FDFS1372
Vehicle Make	Freightliner
Model	M2
Series	106 Medium Duty
Model Year	2015
Unit Number	U13445

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	Cummins 8.9L ISL	73684592	05317106 04090648 011321004359 20718013 G1 BDO	J1939 (High)
Brakes	WABCO E Basic(12V) 4S/4M	??45??	E442	J1939 (High) /J1587 (Low)
Instrument Cluster	DTNA ICU3X-2013	N/A	11/42/00 04_3.2 60	J1939 (High)
Chassis Module	Freightliner CHM_L	N/A	U.r.2.A0.04.20	J1939 (High)
Bulkhead Module	Freightliner BHM_L	134930	U.r.2.A0.07.30	J1939 (High) /J1587 (Low)

LENOX
MOBILE TRUCK REPAIR

JPRO ® DIAGNOSTIC REPORT

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: December 19, 2025 11:53 AM
Print Date: December 19, 2025 11:53 AM

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	5.80 mpg
Battery Potential	12.30 volts
Total Idle Hrs	1,772.40 hrs
Idle Shutdown	60.00 min
Road Speed Limit	69.00 mph
PTO Status	Enable
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	0 rpm
Exhaust System High Temperature Lamp Command	Off
ABS Control Status, Trailer	Not Available
Engine Odometer	76,089.26 mi
Fuel	20%
Diesel Exhaust Fluid	94%

Description	Parameter Value
Idle Fuel Used	1,531.10 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	4,473.70 hrs
Cruise Spd Limit	69.00 mph
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Off
ABS Control Status	Normal
Odometer	76,089.26 mi
Instrument Cluster Odometer	76,089.26 mi
Coolant	Normal

Vehicle Issues

No Active Faults

Faults

Status	Component	Description	Lookup Code	FMI	Count

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign

Date