Truck Service Summary – Unit U13558

2015 Trail king TK80HT

Inspection & Preparation

- Completed 90-day trailer inspection
- Topped hub oils
- Greased chassis
-

Mechanical Repairs

- Replaced worn glad-hand rubbers
- Drilled/tapped set-screw threads
- Adjusted upper deck/valve linkage

Electrical & Lighting

- Replaced R/S amber marker lights
- Replaced failed load lights/brackets
- Repaired R/S tail-light wiring
- Replaced R/S hump light/harness

Cab & Interior

-

Exterior & Visibility

- Replaced license plate frame
- Welded rear tail-hinge cracks
- Painted repaired area gloss black
- Completed trailer wash

Add-Ons & General Service

- Serviced portable power unit
- Replaced oil, air and fuel filters
- Replaced spark plugs
- Added Honda 10W-30 oil

Additional Work Performed

- Straightened bent upper deck
- Installed new winch cable/set screw
- Replaced two shop light bulbs
-

Final Service

- Completed inspection and wash
- Completed lighting/wiring repairs
- Completed winch/deck repairs
- Returned unit to sale-ready condition

Vehicle Details

- Unit: U13558
- Year/Make/Model: 2015 Trail king TK80HT
- Type: Trailer

Summary

U13558 received inspection/prep, trailer wash, lighting/wiring repairs, license plate frame, glad-hand rubbers, winch cable repair, upper-deck adjustment, rear hinge weld repair and portable power-unit service. Year/make/model: not provided.

Eliminate downtime. If the wheels aren't turning, you're not earning.

Total Reconditioning Investment: **$4,428.99**

Source: scanned invoice packet, all 8 pages reviewed visually.

Lenox Mobile Truck Repair LLC
327 Pepperwood Drive
Cloverdale, CA. 95425
7074832195
lenoxrepair@gmail.com
www.lenoxrepair.com

LENOX
MOBILE TRUCK REPAIR

CALIFORNIA 90Day BIT INSPECTION

Vehicle History Record

Report Number	FLEET UNIT NUMBER
5445	U13558
DATE	4/7/26

MOTOR CARRIER OPERATOR Charter Sales Company	INSPECTOR'S NAME (PRINT OR TYPE)
ADDRESS 27000 Asti Road	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 34505.5 CVC ☑ YES
CITY, STATE, ZIP CODE Cloverdale, CA. 95425	VEHICLE IDENTIFICATION (✓) AND COMPLETE ☐ LIC. PLATE NO. ☑ VIN ☐ OTHER LICENSE PLATE/VIN M057945
VEHICLE TYPE ☐ TRACTOR ☑ TRAILER ☐ TRUCK ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL) Cloverdale, CA.

VEHICLE COMPONENTS INSPECTED

ITEM	NA	OK	NEEDS REPAIR	REPAIRED DATE
1. BRAKE SYSTEM				
a. Service Brakes		●		
b. Parking Brake System		●		
c. Brake Drums or Rotors		●		
d. Brake Hose		●		
e. Brake Tubing		●		
f. Low Pressure Warning Device	X			
g. Tractor Protection Valve	X			
h. Air Compressor	X			
i. Electric Brakes	X			
j. Hydraulic Brakes	X			
k. Vacuum Systems				
2. COUPLING DEVICES				
a. Fifth Wheels		●		
b. Pintle Hooks	X			
c. Drawbar/Towbar Eye		●		
d. Drawbar/Towbar Tongue		●		
e. Safety Devices		●		
f. Saddle-Mounts		●		
3. EXHAUST SYSTEM				
a. Any exhaust system determined to be leaking at a point forward of or directly below the driver/sleeper compartment.	X			
b. A bus exhaust system leaking or discharging to the atmosphere in violation of standards (1), (2), or (3).	X			
c. No part of the exhaust system of any motor vehicle shall be so located as would be likely to result in burning, charring, or damaging the electrical wiring, the fuel supply, or any combustible part of the motor vehicle.	X			
4. FUEL SYSTEM				
a. Visible leak	X			
b. Fuel tank filler cap missing	X			
c. Fuel tank securely attached	X			
5. LIGHTING DEVICES				
All lighting devices and reflectors required by Section 393 shall be operable.		●		
6. SAFE LOADING				
a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.		●		
b. Protection against shifting cargo		●		

ITEM	NA	OK	NEEDS REPAIR	REPAIRED DATE
7. STEERING MECHANISM				
a. Steering Wheel Free Play	X			
b. Steering Column	X			
c. Front axle beam and ALL steering components other than steering column	X			
d. Steering Gear Box	X			
e. Pitman Arm	X			
f. Power Steering	X			
g. Ball and Socket Joints	X			
h. Tie Rods and Drag Links	X			
i. Nuts	X			
j. Steering System	X			
8. SUSPENSION				
a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.		●		
b. Spring Assembly		●		
c. Torque, Radius, or Tracking Components		●		
9. FRAME				
a. Frame Members		●		
b. Tire and Wheel Clearance		●		
c. Adjustable Axle Assemblies (Sliding Subframes)	X			
10. TIRES				
a. Tires on any steering axle of a power unit.	X			
b. All other tires.		●		
11. WHEELS AND RIMS				
a. Lock or Side Ring	X			
b. Wheels and Rims		●		
c. Fasteners		●		
d. Welds		●		
12. WINDSHIELD GLAZING				
Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).	X			
13. WINDSHIELD WIPERS				
Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.	X			
List any other condition which may prevent safe operation of this vehicle.				

Instructions: Mark column entries to verify inspection: X OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, ____ REPAIRED DATE.
CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INPECTION ITEMS FOR THE CA 90DAY BIT VEHICLE INSPECTION REPORT IN ACCORDANCE WITH 34505.5 CVC.