Truck Service Summary – Unit U13593

2015 Volvo VHD

Inspection & Preparation

- Completed CARB Clean Truck Check & passed
- ECM report for records
- Completed multi point PM inspection
- Topped fluids and greased chassis

Mechanical Repairs

- Replaced crankcase vent module/gasket
- Replaced L/S front axle inner seal
- Replaced worn drag link and hardware
- Replaced dirty engine air filter

Electrical & Lighting

- Replaced hazard flasher control switch
- Replaced steering-wheel control module
- Replaced non-op clearance lights

Cab & Interior

- Made an extra key for the truck
- Replaced worn left-side seatbelt
- Removed driver seat for reupholstery
-

Exterior & Visibility

- Replaced worn windshield wipers
- Replaced broken hood grille/crown
- Straightened bottom step and exhaust tip
- Removed broken passenger-side spot mirror

Add-Ons & General Service

- Installed four new Charter mudflaps
- Added mudflap reflector plate set
- Interior & exterior detail with decal removal

Additional Work Performed

- Repaired firewall air-manifold fittings
- Replaced rear bed reflective tape
-

Final Service

- Verified inspection/prep work complete
- Finalized interior & exterior detail package
- Returned unit to sale-ready condition

Vehicle Details

- VIN: 4V5KC9EG6FN913254
- Mileage: 308,238 miles at service intake

Summary

U13593 received inspection/prep, CARB verification, interior & exterior detail, mechanical repairs, electrical and lighting repairs, cab/interior items, mudflaps, and final sale-ready cleanup.

Eliminate downtime. If the wheels aren't turning, you're not earning.

Total Reconditioning Investment: **$8,926.84**

Source: 14-page scanned invoice packet, pages reviewed visually.

LENOX
MOBILE TRUCK REPAIR

Retail B

PM SERVICE & INSPECTION

B - Service & Inspection

CUSTOMER / FLEET NAME	DATE.	ODOMETER / ENGINE HOURS	REPAIR ORDER #
Charter Trucks	6/2/26	308,630	3824
ADDRESS	**UNIT NO.**	**VIN # (LAST 7 DIGITS)**	**VEHICLE MAKE & MODEL**
27000 Asti Road	U13593	N913254	Volvo / VHD
CITY, STATE / PROVINCE, ZIP / POSTAL CODE	**PHONE:**	**Inspection Location:**	
Cloverdale, CA 95425	(707) 893-6428	Cloverdale, CA.	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

√ = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:	B
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	√
Air Leaks	√
Headlights - High & Low Beams	√
Road Lights	√
Clearance Lights / Reflectors	√
Turn Lights	√
Brake Lights	√
Emergency Flasher	√
Backup / Load Lights	√
License Plates, Permits & Mounting	√
Mud Flaps / Serviceable	√
Fuel Tank Mounting / Filler Cap in Place	√
Fuel Crossover Line (Droop, Damage) If equipped	√
Exhaust System-Condition, Leaks & Mounting Bolts	√
CAB - COE: Hold Down Latches	N
Inspect Clutch Cable (If Applicable)	N
Mounts	√
Front Pivot Assembly	√
Jack Operation & Leaks	N
Safety Locks, Tip-Over Stop (Visual Inspection)	√
INITIAL DRIVE IN:	**B**
Clutch Pedal Free Travel	N
Parking Brake - Brakes applied upon activation of control	√
Glass for Cracks or Chips	√
Steering Wheel Free Play & Column Mounting	√
Door Window Operation	√
Interior Lights	√
Cranking System Operation	√
Gauges / Warning Lights - Illumination / Operational:	√
Maintain Low Idle	√
Oil Pressure	√
Low Air Pressure Warning Devices	√
Air Cleaner Restriction Gauge	√
Electronic Warning Module / A&B Cluster Lights On/Off	√
Governed Air Pressure: 130 PSI - KpA	√
Air Pressure Drop-Brakes Not Applied: 0 (PSI - KpA/min.)	√
Air Pressure Drop-Brakes Applied: 0 (PSI - KpA/min.)	√
Windshield Wiper / Washer Condition & Operation	√
Horns (Electric & Air)	√
Mirrors / Heated / Motorized Operation	√
Drain Water from Air Tanks	√
Air Tank Check Value	√
Emergency Operation of Spring Brakes	√
Tractor Protection Valve Breakaway Test	√
Fire Extinguisher Charge	√
Flare Kit / Reflectors - Readily Accessible	√
BATTERIES:	**B**
Hold-Down & Box-Mounting Bolts	√
Signs of Over-Charging - Visual Inspection	√

Sealed Type - Condition:

Color of Charge Indicator for Each Battery

1.) green 2.) green 3.) green 4.) N/A

REAR FRAME	B
Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	√
5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	N
Air Lines & Glad-hands	√
Trailer Light Cord & Connectors	N
Pintle - Hook / Eye Mounting & Condition	N
Inner & Outer Hub Seals Leaks	√
Spring Shackles & Hanger Brackets	√
Spring Leaves / Bushings / Shocks / Air Bags	√
Radius Rods / Torque Arms	√
TIRES & WHEELS:	**B**
Missing Valve Caps / Tighten Stem Locks	√
Cracks or Loose Wheel Lugs	√
Tire Pressure (Record Below)	√
Remaining Tread (Record Below)	√

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle Driver Side:	PSI: 107	
	32nd's: 14	
Front Tandem Driver Side:	PSI: 94	PSI: 93
	32nd's: 14	32nd's: 15
Rear Tandem Driver Side	PSI: 92	PSI: 93
	32nd's: 12	32nd's: 11
Front Axle Pass. Side:	PSI: 105	
	32nd's: 15	
Front Tandem Pass. Side:	PSI: 93	PSI: 95
	32nd's: 10	32nd's: 11
Rear Tandem Pass. Side:	PSI: 89	PSI: 94
	32nd's: 12	32nd's: 13

Air Pressure Adjusted to Front Tires: 115 Rear Tires: 100

CHASSIS LUBE - BEGIN:	B
Lubricate Door Hinges & Latches	√
Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	√
UNDER VEHICLE:	**B**
Rear Axle Leaks & Lubricant Level	√
Rear Axle Breathers - Clear	√
Drive Lines - U-Joints & Slip Yokes	√
Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	√
Adjust Brakes - Check Auto Slack Adjusters	√

Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY

	Circle one for each:		
Front Axle L:	✔ 1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Axle R:	✔ 1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem L:	✔ 1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	✔ 1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	✔ 1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	✔ 1/2" or more	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

UNDER VEHICLE (continued):	B
Drum Condition - Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY Front Axle L: Good Front Axle R: Good Front Tandem L: Good Front Tandem R: Good Rear Tandem L: Good Rear Tandem R: Good	
Transmission Leaks & Lubricant Level	√
Engine & Transmission Mounts	√
Engine Oil Pan Plug - Reinstall	√
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	√
Steering Shaft Splines & Joint(s)	√
Pitman Arm	√
Drag Link	√
Steering Arms	√
Tie Rod Arms	√
Tie Rod Ends	√
Radius Rods / Torque Arms	√
Spring Shackles & Hanger Brackets	√
King Pin Wear	√
Spring Leaves / Shocks / Air Bags	√
Front Axle Beam for Cracks or Obvious Welded Repairs	√
Wheel Bearing Play	√
Front Hub Lubricant Level / Leaks	√
ENGINE COMPARTMENT:	**B**
Engine Oil Level	√
Cranking System: Visual Inspection Loose Connections	√
Cab, Chassis Grounds	√
Steering Gear - Fluid Level	√
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	N
Drive Belt(s) Condition	√
Drive Belt(s) Adjustment	√
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	√
Fan Assembly & Idler Pulley	√
Fan Clutch & Over-Ride Operation	√
Radiator - Exterior Condition	√
Radiator Mounting	√
Hose Condition & Connections	√
Air Conditioning Compressor / Condenser Mounts / Leaks	√
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec SCA's OK ✔ Undercharged_____ Overcharged_____	
Coolant Level	√
Coolant Protection (Freeze Point): -34 ° (degrees Fahrenheit / Celcius)	√
Pressure Test / Check Leaks	√
Air Cleaning Mounting / Interference	√
Contaminent Accumulation	√
Vacuator Valve - Operation & Condition	√

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

DRIVER'S COMMENTS:

CHARTER REQUIREMENTS:	
One Spare Key	√
Replace Red & Yellow Brake Knobs if Faded	√
Top-off all Fluids	√
A/C Works	√
Air Blows Out of all Vents	√
Clean RH View Window	N
New Charter Flaps w/ Straight Hangers	√
Replace Door Seal if Damaged	√
Replace Q-Fenders if Damaged or Plastic	N
Replace Stack if Damaged or Rusty	√
Operate all Attached Equipment	√
Chrome Kit	√
Order Clean Idle Stickers if not there	√
Plug all Holes in Dash	√
Plug all Holes In Frame with Painted Bolt	√
Repair all Air Leaks	√

FOR DEALERSHIP USE ONLY

✔ This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection

VIN # M652001
(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: Rodica

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

APPROVED BY: JR
CUSTOMER SIGNATURE REQUIRED HERE

This insoection comolies with the DOT Federal Annual Insoection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: May 15, 2026 9:32 AM
Print Date: May 15, 2026 9:32 AM

VIN	4V5KC9EG6FN913254
Vehicle Make	Volvo Truck
Model	VHD
Series	
Model Year	2015
Unit Number	U13593

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	Volvo D13	14172468	23386547 23455521 23455591	J1939 (High) /J1587 (Low) /15765 (CAN)
Brakes	Bendix EC-60 Premium ABS	3D13140715	BB41102	J1939 (High) /J1587 (Low)
Instrument Cluster	Volvo Information Display	14163046	23216823 21548177 23159214	J1939 (High) /J1587 (Low)
Vehicle ECU	Volvo Vehicle ECU	14070052	23976550 23976558 23976562	J1939 (High) /J1587 (Low)
Lighting - Operator Controls	Volvo Lighting Control Module	00000114	23520894 21395099 21965199	J1939 (High) /J1587 (Low)
Cab Climate Control	Volvo ECC-ECU	00137281	22482407 21241348 21496490	J1587 (Low)
Body Controller	Volvo Bodybuilder Module	14070052	23462962 23462966 23462969	J1587 (Low)
Safety Restraint System	Volvo SRS Airbag ECU	00108714	21361812 21361837 21361839	J1587 (Low)
Base Unit (Radio Gateway to Fixed End)	Volvo Radio	40650082	N/A	J1587 (Low)

LENOX
MOBILE TRUCK REPAIR

JPRO ® DIAGNOSTIC REPORT

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: May 15, 2026 9:32 AM
Print Date: May 15, 2026 9:32 AM

Vehicle Key Data Points

Description	Parameter Value	Description	Parameter Value
Avg Fuel Econ	7.10 mpg	Idle Fuel Used	3,849.60 gal
Battery Potential	12.80 volts	DPF Soot Level	Low
Total Idle Hrs	4,484.20 hrs	DPF Derate	Low
Idle Shutdown	Not Available	Total Engine Run Time	13,237.60 hrs
Road Speed Limit	72.00 mph	Cruise Spd Limit	Not Available
PTO Status	Not Available	Malfunction Indicator Lamp	Off
Red Stop Lamp	Off	Amber Warning Lamp	Off
Protect Lamp	Off	Parking Brake Switch	On
Engine Speed	0 rpm	DPF Lamp Command	Off
Exhaust System High Temperature Lamp Command	Off	ABS Control Status	On
ABS Control Status, Trailer	Not Available	Odometer	308,630.29 mi
Engine Odometer	308,630.29 mi	Instrument Cluster Odometer	308,630.29 mi
Fuel	60%	Engine Oil	66%
Coolant	Normal	Diesel Exhaust Fluid	53%

Vehicle Issues

No Active Issues Found

Faults

Status	Component	Description	Lookup Code	FMI	Count

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____ Date _____