Truck Service Summary – Unit U13680

2016 Mack GU433

Inspection & Preparation

- Completed CARB Clean Truck Check; passed
- Performed PM inspection
- Updated speed governor/control speed
- Washed/detail-cleaned truck and removed stickers

Mechanical Repairs

- Removed hydraulic reservoir and PTO pump
- Removed under-bed cone holder/toolbox brackets
- Reinstalled reservoir with hoses after frame work
- Installed steel diamond-plate deck-hole cover

Electrical & Lighting

- Completed ECM download for records
- Replaced right-side cab-light bulb

Cab & Interior

- Rebuilt steering-wheel position lock
- Repaired seat air switch
- Replaced right/left shifter head and MV3 knobs
-

Exterior & Visibility

- Installed new license-plate frames
- Cleaned view window and removed old antennas
- Added safety triangle kit
-

Add-Ons & General Service

- Filled open frame holes with new flange bolts
- Removed old bed/conveyor brackets and hardware
-

Additional Work Performed

- Removed frame hydraulic stabilizer assembly and hoses Removed conveyor belt assy.
- Cut off headboard conveyor guide mounts
- Removed cone holder and unwanted hardware
- Completed frame cleanup for final configuration

Final Service

- Completed PM inspection and final checks
- Confirmed CARB Clean Truck Check passed
- Finished wash/detail and presentation cleanup
- Returned unit to sale-ready condition

Vehicle Details

Summary

U13680 received compliance and PM inspections, ECM/speed-governor setup, cab repairs, lighting and visibility items, seat work, hydraulic/bed hardware removal, frame cleanup, and final wash/detail preparation for a clean, sale-ready presentation.

Total Reconditioning Investment: **$5,394.50**

LENOX
MOBILE TRUCK REPAIR

Retail B

PM SERVICE & INSPECTION

B - Service & Inspection

CUSTOMER / FLEET NAME	DATE.	ODOMETER / ENGINE HOURS	REPAIR ORDER #
Charter Trucks	9/15/26	214,009	3828
ADDRESS	**UNIT NO.**	**VIN # (LAST 7 DIGITS)**	**VEHICLE MAKE & MODEL**
27000 Asti Road	U13680	M010983	Mack / GU433
CITY, STATE / PROVINCE, ZIP / POSTAL CODE	**PHONE:**	**Inspection Location**:	
Cloverdale, CA. 95425	(707) 893-6428	Cloverdale, CA.	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

√ = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:	B
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	√
Air Leaks	√
Headlights - High & Low Beams	√
Road Lights	√
Clearance Lights / Reflectors	√
Turn Lights	√
Brake Lights	√
Emergency Flasher	√
Backup / Load Lights	√
License Plates, Permits & Mounting	√
Mud Flaps / Serviceable	√
Fuel Tank Mounting / Filler Cap in Place	√
Fuel Crossover Line (Droop, Damage) If equipped	√
Exhaust System-Condition, Leaks & Mounting Bolts	√
CAB - COE: Hold Down Latches	N
Inspect Clutch Cable (If Applicable)	N
Mounts	√
Front Pivot Assembly	√
Jack Operation & Leaks	N
Safety Locks, Tip-Over Stop (Visual Inspection)	N
INITIAL DRIVE IN:	**B**
Clutch Pedal Free Travel	N
Parking Brake - Brakes applied upon activation of control	√
Glass for Cracks or Chips	√
Steering Wheel Free Play & Column Mounting	√
Door Window Operation	√
Interior Lights	√
Cranking System Operation	√
Gauges / Warning Lights - Illumination / Operational:	√
Maintain Low Idle	√
Oil Pressure	√
Low Air Pressure Warning Devices	√
Air Cleaner Restriction Gauge	√
Electronic Warning Module / A&B Cluster Lights On/Off	√
Governed Air Pressure: 130 PSI - KpA	√
Air Pressure Drop-Brakes Not Applied: 0 (PSI - KpA/min.)	√
Air Pressure Drop-Brakes Applied: 0 (PSI - KpA/min.)	√
Windshield Wiper / Washer Condition & Operation	√
Horns (Electric & Air)	√
Mirrors / Heated / Motorized Operation	√
Drain Water from Air Tanks	√
Air Tank Check Value	√
Emergency Operation of Spring Brakes	√
Tractor Protection Valve Breakaway Test	√
Fire Extinguisher Charge	√
Flare Kit / Reflectors - Readily Accessible	√
BATTERIES:	**B**
Hold-Down & Box-Mounting Bolts	√
Signs of Over-Charging - Visual Inspection	√

Sealed Type - Condition:

Color of Charge Indicator for Each Battery

1.) green **2.)** green **3.)** green **4.)** N/A

REAR FRAME	B
Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	√
5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	N
Air Lines & Glad-hands	√
Trailer Light Cord & Connectors	N
Pintle - Hook / Eye Mounting & Condition	N
Inner & Outer Hub Seals Leaks	√
Spring Shackles & Hanger Brackets	√
Spring Leaves / Bushings / Shocks / Air Bags	√
Radius Rods / Torque Arms	√
TIRES & WHEELS:	**B**
Missing Valve Caps / Tighten Stem Locks	√
Cracks or Loose Wheel Lugs	√
Tire Pressure (Record Below)	√
Remaining Tread (Record Below)	√

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle Driver Side:	**PSI:** 107	
	32nd's: 14	
Front Tandem Driver Side:	**PSI:** 94	**PSI:** 93
	32nd's: 14	**32nd's:** 15
Rear Tandem Driver Side	**PSI:** 92	**PSI:** 93
	32nd's: 12	**32nd's:** 11
Front Axle Pass. Side:	**PSI:** 105	
	32nd's: 15	
Front Tandem Pass. Side:	**PSI:** 93	**PSI:** 95
	32nd's: 10	**32nd's:** 11
Rear Tandem Pass. Side:	**PSI:** 89	**PSI:** 94
	32nd's: 12	**32nd's:** 13

Air Pressure Adjusted to Front Tires: 115 Rear Tires: 100

CHASSIS LUBE - BEGIN:	B
Lubricate Door Hinges & Latches	√
Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	√
UNDER VEHICLE:	**B**
Rear Axle Leaks & Lubricant Level	√
Rear Axle Breathers - Clear	√
Drive Lines - U-Joints & Slip Yokes	√
Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	√
Adjust Brakes - Check Auto Slack Adjusters	√

Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY

Circle one for each:

Front Axle L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Axle R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

LENOX
MOBILE TRUCK REPAIR

B LEVEL SERVICE & INSPECTION

UNDER VEHICLE (continued):	B
Drum Condition - Visual Inspection: **(Good, Fair, Bad)** - NO DISASSEMBLY	
Front Axle L: Good	
Front Axle R: Good	
Front Tandem L: Good	
Front Tandem R: Good	
Rear Tandem L: Good	
Rear Tandem R: Good	
Transmission Leaks & Lubricant Level	√
Engine & Transmission Mounts	√
Engine Oil Pan Plug - Reinstall	√
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	√
Steering Shaft Splines & Joint(s)	√
Pitman Arm	√
Drag Link	√
Steering Arms	√
Tie Rod Arms	√
Tie Rod Ends	√
Radius Rods / Torque Arms	√
Spring Shackles & Hanger Brackets	√
King Pin Wear	√
Spring Leaves / Shocks / Air Bags	√
Front Axle Beam for Cracks or Obvious Welded Repairs	√
Wheel Bearing Play	√
Front Hub Lubricant Level / Leaks	√
ENGINE COMPARTMENT:	**B**
Engine Oil Level	√
Cranking System: Visual Inspection Loose Connections	√
Cab, Chassis Grounds	√
Steering Gear - Fluid Level	√
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	N
Drive Belt(s) Condition	√
Drive Belt(s) Adjustment	√
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	√
Fan Assembly & Idler Pulley	√
Fan Clutch & Over-Ride Operation	√
Radiator - Exterior Condition	√
Radiator Mounting	√
Hose Condition & Connections	√
Air Conditioning Compressor / Condenser Mounts / Leaks	√
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec	
SCA's OK ✔ Undercharged_____ Overcharged_____	
Coolant Level	√
Coolant Protection (Freeze Point): -34 ° (degrees Fahrenheit / Celcius)	√
Pressure Test / Check Leaks	√
Air Cleaning Mounting / Interference	√
Contaminent Accumulation	√
Vacuator Valve - Operation & Condition	√

DRIVER'S COMMENTS:

CHARTER REQUIREMENTS:	
One Spare Key	√
Replace Red & Yellow Brake Knobs if Faded	√
Top-off all Fluids	√
A/C Works	√
Air Blows Out of all Vents	√
Clean RH View Window	√
New Charter Flaps w/ Straight Hangers	√
Replace Door Seal if Damaged	√
Replace Q-Fenders if Damaged or Plastic	N
Replace Stack if Damaged or Rusty	√
Operate all Attached Equipment	√
Chrome Kit	√
Order Clean Idle Stickers if not there	√
Plug all Holes in Dash	√
Plug all Holes in Frame with Painted Bolt	√
Repair all Air Leaks	√

FOR DEALERSHIP USE ONLY

✔ **This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection**

VIN # M010983

(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: _____

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

APPROVED BY: JR

CUSTOMER SIGNATURE REQUIRED HERE

This inspection complies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: August 28, 2026 1:00 PM
Print Date: August 28, 2026 1:00 PM

VIN	1M2AX32C5GM010983
Vehicle Make	Mack
Model	GU (Granite)
Series	GU433
Model Year	2016
Unit Number	U13680

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	Cummins 8.9L ISL	73862870	05317106 05018593 011321004359 20718013 G1 BDO	J1939 (High) /J1587 (Low)
Brakes	Bendix EC-80 ABS	0620151611	BB41286	J1939 (High) /15765 (CAN)
Instrument Cluster	VMAC IV ICM	15222794	22514284 21931357 22545532	J1939 (High) /J1587 (Low)
Vehicle ECU	VMAC IV VECU	15170326	23170092 23170094 23170098	J1939 (High) /J1587 (Low)

LENOX
MOBILE TRUCK REPAIR

JPRO ® DIAGNOSTIC REPORT

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: August 28, 2026 1:00 PM
Print Date: August 28, 2026 1:00 PM

Vehicle Key Data Points

Description	Parameter Value	Description	Parameter Value
Avg Fuel Econ	Not Available	Idle Fuel Used	773.50 gal
Battery Potential	12.80 volts	DPF Soot Level	Low
Total Idle Hrs	820.40 hrs	DPF Derate	Low
Idle Shutdown	60.00 min	Total Engine Run Time	10,682.80 hrs
Road Speed Limit	80.00 mph	Cruise Spd Limit	80.00 mph
PTO Status	Enable	Malfunction Indicator Lamp	Off
Red Stop Lamp	Off	Amber Warning Lamp	Off
Protect Lamp	Off	Parking Brake Switch	On
Engine Speed	0 rpm	DPF Lamp Command	Off
Exhaust System High Temperature Lamp Command	Off	ABS Control Status	Normal
ABS Control Status, Trailer	Not Available	Odometer	214,009.25 mi
Engine Odometer	214,009.25 mi	Instrument Cluster Odometer	214,009.25 mi
Fuel	16%	Diesel Exhaust Fluid	40%

Vehicle Issues

No Active Faults

Faults

Status	Component	Description	Lookup Code	FMI	Count

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____ Date _____