Truck Service Summary – Unit U13637

2016 Trail King TK80HT

Inspection & Preparation

- Completed 90-day trailer inspection
- Greased chassis

Mechanical Repairs

- Replaced worn hydraulic fittings
- Replaced four worn oil hubcaps
- Installed new hardware where required

Electrical & Lighting

- No electrical repairs at this time

Cab & Interior

Exterior & Visibility

- Removed failed license-plate nutserts
- Installed twenty new 1/4"-20 nutserts
- Installed a new license-plate frame
- Secured mounting hardware for final fit

Add-Ons & General Service

- Washed trailer

Additional Work Performed

- Check Hyd operation OK

Final Service

- Completed final chassis greasing
- Verified installed hubcaps and hardware
- Completed documented inspection items

Vehicle Details

- Unit number: U13637
- 2016 Trail king TK80HT

Summary

U13637 received a 90-day inspection, chassis greasing, hydraulic-fitting service, license-plate mounting repairs, replacement oil hubcaps. Eliminate downtime. If the wheels aren't turning, you're not earning.

Total Reconditioning Investment: **$930.17**

Source: scanned invoice packet, pages reviewed visually.

Lenox Mobile Truck Repair LLC
327 Pepperwood Drive
Cloverdale, CA. 95425
7074832195
lenoxrepair@gmail.com
www.lenoxrepair.com

LENOX
MOBILE TRUCK REPAIR

CALIFORNIA 90Day BIT INSPECTION

Vehicle History Record

Report Number	FLEET UNIT NUMBER
5454	U13637
DATE	7/29/26

MOTOR CARRIER OPERATOR Charter Sales Company	INSPECTOR'S NAME (PRINT OR TYPE)
ADDRESS 27000 Asti Road	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 34505.5 CVC ☑ YES
CITY, STATE, ZIP CODE Cloverdale, CA. 95425	VEHICLE IDENTIFICATION (✓) AND COMPLETE ❑ LIC. PLATE NO. ☑ VIN ❑ OTHER LICENSE PLATE/VIN M078097
VEHICLE TYPE ❑ TRACTOR ☑ TRAILER ❑ TRUCK ❑ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL) Cloverdale, CA.

VEHICLE COMPONENTS INSPECTED

ITEM	NA	OK	NEEDS REPAIR	REPAIRED DATE
1. BRAKE SYSTEM				
a. Service Brakes		●		
b. Parking Brake System		●		
c. Brake Drums or Rotors		●		
d. Brake Hose		●		
e. Brake Tubing		●		
f. Low Pressure Warning Device	X			
g. Tractor Protection Valve	X			
h. Air Compressor	X			
i. Electric Brakes	X			
j. Hydraulic Brakes	X			
k. Vacuum Systems				
2. COUPLING DEVICES				
a. Fifth Wheels		●		
b. Pintle Hooks	X			
c. Drawbar/Towbar Eye	X			
d. Drawbar/Towbar Tongue	X			
e. Safety Devices		●		
f. Saddle-Mounts		●		
3. EXHAUST SYSTEM				
a. Any exhaust system determined to be leaking ot a point forward of or directly below the driver/sleeper compartment.	X			
b. A bus exhaust system leaking or discharging to the atmosphere in violation of standards (1), (2), or (3).	X			
c. No part of the exhaust system of any motor vehicle shall be so located as would be likely to result in burning, charring, or damaging the electrical wiring, the fuel supply, or any combustible part of the motor vehicle.	X			
4. FUEL SYSTEM				
a. Visible leak	X			
b. Fuel tank filler cap missing	X			
c. Fuel tank securely attached	X			
5. LIGHTING DEVICES				
All lighting devices and reflectors required by Section 393 shall be operable.		●		
6. SAFE LOADING				
a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.		●		
b. Protection against shifting cargo		●		

ITEM	NA	OK	NEEDS REPAIR	REPAIRED DATE
7. STEERING MECHANISM				
a. Steering Wheel Free Play	X			
b. Steering Column	X			
c. Front axle beam and ALL steering components other than steering column	X			
d. Steering Gear Box	X			
e. Pitman Arm	X			
f. Power Steering	X			
g. Ball and Socket Joints	X			
h. Tie Rods and Drag Links	X			
i. Nuts	X			
j. Steering System	X			
8. SUSPENSION				
a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.		●		
b. Spring Assembly		●		
c. Torque, Radius, or Tracking Components		●		
9. FRAME				
a. Frame Members		●		
b. Tire and Wheel Clearance		●		
c. Adjustable Axle Assemblies (Sliding Subframes)		●		
10. TIRES				
a. Tires on any steering axle of a power unit.	X			
b. All other tires.		●		
11. WHEELS AND RIMS				
a. Lock or Side Ring	X			
b. Wheels and Rims		●		
c. Fasteners		●		
d. Welds		●		
12. WINDSHIELD GLAZING				
Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).	X			
13. WINDSHIELD WIPERS				
Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.	X			
List any other condition which may prevent safe operation of this vehicle.				

Instructions: Mark column entries to verify inspection: X OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, ____ REPAIRED DATE.
CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INPECTION ITEMS FOR THE CA 90DAY BIT VEHICLE INSPECTION REPORT IN ACCORDANCE WITH 34505.5 CVC.