Truck Service Summary – Unit U13612

2017 Kenworth T800 |

Inspection & Preparation

• Completed truck PM inspection; topped fluids and greased chassis.
•

Mechanical Repairs

• Replaced engine oil-pressure and turbo-speed sensors.
• Repaired leaking air fittings and compressor-unloader fitting.
• Replaced both steer shocks, rear torque rod and both exhaust-bushing kits.
• Replaced both fuel filters; topped DEF.

Brakes & Wheel Ends

• Replaced drive-axle brake shoes and drums on both sides.
• Replaced both rear inner drive-wheel seals.
• Replaced left-rear brake spider and flange gasket.
• Replaced left 3rd-axle S-cam tube and leaking brake chamber.
• Replaced four 255/70R22.5 tag-axle tires.

Electrical & Lighting

• Replaced city horn, dome bulbs and flasher switches.
• Repaired load lights; secured loose wiring.
• Removed GPS module/harnesses and failed rear flap-arm lights.

Cab & Interior

• Replaced seat belt, clutch-pedal pad and driver's inner door latch.
• Replaced both cruise-control switches; straightened ignition switch.
• Replaced left lower entry step; modified mounting.

Exterior & Visibility

• Installed new windshield; cleaned view windows.
• Replaced passenger curb mirror and front bumper with stainless hardware.
• Installed Charter mudflaps and reflectors.
• Removed right tag-axle fender to match missing left side.

Add-Ons & General Service

• Installed four-axle chrome kit; supplied steer moon covers.
• Supplied red/yellow MV3 knobs, glad-hands and door-panel light lenses.
• Added fire extinguisher, warning triangles and extra key.

Trailer U13612-B

• Completed 90-day trailer inspection; topped hub oils and greased chassis.
• Replaced all four hubcaps and topped oil.
• Repaired right turn signal; replaced center clearance-light bar.
• Replaced license frame, 36-inch mudflaps, reflectors and rear reflective tape.
• Returned trailer to truck bunk.

Final Service

• Oil-pressure repair made check-engine light inactive; cleared old codes.
• Cleared low-voltage warnings.
• Completed wash, inside/outside detail and sticker removal.
• Passed CARB Clean Truck Check on 8/4/26.
• Adjusted repaired brake to spec on 9/15/26.

Summary

Truck and trailer received inspections, brake and wheel-end repairs, sensor and lighting repairs, cab/exterior updates and detailing.

*Invoice total includes trailer service and shop-light work that was not separately priced.

Eliminate downtime. If the wheels aren't turning, you're not earning.

Total Reconditioning Investment*: **$14,140.92**

LENOX
MOBILE TRUCK REPAIR

Retail B

PM SERVICE & INSPECTION

B - Service & Inspection

CUSTOMER / FLEET NAME	DATE.	ODOMETER / ENGINE HOURS	REPAIR ORDER #
Charter Sales Company	7/27/26	634,129	3902
ADDRESS	**UNIT NO.**	**VIN # (LAST 7 DIGITS)**	**VEHICLE MAKE & MODEL**
27000 Asti Road	U13612	R153612	Kenworth / T800
CITY, STATE / PROVINCE, ZIP / POSTAL CODE	**PHONE:**	**Inspection Location**:	
Cloverdale, CA. 95425	(707) 893-6428	Cloverdale, CA.	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

√ = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:	B
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	√
Air Leaks	√
Headlights - High & Low Beams	√
Road Lights	√
Clearance Lights / Reflectors	√
Turn Lights	√
Brake Lights	√
Emergency Flasher	√
Backup / Load Lights	√
License Plates, Permits & Mounting	√
Mud Flaps / Serviceable	√
Fuel Tank Mounting / Filler Cap in Place	√
Fuel Crossover Line (Droop, Damage) If equipped	√
Exhaust System-Condition, Leaks & Mounting Bolts	√
CAB - COE: Hold Down Latches	N
Inspect Clutch Cable (If Applicable)	√
Mounts	√
Front Pivot Assembly	√
Jack Operation & Leaks	N
Safety Locks, Tip-Over Stop (Visual Inspection)	√
INITIAL DRIVE IN:	**B**
Clutch Pedal Free Travel	√
Parking Brake - Brakes applied upon activation of control	√
Glass for Cracks or Chips	√
Steering Wheel Free Play & Column Mounting	√
Door Window Operation	√
Interior Lights	√
Cranking System Operation	√
Gauges / Warning Lights - Illumination / Operational:	√
Maintain Low Idle	√
Oil Pressure	√
Low Air Pressure Warning Devices	√
Air Cleaner Restriction Gauge	√
Electronic Warning Module / A&B Cluster Lights On/Off	√
Governed Air Pressure: 130 PSI - KpA	√
Air Pressure Drop-Brakes Not Applied: 0 (PSI - KpA/min.)	√
Air Pressure Drop-Brakes Applied: 0 (PSI - KpA/min.)	√
Windshield Wiper / Washer Condition & Operation	√
Horns (Electric & Air)	√
Mirrors / Heated / Motorized Operation	√
Drain Water from Air Tanks	√
Air Tank Check Value	√
Emergency Operation of Spring Brakes	√
Tractor Protection Valve Breakaway Test	√
Fire Extinguisher Charge	√
Flare Kit / Reflectors - Readily Accessible	√
BATTERIES:	**B**
Hold-Down & Box-Mounting Bolts	√
Signs of Over-Charging - Visual Inspection	√

Sealed Type - Condition:

Color of Charge Indicator for Each Battery

1.) green **2.)** green **3.)** green **4.)** N/A

REAR FRAME	B
Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	√
5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	N
Air Lines & Glad-hands	√
Trailer Light Cord & Connectors	√
Pintle - Hook / Eye Mounting & Condition	√
Inner & Outer Hub Seals Leaks	√
Spring Shackles & Hanger Brackets	√
Spring Leaves / Bushings / Shocks / Air Bags	√
Radius Rods / Torque Arms	√
TIRES & WHEELS:	**B**
Missing Valve Caps / Tighten Stem Locks	√
Cracks or Loose Wheel Lugs	√
Tire Pressure (Record Below)	√
Remaining Tread (Record Below)	√

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle Driver Side:	**PSI:** 104	
	32nd's: 17	
Front Tandem Driver Side:	**PSI:** 94	**PSI:** 93
	32nd's: 16	**32nd's:** 16
Rear Tandem Driver Side	**PSI:** 92	**PSI:** 89
	32nd's: 16	**32nd's:** 16
Front Axle Pass. Side:	**PSI:** 105	
	32nd's: 18	
Front Tandem Pass. Side:	**PSI:** 92	**PSI:** 93
	32nd's: 16	**32nd's:** 16
Rear Tandem Pass. Side:	**PSI:** 92	**PSI:** 92
	32nd's: 16	**32nd's:** 17

Air Pressure Adjusted to Front Tires: 115 Rear Tires: 100

CHASSIS LUBE - BEGIN:	B
Lubricate Door Hinges & Latches	√
Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	√
UNDER VEHICLE:	**B**
Rear Axle Leaks & Lubricant Level	√
Rear Axle Breathers - Clear	√
Drive Lines - U-Joints & Slip Yokes	√
Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	√
Adjust Brakes - Check Auto Slack Adjusters	√

Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY

Circle one for each:

Front Axle L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Axle R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

LENOX
MOBILE TRUCK REPAIR

B LEVEL SERVICE & INSPECTION

UNDER VEHICLE (continued):	B
Drum Condition - Visual Inspection: **(Good, Fair, Bad)** - NO DISASSEMBLY	
Front Axle L: Good	
Front Axle R: Good	
Front Tandem L: Good	
Front Tandem R: Good	
Rear Tandem L: Good	
Rear Tandem R: Good	
Transmission Leaks & Lubricant Level	√
Engine & Transmission Mounts	√
Engine Oil Pan Plug - Reinstall	√
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	√
Steering Shaft Splines & Joint(s)	√
Pitman Arm	√
Drag Link	√
Steering Arms	√
Tie Rod Arms	√
Tie Rod Ends	√
Radius Rods / Torque Arms	√
Spring Shackles & Hanger Brackets	√
King Pin Wear	√
Spring Leaves / Shocks / Air Bags	√
Front Axle Beam for Cracks or Obvious Welded Repairs	√
Wheel Bearing Play	√
Front Hub Lubricant Level / Leaks	√
ENGINE COMPARTMENT:	**B**
Engine Oil Level	√
Cranking System: Visual Inspection Loose Connections	√
Cab, Chassis Grounds	√
Steering Gear - Fluid Level	√
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	N
Drive Belt(s) Condition	√
Drive Belt(s) Adjustment	√
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	√
Fan Assembly & Idler Pulley	√
Fan Clutch & Over-Ride Operation	√
Radiator - Exterior Condition	√
Radiator Mounting	√
Hose Condition & Connections	√
Air Conditioning Compressor / Condenser Mounts / Leaks	√
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec	
SCA's OK ✔ Undercharged_____ Overcharged_____	
Coolant Level	√
Coolant Protection (Freeze Point): -34 ° (degrees Fahrenheit / Celcius)	√
Pressure Test / Check Leaks	√
Air Cleaning Mounting / Interference	√
Contaminent Accumulation	√
Vacuator Valve - Operation & Condition	√

DRIVER'S COMMENTS:

CHARTER REQUIREMENTS:	
One Spare Key	√
Replace Red & Yellow Brake Knobs if Faded	√
Top-off all Fluids	√
A/C Works	√
Air Blows Out of all Vents	√
Clean RH View Window	√
New Charter Flaps w/ Straight Hangers	√
Replace Door Seal if Damaged	√
Replace Q-Fenders if Damaged or Plastic	√
Replace Stack if Damaged or Rusty	√
Operate all Attached Equipment	√
Chrome Kit	√
Order Clean Idle Stickers if not there	√
Plug all Holes in Dash	√
Plug all Holes in Frame with Painted Bolt	√
Repair all Air Leaks	√

FOR DEALERSHIP USE ONLY

✔ **This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection**

VIN # R153612

(Last 7 Digits Required for Annual Inspection)

INSPECTED BY:_____

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

APPROVED BY: JR

CUSTOMER SIGNATURE REQUIRED HERE

This inspection complies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: June 23, 2026 9:50 AM
Print Date: June 23, 2026 9:50 AM

VIN	1NKDXPEX2HR153612
Vehicle Make	Kenworth
Model	T8 Series
Series	
Model Year	2017
Unit Number	U13612

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	PACCAR MX 13 EPA 13	Y107768	PC4_A1434P161J AP161J10082- 06_a MY2016 EPA13	J1939 (High) /15765 (CAN)
Brakes	Bendix EC-80 ATC ABS	2W35151765	BB41258	J1939 (High) /15765 (CAN)
Cab Controller - Primary	PACCAR CECU3	N/A	P30-1031	J1939 (High) /15765 (CAN)

LENOX
MOBILE TRUCK REPAIR

JPRO ® DIAGNOSTIC REPORT

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: June 23, 2026 9:50 AM
Print Date: June 23, 2026 9:50 AM

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	5.60 mpg
Battery Potential	12.90 volts
Total Idle Hrs	5,769.20 hrs
Idle Shutdown	Not Available
Road Speed Limit	71.00 mph
PTO Status	Not Available
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	0 rpm
Exhaust System High Temperature Lamp Command	Off
ABS Control Status, Trailer	Off
Engine Odometer	634,129.85 mi
Fuel	51%
Diesel Exhaust Fluid	49%

Description	Parameter Value
Idle Fuel Used	4,252.40 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	22,442.40 hrs
Cruise Spd Limit	71.00 mph
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Off
ABS Control Status	Off
Odometer	634,129.85 mi
Instrument Cluster Odometer	634,129.85 mi
Coolant	Normal

Vehicle Issues

No Active Faults

Faults

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____

Date _____