Truck Service Summary – Unit U13621

2017 Kenworth T880

Inspection & Preparation

- Completed 102 point PM inspection
- Checked fluids and greased chassis
- Completed Clean Truck Check and CARB retest

Mechanical Repairs

- Replaced rear brake shoes and drums
- Replaced fan and accessory belts/tensioner
- Serviced air dryer and purge valve
- Repaired engine-bay air leak

Electrical & Lighting

- Replaced three failed batteries
- Replaced windshield washer pump
- Updated engine software and parameters
- Verified lighting during inspection

Cab & Interior

- Replaced cabin air and fresh-air filters
- Replaced both visor clips
- Repaired driver door check and seal
- Cleaned HVAC blower and verified operation

Exterior & Visibility

- Installed new windshield
- Installed quarter fenders and mudflaps
- Added hangers, reflectors and plate frames
- Removed decals

Add-Ons & General Service

- Replaced red and blue glad-hands
- Installed fire extinguisher and mount
- Made two keys and added clean-idle label
- Removed aftermarket camera and harnesses

Additional Work Performed

- Topped coolant and differential fluid
- Completed engine wash and full detail
- Adjusted maximum road speed setting

Final Service

- Confirmed service items operational
- Prepared unit for final delivery

Vehicle Details

- VIN: 1XKZAP8X1HJ151129
- Mileage: 272,370 miles

Summary

U13621 received comprehensive inspection and preparation, brake and belt repairs, air-system service, battery and washer repairs, cab and door updates, a new windshield, exterior upgrades, full detailing, and final CARB verification.

Eliminate downtime. If the wheels aren't turning, you're not earning.

Total Reconditioning Investment: **$7,154.75**

Source: scanned invoice packet, all 18 pages reviewed visually.

COAST COUNTIES Peterbilt Since 1949

PREVENTATIVE MAINTENANCE SERVICE & INSPECTION

Silver Level Inspection

CUSTOMER NAME: CHARTER SALES COMPANY	DATE 7-1-26	ODOMETER / ENGINE HOURS / FUEL 272,370	REPAIR ORDER # 91198
ADDRESS: 27000 ASTI RD. CLOVERDALE, CA 95425	UNIT NO. U1362.1	VIN # (LAST 7 DIGITS) H35179	VEHICLE MAKE & MODEL Kenworth T880
	PHONE: 707.669.6202	DEALER NAME & CODE Coast Counties Peterbilt C506	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

V = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:		REAR FRAME	
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	✓	Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	✓
Air Leaks	X	5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	✓
Headlights - High & Low Beams	✓	Air Lines & Glad-hands	✓
Road Lights	✓	Trailer Light Cord & Connectors	✓
Clearance Lights / Reflectors	✓	Pintle - Hook / Eye Mounting & Condition	✓
Turn Lights	✓	Inner & Outer Hub Seals Leaks	✓
Brake Lights	✓	Spring Shackles & Hanger Brackets	✓
Emergency Flasher	✓	Spring Leaves / Bushings / Shocks / Air Bags	✓
Backup / Load Lights	✓	Radius Rods / Torque Arms	✓
License Plates, Permits & Mounting	✓	**TIRES & WHEELS:**	
Mud Flaps / Serviceable	✓	Missing Valve Caps / Tighten Stem Locks	✓
Fuel Tank Mounting / Filler Cap in Place	✓	Cracks or Loose Wheel Lugs	✓
Fuel Crossover Line (Droop, Damage) If equipped	✓	Tire Pressure (Record Below)	✓
Exhaust System-Condition, Leaks & Mounting Bolts	✓	Remaining Tread (Record Below)	✓
INITIAL DRIVE IN:			
Clutch Pedal Free Travel	✓		
Parking Brake - Brakes applied upon activation of control	✓		
Glass for Cracks or Chips	✓		
Steering Wheel Free Play & Column Mounting	✓		
Door Window Operation	✓		
Interior Lights	✓		
Cranking System Operation	✓		
Gauges / Warning Lights - Illumination / Operational:	✓		
Maintain Low Idle	✓		
Oil Pressure	✓		
Low Air Pressure Warning Devices	✓		
Air Cleaner Restriction Gauge	✓		
Electronic Warning Module / A&B Cluster Lights On/Off	✓		
Governed Air Pressure: 120 PSI - KpA	✓		
Air Pressure Drop-Brakes Not Applied:_____(PSI - KpA/min.)	✓	**CHASSIS LUBE - BEGIN:**	
Air Pressure Drop-Brakes Applied:_____(PSI - KpA/min.)	✓	Lubricate Door Hinges & Latches	✓
Windshield Wiper / Washer Condition & Operation	X	Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	✓
Horns (Electric & Air)	✓	**UNDER VEHICLE:**	
Mirrors / Heated / Motorized Operation	✓	Rear Axle Leaks & Lubricant Level	✓
Drain Water from Air Tanks	✓	Rear Axle Breathers - Clear	✓
Air Tank Check Value	✓	Drive Lines - U-Joints & Slip Yokes	✓
Emergency Operation of Spring Brakes	✓	Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	✓
Tractor Protection Valve Breakaway Test	✓	Adjust Brakes - Check Auto Slack Adjusters	✓
Fire Extinguisher Charge	X	Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY	
Flare Kit / Reflectors - Readily Accessible	✓		
BATTERIES:			
Hold-Down & Box-Mounting Bolts	✓		
Signs of Over-Charging - Visual Inspection	✓		

Sealed Type - Condition:

Color of Charge Indicator for Each Battery

1.) Green 2.) Green 3.) 4.)

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle Driver Side:	PSI: 88	
	32nd's: 13	
Front Tandem Driver Side:	PSI: NA	PSI: NA
	32nd's: NA	32nd's: NA
Rear Tandem Driver Side	PSI: 87	PSI: 90
	32nd's: 11	32nd's: 11
Front Axle Pass. Side:	PSI: 91	
	32nd's: 14	
Front Tandem Pass. Side:	PSI: NA	PSI: NA
	32nd's: NA	32nd's: NA
Rear Tandem Pass. Side:	PSI: 87	PSI: 84
	32nd's: 13	32nd's: 13

Air Pressure Adjusted to Front Tires: 110 Rear Tires: 105

Circle one for each:

Front Axle L:	1/2" or more	(1/4" to 1/2")	Less than 1/4"
Front Axle R:	1/2" or more	(1/4" to 1/2")	Less than 1/4"
Front Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	1/2" or more	1/4" to 1/2"	(Less than 1/4")
Rear Tandem R:	1/2" or more	1/4" to 1/2"	(Less than 1/4")

This Inspection complies with the DOT Federal Annual Inspection requirements

UNDER VEHICLE (continued):	
Drum Condition - Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY	
Front Axle L: Fair	
Front Axle R: Fair	
Front Tandem L:	
Front Tandem R:	
Rear Tandem L: Bad	
Rear Tandem R: Bad	
Transmission Leaks & Lubricant Level	✓
Engine & Transmission Mounts	✓
Engine Oil Pan Plug - Reinstall	✓
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	✓
Steering Shaft Splines & Joint(s)	✓
Pitman Arm	✓
Drag Link	✓
Steering Arms	✓
Tie Rod Arms	✓
Tie Rod Ends	✓
Radius Rods / Torque Arms	✓
Spring Shackles & Hanger Brackets	✓
King Pin Wear	✓
Spring Leaves / Shocks / Air Bags	✓
Front Axle Beam for Cracks or Obvious Welded Repairs	✓
Wheel Bearing Play	✓
Front Hub Lubricant Level / Leaks	✓
ENGINE COMPARTMENT:	
Engine Oil Level	✓
Cranking System: Visual Inspection Loose Connections	✓
Cab, Chassis Grounds	✓
Steering Gear - Fluid Level	✓
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	NA
Drive Belt(s) Condition	✓
Drive Belt(s) Adjustment	✓
Air Comparessor & Pulley, Mtg Brackets, Broken, Cracked, Loose Parts	✓
Fan Assembly & Idler Pulley	✓
Fan Clutch & Over-Ride Operation	✓
Radiator - Exterior Condition	✓
Radiator Mounting	✓
Hose Condition & Connections	✓
Air Conditioning Compressor / Condenser Mounts / Leaks	✓
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec	
SCA's OK ✓ Undercharged_____ Overcharged_____	
Coolant Level	✓
Coolant Protection (Freeze Point): -30 ° (degrees Fahrenheit / Celcius)	✓
Pressure Test / Check Leaks	✓
Air Cleaning Mounting / Interference	✓
Contaminent Accumulation	✓
Vacuator Valve - Operation & Condition	✓

DRIVER'S COMMENTS:

CHARTER REQUIREMENTS:	
One Spare Key	✓
Top-off all Fluids	✓
A/C Works	✓
Air Blows Out of all Vents	✓
Clean RH View Window	✓
Chrome Kit	✓
Order Clean Idle Stickers if not there	✓
Repair all Air Leaks	✓
Replace Red & Yellow Brake Knob if faded	✓
New Charter Flaps w/ Straight Hangers	✓
Operate all attached equipment	✓

FOR DEALERSHIP USE ONLY

✓ **This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection**

VIN # HJ151429

(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: Jose Ponce

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

APPROVED BY:_____

CUSTOMER SIGNATURE REQUIRED HERE

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

This inspection complies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: July 13, 2026 3:40 PM
Print Date: July 13, 2026 3:40 PM

VIN	1XKZAP8X1HJ151129
Vehicle Make	Kenworth
Model	T880
Series	
Model Year	2017
Unit Number	U13621

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	PACCAR MX 13 EPA 13	Y106503	PC4_A1434P161J AP161J10082- 06_a MY2016 EPA13	J1939 (High) /15765 (CAN)
Brakes	Bendix EC-80 ABS	0635154729	BB41264	J1939 (High) /15765 (CAN)
Cab Controller - Primary	PACCAR CECU3 with Chassis Node	N/A	P30-1011	J1939 (High) /15765 (CAN)

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: July 13, 2026 3:40 PM
Print Date: July 13, 2026 3:40 PM

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	6.90 mpg
Battery Potential	11.90 volts
Total Idle Hrs	2,463.30 hrs
Idle Shutdown	Not Available
Road Speed Limit	120.00 mph
PTO Status	Not Available
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	0 rpm
Exhaust System High Temperature Lamp Command	Off
ABS Control Status, Trailer	Off
Engine Odometer	272,392.40 mi
Fuel	34%
Diesel Exhaust Fluid	22%

Description	Parameter Value
Idle Fuel Used	1,569.30 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	8,346.70 hrs
Cruise Spd Limit	99.00 mph
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Off
ABS Control Status	Off
Odometer	272,392.40 mi
Instrument Cluster Odometer	272,392.40 mi
Coolant	Normal

Vehicle Issues

No active Faults

Faults

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____

Date _____