Truck Service Summary – Unit U13615

2018 Freightliner Cascadia 113

Inspection & Preparation

- Completed Charter 102 point inspection
- ECM download for record
- CTC Test Passed
- Topped off fluids & Greased Chassis
- Verified air flow through all vents

Electrical & Lighting

- Installed remanufactured CPC4 control unit
- Programmed CPC4; checked throttle wiring
- Replaced front turn-signal and marker bulbs

Exterior & Visibility

- Completed full interior & exterior detail
- Replaced license plate frames
- Installed 36-inch mudflaps and reflectors
- Replaced rear liftgate reflective tape

Additional Work Performed

- Sanded and primed aftertreatment cover
- Repainted cover gloss black
- Updated door tape and installed engine label

Vehicle Details

- VIN: 3ALHGBDV0JDJR9564
- Engine: Detroit Diesel DD13
- Service dates: 6/30/2026 - 8/4/2026

Mechanical Repairs

- Replaced failed A/C compressor
- Installed new A/C line O-rings
- Recharged A/C refrigerant
- Replaced original air dryer filter

Cab & Interior

- Installed two truck seat cushions
- Replaced motorized mirror switch
- Made an extra key
- Replaced extinguisher pin and breakaway tie

Add-Ons & General Service

- Replaced missing warning triangle kit
- Supplied chrome steer-axle moon covers

Final Service

- Confirmed A/C blowing cold after repair
- Road tested
- Cleaned serviced area

Summary

U13615 received inspection/prep, A/C and air dryer service, CPC4 replacement/programming, cab updates, exterior refurbishment and safety equipment. CARB Clean Truck Check passed 8/4/26.

Eliminate downtime. If the wheels aren't turning, you're not earning.

Total Reconditioning Investment: **$6,617.24**

LENOX
MOBILE TRUCK REPAIR

Retail B

PM SERVICE & INSPECTION

B - Service & Inspection

CUSTOMER / FLEET NAME	DATE.	ODOMETER / ENGINE HOURS	REPAIR ORDER #
Charter Sales Company	7/9/26	411,765	3904
ADDRESS	**UNIT NO.**	**VIN # (LAST 7 DIGITS)**	**VEHICLE MAKE & MODEL**
27000 Asti Road	U13615	DJR9564	Freightliner / M2106
CITY, STATE / PROVINCE, ZIP / POSTAL CODE	**PHONE:**	**Inspection Location**:	
Cloverdale, CA. 95425	(707) 893-6428	Cloverdale, CA	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

√ = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:	B
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	√
Air Leaks	√
Headlights - High & Low Beams	√
Road Lights	√
Clearance Lights / Reflectors	√
Turn Lights	√
Brake Lights	√
Emergency Flasher	√
Backup / Load Lights	√
License Plates, Permits & Mounting	√
Mud Flaps / Serviceable	√
Fuel Tank Mounting / Filler Cap in Place	√
Fuel Crossover Line (Droop, Damage) If equipped	√
Exhaust System-Condition, Leaks & Mounting Bolts	√
CAB - COE: Hold Down Latches	N
Inspect Clutch Cable (If Applicable)	N
Mounts	√
Front Pivot Assembly	√
Jack Operation & Leaks	N
Safety Locks, Tip-Over Stop (Visual Inspection)	√
INITIAL DRIVE IN:	**B**
Clutch Pedal Free Travel	N
Parking Brake - Brakes applied upon activation of control	√
Glass for Cracks or Chips	√
Steering Wheel Free Play & Column Mounting	√
Door Window Operation	√
Interior Lights	√
Cranking System Operation	√
Gauges / Warning Lights - Illumination / Operational:	√
Maintain Low Idle	√
Oil Pressure	√
Low Air Pressure Warning Devices	√
Air Cleaner Restriction Gauge	√
Electronic Warning Module / A&B Cluster Lights On/Off	√
Governed Air Pressure: 130 PSI - KpA	√
Air Pressure Drop-Brakes Not Applied: 0 (PSI - KpA/min.)	√
Air Pressure Drop-Brakes Applied: 0 (PSI - KpA/min.)	√
Windshield Wiper / Washer Condition & Operation	√
Horns (Electric & Air)	√
Mirrors / Heated / Motorized Operation	√
Drain Water from Air Tanks	√
Air Tank Check Value	√
Emergency Operation of Spring Brakes	√
Tractor Protection Valve Breakaway Test	√
Fire Extinguisher Charge	√
Flare Kit / Reflectors - Readily Accessible	√
BATTERIES:	**B**
Hold-Down & Box-Mounting Bolts	√
Signs of Over-Charging - Visual Inspection	√

Sealed Type - Condition:

Color of Charge Indicator for Each Battery

1.) green **2.)** green **3.)** N/A **4.)** N/A

REAR FRAME	B
Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	√
5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	N
Air Lines & Glad-hands	N
Trailer Light Cord & Connectors	N
Pintle - Hook / Eye Mounting & Condition	N
Inner & Outer Hub Seals Leaks	√
Spring Shackles & Hanger Brackets	√
Spring Leaves / Bushings / Shocks / Air Bags	√
Radius Rods / Torque Arms	√
TIRES & WHEELS:	**B**
Missing Valve Caps / Tighten Stem Locks	√
Cracks or Loose Wheel Lugs	√
Tire Pressure (Record Below)	√
Remaining Tread (Record Below)	√

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle Driver Side:	**PSI:** 104	
	32nd's:	
Front Tandem Driver Side:	**PSI:** 98	**PSI:** 96
	32nd's:	**32nd's:**
Rear Tandem Driver Side	**PSI:** 97	**PSI:** 96
	32nd's:	**32nd's:**
Front Axle Pass. Side:	**PSI:** 106	
	32nd's:	
Front Tandem Pass. Side:	**PSI:** 94	**PSI:** 93
	32nd's:	**32nd's:**
Rear Tandem Pass. Side:	**PSI:** 92	**PSI:** 96
	32nd's:	**32nd's:**

Air Pressure Adjusted to Front Tires: 110 Rear Tires: 100

CHASSIS LUBE - BEGIN:	B
Lubricate Door Hinges & Latches	√
Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	√
UNDER VEHICLE:	**B**
Rear Axle Leaks & Lubricant Level	√
Rear Axle Breathers - Clear	√
Drive Lines - U-Joints & Slip Yokes	√
Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	√
Adjust Brakes - Check Auto Slack Adjusters	√

Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY

Circle one for each:

Front Axle L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Axle R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

LENOX
MOBILE TRUCK REPAIR

B LEVEL SERVICE & INSPECTION

UNDER VEHICLE (continued):	B
Drum Condition - Visual Inspection: **(Good, Fair, Bad)** - NO DISASSEMBLY	
Front Axle L: Good	
Front Axle R: Good	
Front Tandem L: Good	
Front Tandem R: Good	
Rear Tandem L: Good	
Rear Tandem R: Good	
Transmission Leaks & Lubricant Level	√
Engine & Transmission Mounts	√
Engine Oil Pan Plug - Reinstall	N
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	√
Steering Shaft Splines & Joint(s)	√
Pitman Arm	√
Drag Link	√
Steering Arms	√
Tie Rod Arms	√
Tie Rod Ends	√
Radius Rods / Torque Arms	√
Spring Shackles & Hanger Brackets	√
King Pin Wear	√
Spring Leaves / Shocks / Air Bags	√
Front Axle Beam for Cracks or Obvious Welded Repairs	√
Wheel Bearing Play	√
Front Hub Lubricant Level / Leaks	√
ENGINE COMPARTMENT:	**B**
Engine Oil Level	√
Cranking System: Visual Inspection Loose Connections	√
Cab, Chassis Grounds	√
Steering Gear - Fluid Level	√
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	N
Drive Belt(s) Condition	√
Drive Belt(s) Adjustment	√
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	√
Fan Assembly & Idler Pulley	√
Fan Clutch & Over-Ride Operation	√
Radiator - Exterior Condition	√
Radiator Mounting	√
Hose Condition & Connections	√
Air Conditioning Compressor / Condenser Mounts / Leaks	√
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec	
SCA's OK ✔ Undercharged_____ Overcharged_____	
Coolant Level	√
Coolant Protection (Freeze Point): -34 ° (degrees Fahrenheit / Celcius)	√
Pressure Test / Check Leaks	√
Air Cleaning Mounting / Interference	√
Contaminent Accumulation	√
Vacuator Valve - Operation & Condition	√

DRIVER'S COMMENTS:

CHARTER REQUIREMENTS:	
One Spare Key	√
Replace Red & Yellow Brake Knobs if Faded	√
Top-off all Fluids	√
A/C Works	√
Air Blows Out of all Vents	√
Clean RH View Window	N
New Charter Flaps w/ Straight Hangers	√
Replace Door Seal if Damaged	√
Replace Q-Fenders if Damaged or Plastic	N
Replace Stack if Damaged or Rusty	√
Operate all Attached Equipment	√
Chrome Kit	√
Order Clean Idle Stickers if not there	√
Plug all Holes in Dash	√
Plug all Holes in Frame with Painted Bolt	√
Repair all Air Leaks	√

FOR DEALERSHIP USE ONLY

✔ **This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection**

VIN # DJR9564
(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: _____

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

APPROVED BY: JR
CUSTOMER SIGNATURE REQUIRED HERE

This inspection complies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: June 25, 2026 9:49 AM
Print Date: June 25, 2026 9:49 AM

VIN	3ALHGBDV0JDJR9564
Vehicle Make	Freightliner
Model	Cascadia
Series	
Model Year	2018
Unit Number	U13615

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine/CPC	Detroit DD13 CPC04T	471928S0486316	App_0411	J1939 (High) /15765 (CAN)
Transmission	Detroit DT12 TCM01T	N/A	20/41/00 000 022 0504482109-002 DTNA NAMT201403 2020-10-09	J1939 (High) /15765 (CAN)
Brakes	WABCO E Series ABS E8 4S/4M	004020053625	2460030622 1.83.1.31 E801	J1939 (High) /15765 (CAN)
Instrument Cluster	DTNA ICU3S-P3-2016	N/A	15/37/00 1.2 ICU3S -P3-2016 60	J1939 (High)
SAM Cabin	Freightliner SAM Cabin	N/A	N/A	J1939 (High) /15765 (CAN)
Modular Switch Field	Freightliner Modular Switch Field	N/A	N/A	J1939 (High) /15765 (CAN)
Motor Control Module	Detroit DD13 MCM21T	N/A	mcm_0x06F6	J1939 (High) /15765 (CAN)
Aftertreatment Control Module	Detroit DD13 ACM21T	N/A	acm_0x0250	J1939 (High) /15765 (CAN)
SAM Chassis	Freightliner SAM Chassis	N/A	N/A	J1939 (High) /15765 (CAN)
HVAC-Front Control Unit	Freightliner HVAC Front	FL-P3D-17042111-0034	R.0.3.2 R.1.3.1	J1939 (High)

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: June 25, 2026 9:49 AM
Print Date: June 25, 2026 9:49 AM

Central Gateway	DTNA Central GateWay	0000164506	15/43/00 020301 0004484927001 0 3	J1939 (High) /15765 (CAN)

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	9.00 mpg
Battery Potential	13.20 volts
Total Idle Hrs	674.80 hrs
Idle Shutdown	5 min
Road Speed Limit	65.00 mph
PTO Status	Off/Disabled
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	0 rpm
Exhaust System High Temperature Lamp Command	Off
ABS Control Status, Trailer	Not Available
Engine Odometer	411,765.54 mi
Fuel	24%
Diesel Exhaust Fluid	32%

Description	Parameter Value
Idle Fuel Used	867.30 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	9,458.70 hrs
Cruise Spd Limit	67.00 mph
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Off
ABS Control Status	Not Available
Odometer	411,765.54 mi
Instrument Cluster Odometer	411,765.54 mi
Coolant	Normal

Vehicle Issues

No Active Faults

Faults

Status	Component	Description	Lookup Code	FMI	Count

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____ Date _____