COAST COUNTIES Peterbilt

Retail B

PREVENTATIVE MAINTENANCE SERVICE & INSPECTION

U136888 **Silver Level Inspection**

CUSTOMER NAME: CHARTER SALES COMPANY	DATE 8/7/26	ODOMETER / ENGINE HOURS 347301	REPAIR ORDER # 69692
ADDRESS: 27000 ASTI RD. CLOVERDALE, CA 95425	UNIT NO. 834.4223	VIN # (LAST 7 DIGITS) JM474348	VEHICLE MAKE & MODEL # 337
	PHONE: 707.669.6202	DEALER NAME & CODE	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

V = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION	B	REAR FRAME	B
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	✓	Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	✓
Air Leaks	✓	5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	
Headlights - High & Low Beams	✓	Air Lines & Glad-hands	
Road Lights	✓	Trailer Light Cord & Connectors	
Clearance Lights / Reflectors	✓	Pintle - Hook / Eye Mounting & Condition	
Turn Lights	✓	Inner & Outer Hub Seals Leaks	✓
Brake Lights	✓	Spring Shackles & Hanger Brackets	✓
Emergency Flasher	✓	Spring Leaves / Bushings / Shocks / Air Bags	✓
Backup / Load Lights	✓	Radius Rods / Torque Arms	✓
License Plates, Permits & Mounting	✓	**TIRES & WHEELS (1)**	**B**
Mud Flaps / Serviceable	✓	Missing Valve Caps / Tighten Stem Locks	✓
Fuel Tank Mounting / Filler Cap in Place	✓	Cracks or Loose Wheel Lugs	✓
Fuel Crossover Line (Droop, Damage) if equipped	✓	Tire Pressure (Record Below)	✓
Exhaust System-Condition, Leaks & Mounting Bolts	✓	Remaining Tread (Record Below)	✓
INITIAL DRIVE IN	**B**		
Clutch Pedal Free Travel	✓		
Parking Brake - Brakes applied upon activation of control	✓		
Glass for Cracks or Chips	✓		
Steering Wheel Free Play & Column Mounting	✓		
Door Window Operation	✓		
Interior Lights	✓		
Cranking System Operation	✓		
Gauges / Warning Lights - Illumination / Operational:	✓		
Maintain Low Idle	✓		
Oil Pressure	✓		
Low Air Pressure Warning Devices	-		
Air Cleaner Restriction Gauge	✓		
Electronic Warning Module / A&B Cluster Lights On/Off	✓		
Governed Air Pressure: 120 PSI - KpA	✓		
Air Pressure Drop-Brakes Not Applied: 0 (PSI - KpA/min.)	✓		
Air Pressure Drop-Brakes Applied: 0 (PSI - KpA/min.)	✓		
Windshield Wiper / Washer Condition & Operation	✓		
Horns (Electric & Air)	✓		
Mirrors / Heated / Motorized Operation	✓		
Drain Water from Air Tanks	✓		
Air Tank Check Value	✓		
Emergency Operation of Spring Brakes	✓		
Tractor Protection Valve Breakaway Test	✓		
Fire Extinguisher Charge	✓		
Flare Kit / Reflectors - Readily Accessible	✓		
BATTERIES	**B**		
Hold-Down & Box-Mounting Bolts	✓		
Signs of Over-Charging - Visual Inspection	✓		
Sealed Type - Condition	✓		

Color of Charge Indicator for Each Battery

1.) good 2.) good 3.) 4.)

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle Driver Side:	PSI: 110	
	32nd's: 15	
Front Tandem Driver Side:	PSI: 104	PSI: 100
	32nd's: 22	32nd's: 22
Rear Tandem Driver Side	PSI:	PSI:
	32nd's:	32nd's:
Front Axle Pass. Side:	PSI: 110	
	32nd's: 15	
Front Tandem Pass. Side:	PSI: 104	PSI: 100
	32nd's: 17	32nd's: 18
Rear Tandem Pass. Side:	PSI:	PSI:
	32nd's:	32nd's:

Air Pressure Adjusted to Front Tires: Rear Tires:

CHASSIS LUBE & BEGIN		**B**
Lubricate Door Hinges & Latches		✓
Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub		✓
UNDER VEHICLE (2)		**B**
Rear Axle Leaks & Lubricant Level		✓
Rear Axle Breathers - Clear		✓
Drive Lines - U-Joints & Slip Yokes		✓
Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply		✓
Adjust Brakes - Check Auto Slack Adjusters		✓
Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY		

Circle one for each:

Front Axle L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Axle R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

UNDER VEHICLE (continued):	B	DRIVER'S COMMENTS:
Drum Condition - Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY		
Front Axle L: Good		
Front Axle R: Good		
Front Tandem L: Good		
Front Tandem R: Good		
Rear Tandem L: Good		
Rear Tandem R: Good		
Transmission Leaks & Lubricant Level	✓	
Engine & Transmission Mounts	✓	
Engine Oil Pan Plug - Reinstall	✓	CHARTER REQUIREMENTS
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	✓	One Spare Key
Steering Shaft Splines & Joint(s)	✓	Replace Red & Yellow Brake Knobs if Faded
Pitman Arm	✓	Top-off all Fluids
Drag Link	✓	A/C Works
Steering Arms	✓	Air Blows Out of all Vents
Tie Rod Arms	✓	Clean RH View Window
Tie Rod Ends	✓	New Charter Flags w/ Straight Hangers
Radius Rods / Torque Arms	✓	Operate all Attached Equipment
Spring Shackles & Hanger Brackets	✓	Chrome Kit
King Pin Wear	✓	Order Clean Idle Stickers if not there
Spring Leaves / Shocks / Air Bags	✓	Plug all Holes in Dash
Front Axle Beam for Cracks or Obvious Welded Repairs	✓	Plug all Holes in Frame with Painted Bolt
Wheel Bearing Play	✓	Repair all Air Leaks
Front Hub Lubricant Level / Leaks	✓	
ENGINE COMPARTMENT	**B**	
Engine Oil Level	✓	
Cranking System: Visual Inspection Loose Connections	✓	
Cab, Chassis Grounds	✓	
Steering Gear - Fluid Level	✓	
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	✓	
Drive Belt(s) Condition	✓	
Drive Belt(s) Adjustment	✓	
Air Compressor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	✓	
Fan Assembly & Idler Pulley	✓	
Fan Clutch & Over-Ride Operation	✓	
Radiator - Exterior Condition	✓	
Radiator Mounting	✓	
Hose Condition & Connections	✓	
Air Conditioning Compressor / Condenser Mounts / Leaks	✓	
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec		
SCA's OK ✓ Undercharged ____ Overcharged ____		
Coolant Level		
Coolant Protection (Freeze Point): ____° (degrees Fahrenheit / Celcius)	✓	
Pressure Test / Check Leaks	✓	
Air Cleaning Mounting / Interference	✓	
Contaminent Accumulation	✓	
Vacuator Valve - Operation & Condition		

Fuel tank
Inside cab harness
Driver seat belt
2 CB in windshield
Tires
Bumper damaged
Cab leaning forward
Replace DEF tank
Light out on top of cab
Rear inside marker light out
Fog light out
Coolant leak front of cab
Repaired 7/25/25

FOR DEALERSHIP USE ONLY

☐ This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection

VIN # ____ JM 474348
(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: [signature]

OTHER INSPECTIONS & EXPIRATION DATES

California BIT 90 Days

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

APPROVED BY: _____
CUSTOMER SIGNATURE REQUIRED HERE

ection complies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: September 15, 2026 2:54 PM
Print Date: September 15, 2026 2:54 PM

VIN	2NP2HM6X4JM474348
Vehicle Make	Peterbilt
Model	337
Series	
Model Year	2018
Unit Number	U13688P

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	Cummins B6.7	74146542	04384413 21075028 012819184851 22701728 G1 BGU 02030108	J1939 (High)
Transmission	Allison 1000/2000 5th Gen	BK6882A170980211	L16BCDPC_5J6996B B16200034B59J	J1939 (High) /15765 (CAN)
Brakes	Bendix EC-80 ABS	0642163003	BB41264	J1939 (High) /15765 (CAN)
Cab Controller - Primary	PACCAR CECU3	N/A	N/A	J1939 (High)
Shift Console - Primary	PACCAR Right Hand Stalk Switch	N/A	250_04 1501 204	J1939 (High)

LENOX
MOBILE TRUCK REPAIR

JPRO ® DIAGNOSTIC REPORT

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: September 15, 2026 2:54 PM
Print Date: September 15, 2026 2:54 PM

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	9.00 mpg
Battery Potential	12.80 volts
Total Idle Hrs	2,872.60 hrs
Idle Shutdown	60.00 min
Road Speed Limit	80.00 mph
PTO Status	Enable
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	0 rpm
Exhaust System High Temperature Lamp Command	Off
ABS Control Status, Trailer	Not Available
Engine Odometer	347,301.19 mi
Fuel	46%
Diesel Exhaust Fluid	78%

Description	Parameter Value
Idle Fuel Used	1,860.30 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	11,885.10 hrs
Cruise Spd Limit	80.00 mph
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Off
ABS Control Status	Not Available
Odometer	347,301.19 mi
Instrument Cluster Odometer	347,301.19 mi
Coolant	Normal

Vehicle Issues

No Active Issues Found

Faults

Status	Component	Description	Lookup Code	FMI	Count

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign

Date