JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: October 27, 2026 4:23 PM
Print Date: October 27, 2026 4:23 PM

VIN	2NP3XJ0XXKM657785
Vehicle Make	Peterbilt
Model	348
Series	
Model Year	2019
Unit Number	U13711

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	Cummins L9	74419746	04384413 22316504 090123011523 23701870 G1 BGV 02030108	J1939 (High)
Transmission	Allison 3000/4000 5th Gen	BK6882A182765206	W17BCD_PC_7N32 C17200084C44L	J1939 (High) /15765 (CAN)
Brakes	Bendix EC-80 ESP ABS	6236180691	Z091290	J1939 (High) /15765 (CAN)
Headway Controller	Bendix Wingman® FLR21™ Radar Sensor	184303548	BX180200	J1939 (High) /15765 (CAN)
Cab Controller - Primary	PACCAR CECU3	N/A	N/A	J1939 (High)
Shift Console - Primary	PACCAR Right Hand Stalk Switch	N/A	30MAf.	J1939 (High)
Collision Avoidance System	Bendix DIU	210746	12.220.0	J1939 (High)

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: October 27, 2026 4:23 PM
Print Date: October 27, 2026 4:23 PM

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	5.90 mpg
Battery Potential	12.50 volts
Total Idle Hrs	4,007.60 hrs
Idle Shutdown	5.00 min
Road Speed Limit	80.00 mph
PTO Status	Enable
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	0 rpm
Exhaust System High Temperature Lamp Command	Off
ABS Control Status, Trailer	Not Available
Engine Odometer	145,879.59 mi
Fuel	26%
Diesel Exhaust Fluid	91%

Description	Parameter Value
Idle Fuel Used	3,542.40 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	9,507.30 hrs
Cruise Spd Limit	80.00 mph
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Off
ABS Control Status	Not Available
Odometer	145,879.59 mi
Instrument Cluster Odometer	145,879.59 mi
Coolant	Normal

Vehicle Issues

No Active Issues Found

Faults

Status	Component	Description	Lookup Code	FMI	Count

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____

Date _____