# JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: October 30, 2026 10:56 AM
Print Date: October 30, 2026 10:56 AM

| | |
|---|---|
| **VIN** | 1XPBDP9X5KD647462 |
| **Vehicle Make** | Peterbilt |
| **Model** | 579 |
| **Series** | |
| **Model Year** | 2019 |
| **Unit Number** | U13715 |

## Vehicle Components

| Component | Description | Serial Number | Software Version | Network |
|---|---|---|---|---|
| Engine | PACCAR MX 13 EPA 17 | Y182025 | PC4_D1463P181E DP181E10082- 10_a MY2018 EPA17 CMPNENT 37 CMPNENT 38 2183030 | J1939 (High) /15765 (CAN) |
| Transmission | PACCAR TX-12 | 018F112C | 2399316 274.26.0 2149627 E003.e002 2390050 422.2 5538105 6 8888884 0.0 | J1939 (High) |
| Brakes | Bendix EC-80 ESP ABS | 6238182029 | Z091290 | J1939 (High) /15765 (CAN) |
| Cab Controller - Primary | PACCAR CECU3 500K | N/A | P30-1041 | J1939 (High) /15765 (CAN) |
| Shift Console - Primary | PACCAR Right Hand Stalk Switch | N/A | S01926B00_D01 | J1939 (High) |
| VECU | PACCAR VECU | N/A | 2320818 | J1939 (High) /15765 (CAN) |
| Headway Controller | Bendix Wingman® FLR21™ Radar Sensor | 221501687 | BX193102 | J1939 (High) /15765 (CAN) |

# JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: October 30, 2026 10:56 AM
Print Date: October 30, 2026 10:56 AM

## Vehicle Key Data Points

| Description | Parameter Value |
|---|---|
| Avg Fuel Econ | 13.70 mpg |
| Battery Potential | 12.90 volts |
| Total Idle Hrs | 12,611.30 hrs |
| Idle Shutdown | Not Available |
| Road Speed Limit | Not Available |
| PTO Status | Off/Disabled |
| Red Stop Lamp | Off |
| Protect Lamp | Off |
| Engine Speed | 0 rpm |
| Exhaust System High Temperature Lamp Command | Off |
| ABS Control Status, Trailer | Off |
| Engine Odometer | 469,408.52 mi |
| Fuel | 38% |
| Diesel Exhaust Fluid | 62% |

| Description | Parameter Value |
|---|---|
| Idle Fuel Used | 8,363.60 gal |
| DPF Soot Level | Low |
| DPF Derate | Low |
| Total Engine Run Time | 21,305.90 hrs |
| Cruise Spd Limit | Not Available |
| Malfunction Indicator Lamp | Off |
| Amber Warning Lamp | Off |
| Parking Brake Switch | On |
| DPF Lamp Command | Off |
| ABS Control Status | Off |
| Odometer | 469,408.52 mi |
| Instrument Cluster Odometer | 469,408.52 mi |
| Coolant | Normal |

## Vehicle Issues

No Active Fault(s) Present

## Faults

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____ Date _____