Truck Service Summary – Unit U13499

2019 Volvo VHD

Inspection & Preparation

- Completed multi point PM inspection
- Topped all fluids and greased chassis
- Performed ECM download for records
- Passed CARB Clean Truck Check & passed

Mechanical Repairs

- Replaced failed outlet particulate matter sensor
- Performed aftertreatment reset
- Completed forced regen successfully
- Cleared codes; functions returned normal

Electrical & Lighting

Cab & Interior

- Replaced worn red and yellow MV3 knobs
- Removed broken rear storage pipe/brackets

Exterior & Visibility

- Completed interior & exterior detail
- Replaced windshield
- Replaced license plate frames
- Replaced upper grille chrome crown

Add-Ons & General Service

Additional Work Performed

Final Service

- Returned toward sale-ready condition

Vehicle Details

- VIN: 4V5K99E42KN193551
- Mileage: 117,139 miles at service intake

Summary

U13499 received inspection/prep, Interior & exterior detail, ECM downloads, CARB check, windshield replacement, MV3 knob replacement, license frame and grille chrome repairs, cab hardware removal, and outlet particulate matter sensor repair with reset/regen for a clean, sale-ready presentation.
Eliminate downtime. If the wheels aren't turning, you're not earning.

Total Reconditioning Investment: **$3,119.69**

Source: scanned invoice packet, pages reviewed visually.

LENOX
MOBILE TRUCK REPAIR

Retail B

PM SERVICE & INSPECTION

B - Service & Inspection

CUSTOMER / FLEET NAME	DATE.	ODOMETER / ENGINE HOURS	REPAIR ORDER #
Charter Trucks	3/10/26	177,162	3824
ADDRESS	**UNIT NO.**	**VIN # (LAST 7 DIGITS)**	**VEHICLE MAKE & MODEL**
27000 Asti Road	U13499	N193551	Volvo / VHD
CITY, STATE / PROVINCE, ZIP / POSTAL CODE	**PHONE:**	**Inspection Location:**	
Cloverdale, CA. 95425	(707) 893-6428	Cloverdale, CA.	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

√ = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:	B
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	√
Air Leaks	√
Headlights - High & Low Beams	√
Road Lights	√
Clearance Lights / Reflectors	√
Turn Lights	√
Brake Lights	√
Emergency Flasher	√
Backup / Load Lights	√
License Plates, Permits & Mounting	√
Mud Flaps / Serviceable	√
Fuel Tank Mounting / Filler Cap in Place	√
Fuel Crossover Line (Droop, Damage) If equipped	√
Exhaust System-Condition, Leaks & Mounting Bolts	√
CAB - COE: Hold Down Latches	N
Inspect Clutch Cable (If Applicable)	N
Mounts	√
Front Pivot Assembly	√
Jack Operation & Leaks	N
Safety Locks, Tip-Over Stop (Visual Inspection)	√
INITIAL DRIVE IN:	**B**
Clutch Pedal Free Travel	N
Parking Brake - Brakes applied upon activation of control	√
Glass for Cracks or Chips	√
Steering Wheel Free Play & Column Mounting	√
Door Window Operation	√
Interior Lights	√
Cranking System Operation	√
Gauges / Warning Lights - Illumination / Operational:	√
Maintain Low Idle	√
Oil Pressure	√
Low Air Pressure Warning Devices	√
Air Cleaner Restriction Gauge	√
Electronic Warning Module / A&B Cluster Lights On/Off	√
Governed Air Pressure: 130 PSI - KpA	√
Air Pressure Drop-Brakes Not Applied: 0 (PSI - KpA/min.)	√
Air Pressure Drop-Brakes Applied: 0 (PSI - KpA/min.)	√
Windshield Wiper / Washer Condition & Operation	√
Horns (Electric & Air)	√
Mirrors / Heated / Motorized Operation	√
Drain Water from Air Tanks	√
Air Tank Check Value	√
Emergency Operation of Spring Brakes	√
Tractor Protection Valve Breakaway Test	√
Fire Extinguisher Charge	√
Flare Kit / Reflectors - Readily Accessible	√
BATTERIES:	**B**
Hold-Down & Box-Mounting Bolts	√
Signs of Over-Charging - Visual Inspection	√

Sealed Type - Condition:

Color of Charge Indicator for Each Battery

1.) green 2.) green 3.) green 4.) N/A

REAR FRAME	B
Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	√
5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	N
Air Lines & Glad-hands	√
Trailer Light Cord & Connectors	√
Pintle - Hook / Eye Mounting & Condition	√
Inner & Outer Hub Seals Leaks	√
Spring Shackles & Hanger Brackets	√
Spring Leaves / Bushings / Shocks / Air Bags	√
Radius Rods / Torque Arms	√
TIRES & WHEELS:	**B**
Missing Valve Caps / Tighten Stem Locks	√
Cracks or Loose Wheel Lugs	√
Tire Pressure (Record Below)	√
Remaining Tread (Record Below)	√

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle Driver Side:	PSI: 107	
	32nd's: 14	
Front Tandem Driver Side:	PSI: 94	PSI: 93
	32nd's: 14	32nd's: 15
Rear Tandem Driver Side	PSI: 92	PSI: 93
	32nd's: 12	32nd's: 11
Front Axle Pass. Side:	PSI: 105	
	32nd's: 15	
Front Tandem Pass. Side:	PSI: 93	PSI: 95
	32nd's: 10	32nd's: 11
Rear Tandem Pass. Side:	PSI: 89	PSI: 94
	32nd's: 12	32nd's: 13

Air Pressure Adjusted to Front Tires: 115 Rear Tires: 105

CHASSIS LUBE - BEGIN:	B
Lubricate Door Hinges & Latches	√
Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	√
UNDER VEHICLE:	**B**
Rear Axle Leaks & Lubricant Level	√
Rear Axle Breathers - Clear	√
Drive Lines - U-Joints & Slip Yokes	√
Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	√
Adjust Brakes - Check Auto Slack Adjusters	√

Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY

Circle one for each:

Front Axle L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Axle R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

UNDER VEHICLE (continued):	B
Drum Condition - Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY Front Axle L: Good Front Axle R: Good Front Tandem L: Good Front Tandem R: Good Rear Tandem L: Good Rear Tandem R: Good	
Transmission Leaks & Lubricant Level	√
Engine & Transmission Mounts	√
Engine Oil Pan Plug - Reinstall	√
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	√
Steering Shaft Splines & Joint(s)	√
Pitman Arm	√
Drag Link	√
Steering Arms	√
Tie Rod Arms	√
Tie Rod Ends	√
Radius Rods / Torque Arms	√
Spring Shackles & Hanger Brackets	√
King Pin Wear	√
Spring Leaves / Shocks / Air Bags	√
Front Axle Beam for Cracks or Obvious Welded Repairs	√
Wheel Bearing Play	√
Front Hub Lubricant Level / Leaks	√
ENGINE COMPARTMENT:	**B**
Engine Oil Level	√
Cranking System: Visual Inspection Loose Connections	√
Cab, Chassis Grounds	√
Steering Gear - Fluid Level	√
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	N
Drive Belt(s) Condition	√
Drive Belt(s) Adjustment	√
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	√
Fan Assembly & Idler Pulley	√
Fan Clutch & Over-Ride Operation	√
Radiator - Exterior Condition	√
Radiator Mounting	√
Hose Condition & Connections	√
Air Conditioning Compressor / Condenser Mounts / Leaks	√
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec SCA's OK ✔ Undercharged_____ Overcharged_____	
Coolant Level	√
Coolant Protection (Freeze Point): -34 ° (degrees Fahrenheit / Celcius)	√
Pressure Test / Check Leaks	√
Air Cleaning Mounting / Interference	√
Contaminent Accumulation	√
Vacuator Valve - Operation & Condition	√

DRIVER'S COMMENTS:

CHARTER REQUIREMENTS:	
One Spare Key	√
Replace Red & Yellow Brake Knobs if Faded	√
Top-off all Fluids	√
A/C Works	√
Air Blows Out of all Vents	√
Clean RH View Window	N
New Charter Flaps w/ Straight Hangers	√
Replace Door Seal if Damaged	√
Replace Q-Fenders if Damaged or Plastic	N
Replace Stack if Damaged or Rusty	√
Operate all Attached Equipment	√
Chrome Kit	√
Order Clean Idle Stickers if not there	√
Plug all Holes in Dash	√
Plug all Holes in Frame with Painted Bolt	√
Repair all Air Leaks	√

FOR DEALERSHIP USE ONLY

✔ This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection

VIN # N193551
(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: [signature]

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

[signature]

APPROVED BY: JR
CUSTOMER SIGNATURE REQUIRED HERE

This inspection comolies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: March 03, 2026 2:52 PM
Print Date: March 03, 2026 2:52 PM

VIN	4V5K99EH2KN193551
Vehicle Make	Volvo Truck
Model	VHD
Series	
Model Year	2019
Unit Number	U13499

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	Volvo D13 GHG17	18080392	23398790 23398805 23398871	J1939 (High) /J1587 (Low) /15765 (CAN)
Transmission	Volvo I-Shift Transmission	N/A	N/A	J1939 (High) /15765 (CAN)
Brakes	Bendix EC-80 ATC ABS	2W05181931	BB41274	J1939 (High) /15765 (CAN)
Instrument Cluster	Volvo Information Display	18073038	23317509 23317505 23317503	J1939 (High) /J1587 (Low)
Vehicle ECU	Volvo Vehicle ECU	17460092	23278399 23278405 23278401	J1939 (High) /J1587 (Low)
Shift Console - Primary	Volvo Gear Selector ECU	18035095	21833550 20714902 21833563	J1939 (High) /J1587 (Low)
Lighting - Operator Controls	Volvo Lighting Control Module	18078171	23337829 23169769 23254467	J1939 (High) /J1587 (Low)
Body Controller	Volvo Bodybuilder Module	17460092	22508337 22508340 22508348	J1587 (Low)
Cab Climate Control	Volvo Cab Climate Control	N/A	N/A	J1587 (Low)
Safety Restraint System	Volvo SRS Airbag ECU	00221021	21361812 21361837 21361839	J1587 (Low)

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: March 03, 2026 2:52 PM
Print Date: March 03, 2026 2:52 PM

Vehicle Key Data Points

Description	Parameter Value	Description	Parameter Value
Avg Fuel Econ	5.70 mpg	Idle Fuel Used	1,424.20 gal
Battery Potential	12.50 volts	DPF Soot Level	Low
Total Idle Hrs	1,730.70 hrs	DPF Derate	Low
Idle Shutdown	Not Available	Total Engine Run Time	6,186.90 hrs
Road Speed Limit	68.00 mph	Cruise Spd Limit	Not Available
PTO Status	Not Available	Malfunction Indicator Lamp	Off
Red Stop Lamp	Off	Amber Warning Lamp	Off
Protect Lamp	Off	Parking Brake Switch	On
Engine Speed	0 rpm	DPF Lamp Command	Off
Exhaust System High Temperature Lamp Command	Off	ABS Control Status	On
ABS Control Status, Trailer	Off	Odometer	117,162.90 mi
Engine Odometer	117,162.90 mi	Instrument Cluster Odometer	117,162.90 mi
Fuel	46%	Engine Oil	80%
Coolant	Normal	Diesel Exhaust Fluid	86%

Vehicle Issues

No Active Issues Found

Faults

Status	Component	Description	Lookup Code	FMI	Count

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____ Date _____