Truck Service Summary – Unit U13563

2020 Freightliner Cascadia

Inspection & Preparation

- Completed multi point PM inspection
- Topped off fluids and greased chassis
- Completed ECM download for records
- CTC passed

Mechanical Repairs

- Replaced leaking air tank fittings
- Replaced all eight drive tires
- Installed steel valve stems and caps
-

Electrical & Lighting

- Replaced rear license plate light housing
- Replaced 15’ coiled elc cable

Cab & Interior

- Made an extra key for the truck
- Replaced red and yellow MV3 knobs
- Replaced failed fire extinguisher
-

Exterior & Visibility

- Replaced license plate frames
- Completed interior & exterior detail package
- Replaced red & blue coiled air lines.

Add-Ons & General Service

-

Additional Work Performed

Final Service

- Returned unit to sale-ready condition

Vehicle Details

- VIN: 3AKJHTDV3LSMD9256
- Mileage: 432,926
- Model year: 2020 Freightliner
- Model: Cascadia

Summary

U13563 received inspection/prep, ECM/CTC checks, fluid, lighting/frame repairs, interior & exterior detail, air tank fitting repair, and eight new drive tires with valve hardware for a sale-ready presentation.
Eliminate downtime. If the wheels aren't turning, you're not earning.

Total Reconditioning Investment: **$5,174.94**

LENOX
MOBILE TRUCK REPAIR

Retail B

PM SERVICE & INSPECTION

B - Service & Inspection

CUSTOMER / FLEET NAME	DATE.	ODOMETER / ENGINE HOURS	REPAIR ORDER #
Charter Trucks	6/2/26	432,970	3825
ADDRESS	**UNIT NO.**	**VIN # (LAST 7 DIGITS)**	**VEHICLE MAKE & MODEL**
27000 Asti Road	U13563	SMD9256	Freightliner / Cascadia
CITY, STATE / PROVINCE, ZIP / POSTAL CODE	**PHONE:**	**Inspection Location:**	
Cloverdale, CA 95425	(707) 893-6428	Cloverdale, CA.	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

√ = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:	B
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	√
Air Leaks	√
Headlights - High & Low Beams	√
Road Lights	√
Clearance Lights / Reflectors	√
Turn Lights	√
Brake Lights	√
Emergency Flasher	√
Backup / Load Lights	√
License Plates, Permits & Mounting	√
Mud Flaps / Serviceable	√
Fuel Tank Mounting / Filler Cap in Place	√
Fuel Crossover Line (Droop, Damage) If equipped	√
Exhaust System-Condition, Leaks & Mounting Bolts	√
CAB - COE: Hold Down Latches	N
Inspect Clutch Cable (If Applicable)	N
Mounts	√
Front Pivot Assembly	√
Jack Operation & Leaks	N
Safety Locks, Tip-Over Stop (Visual Inspection)	√
INITIAL DRIVE IN:	**B**
Clutch Pedal Free Travel	N
Parking Brake - Brakes applied upon activation of control	√
Glass for Cracks or Chips	√
Steering Wheel Free Play & Column Mounting	√
Door Window Operation	√
Interior Lights	√
Cranking System Operation	√
Gauges / Warning Lights - Illumination / Operational:	√
Maintain Low Idle	√
Oil Pressure	√
Low Air Pressure Warning Devices	√
Air Cleaner Restriction Gauge	√
Electronic Warning Module / A&B Cluster Lights On/Off	√
Governed Air Pressure: 130 PSI - KpA	√
Air Pressure Drop-Brakes Not Applied: 0 (PSI - KpA/min.)	√
Air Pressure Drop-Brakes Applied: 0 (PSI - KpA/min.)	√
Windshield Wiper / Washer Condition & Operation	√
Horns (Electric & Air)	√
Mirrors / Heated / Motorized Operation	√
Drain Water from Air Tanks	√
Air Tank Check Value	√
Emergency Operation of Spring Brakes	√
Tractor Protection Valve Breakaway Test	√
Fire Extinguisher Charge	√
Flare Kit / Reflectors - Readily Accessible	√
BATTERIES:	**B**
Hold-Down & Box-Mounting Bolts	√
Signs of Over-Charging - Visual Inspection	√

Sealed Type - Condition:

Color of Charge Indicator for Each Battery

1.) green 2.) green 3.) green 4.) N/A

REAR FRAME	B
Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	√
5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	N
Air Lines & Glad-hands	√
Trailer Light Cord & Connectors	N
Pintle - Hook / Eye Mounting & Condition	N
Inner & Outer Hub Seals Leaks	√
Spring Shackles & Hanger Brackets	√
Spring Leaves / Bushings / Shocks / Air Bags	√
Radius Rods / Torque Arms	√
TIRES & WHEELS:	**B**
Missing Valve Caps / Tighten Stem Locks	√
Cracks or Loose Wheel Lugs	√
Tire Pressure (Record Below)	√
Remaining Tread (Record Below)	√

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle Driver Side:	PSI: 107	
	32nd's: 14	
Front Tandem Driver Side:	PSI: 94	PSI: 93
	32nd's: 14	32nd's: 15
Rear Tandem Driver Side	PSI: 92	PSI: 93
	32nd's: 12	32nd's: 11
Front Axle Pass. Side:	PSI: 105	
	32nd's: 15	
Front Tandem Pass. Side:	PSI: 93	PSI: 95
	32nd's: 10	32nd's: 11
Rear Tandem Pass. Side:	PSI: 89	PSI: 94
	32nd's: 12	32nd's: 13

Air Pressure Adjusted to Front Tires: 115 Rear Tires: 100

CHASSIS LUBE - BEGIN:	B
Lubricate Door Hinges & Latches	√
Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	√
UNDER VEHICLE:	**B**
Rear Axle Leaks & Lubricant Level	√
Rear Axle Breathers - Clear	√
Drive Lines - U-Joints & Slip Yokes	√
Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	√
Adjust Brakes - Check Auto Slack Adjusters	√

Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY

Circle one for each:

Front Axle L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Axle R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	✔	1/2" or more	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

UNDER VEHICLE (continued):	B
Drum Condition - Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY Front Axle L: Good Front Axle R: Good Front Tandem L: Good Front Tandem R: Good Rear Tandem L: Good Rear Tandem R: Good	
Transmission Leaks & Lubricant Level	√
Engine & Transmission Mounts	√
Engine Oil Pan Plug - Reinstall	√
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	√
Steering Shaft Splines & Joint(s)	√
Pitman Arm	√
Drag Link	√
Steering Arms	√
Tie Rod Arms	√
Tie Rod Ends	√
Radius Rods / Torque Arms	√
Spring Shackles & Hanger Brackets	√
King Pin Wear	√
Spring Leaves / Shocks / Air Bags	√
Front Axle Beam for Cracks or Obvious Welded Repairs	√
Wheel Bearing Play	√
Front Hub Lubricant Level / Leaks	√
ENGINE COMPARTMENT:	**B**
Engine Oil Level	√
Cranking System: Visual Inspection Loose Connections	√
Cab, Chassis Grounds	√
Steering Gear - Fluid Level	√
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	N
Drive Belt(s) Condition	√
Drive Belt(s) Adjustment	√
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	√
Fan Assembly & Idler Pulley	√
Fan Clutch & Over-Ride Operation	√
Radiator - Exterior Condition	√
Radiator Mounting	√
Hose Condition & Connections	√
Air Conditioning Compressor / Condenser Mounts / Leaks	√
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec SCA's OK ✔ Undercharged_____ Overcharged_____	
Coolant Level	√
Coolant Protection (Freeze Point): -34 ° (degrees Fahrenheit / Celcius)	√
Pressure Test / Check Leaks	√
Air Cleaning Mounting / Interference	√
Contaminent Accumulation	√
Vacuator Valve - Operation & Condition	√

DRIVER'S COMMENTS:

CHARTER REQUIREMENTS:	
One Spare Key	√
Replace Red & Yellow Brake Knobs if Faded	√
Top-off all Fluids	√
A/C Works	√
Air Blows Out of all Vents	√
Clean RH View Window	N
New Charter Flaps w/ Straight Hangers	√
Replace Door Seal if Damaged	√
Replace Q-Fenders if Damaged or Plastic	N
Replace Stack if Damaged or Rusty	√
Operate all Attached Equipment	√
Chrome Kit	√
Order Clean Idle Stickers if not there	√
Plug all Holes in Dash	√
Plug all Holes in Frame with Painted Bolt	√
Repair all Air Leaks	√

FOR DEALERSHIP USE ONLY

✔ This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection

VIN # SMD9256
(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: Parker

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

Charter

APPROVED BY: JR
CUSTOMER SIGNATURE REQUIRED HERE

This inspection comolies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: March 19, 2026 2:43 PM
Print Date: March 19, 2026 2:43 PM

VIN	3AKJHTDV3LSMD9256
Vehicle Make	Freightliner
Model	Cascadia
Series	
Model Year	2020
Unit Number	U13563

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine/CPC	Detroit DD13 CPC302T	471928S0736688	App_2109	J1939 (High) /15765 (CAN)
Transmission	Detroit DT12 TCM01T	N/A	20/41/00 000 022 0504482109-002 DTNA NAMT201403 2020-10-09	J1939 (High) /15765 (CAN)
Brakes	WABCO mBSP - Modular Braking System Platform 4S/4M	011671	N/A	J1939 (High) /15765 (CAN)
Instrumentation Control Unit	Freightliner Instrumentation Control Unit	N/A	N/A	J1939 (High) /15765 (CAN)
Switch Hub Module	Freightliner Switch Hub Module	N/A	N/A	J1939 (High)
Single SAM	Freightliner Single SAM	N/A	N/A	J1939 (High) /15765 (CAN)
Expansion Module	Freightliner Expansion Module	N/A	N/A	J1939 (High)
Forward Road Image Processor	DTNA Detroit Assurance Video Radar Decision Unit-VRDU	N/A	DETROIT_ASSURANCE_2	J1939 (High)
Central Gateway	DTNA Central Gateway	0000848467	20/05/03 020701 0004488527002 0 3	J1939 (High) /15765 (CAN)
Aftertreatment Control Module	Detroit DD13 ACM21T	N/A	acm_0x0250	J1939 (High) /15765 (CAN)
Motor Control Module	Detroit DD13 MCM21T	N/A	mcm_0x06F2	J1939 (High) /15765 (CAN)

Multipurpose Camera	Freightliner Multipurpose Camera	N/A	N/A	J1939 (High) /15765 (CAN)
Telematics	Freightliner Telematics	N/A	N/A	J1939 (High) /15765 (CAN)
Driver Door Control Module	Freightliner Driver Door Control Module	N/A	N/A	J1939 (High) /15765 (CAN)
Passenger Door Control Module	Freightliner Passenger Door Control Module	N/A	N/A	J1939 (High) /15765 (CAN)
Chassis Module	Freightliner Chassis Module	N/A	N/A	J1939 (High)
HVAC-Front Control Unit	Freightliner HVAC Front	N/A	N/A	J1939 (High) /15765 (CAN)
HVAC Auxiliary	Freightliner HVAC Auxiliary Control Unit	N/A	N/A	J1939 (High)
HVAC Parked	Freightliner HVAC Parked	N/A	N/A	J1939 (High)
Headway Controller	Freightliner Front Radar	N/A	N/A	J1939 (High) /15765 (CAN)
Short Range Radar	Freightliner Short Range Radar	N/A	N/A	J1939 (High)

LENOX
MOBILE TRUCK REPAIR

JPRO ® DIAGNOSTIC REPORT

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: March 19, 2026 2:43 PM
Print Date: March 19, 2026 2:43 PM

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	7.40 mpg
Battery Potential	12.00 volts
Total Idle Hrs	4,207.80 hrs
Idle Shutdown	5.00 min
Road Speed Limit	70.00 mph
PTO Status	Off/Disabled
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	0 rpm
Exhaust System High Temperature Lamp Command	Not Available
ABS Control Status, Trailer	Not Available
Engine Odometer	432,970.50 mi
Fuel	30%
Diesel Exhaust Fluid	38%

Description	Parameter Value
Idle Fuel Used	3,329.50 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	16,792.40 hrs
Cruise Spd Limit	70.00 mph
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Normal
ABS Control Status	Normal
Odometer	432,970.50 mi
Instrument Cluster Odometer	432,970.50 mi
Coolant	Normal

Vehicle Issues

No Active Faults

Faults

Status	Component	Description	Lookup Code	FMI	Count

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____

Date _____