Truck Service Summary – Unit U13626

2020 Freightliner Cascadia

Inspection & Preparation

- Completed 102 point PM inspection
- Checked fluids and greased chassis
- Completed full interior and exterior detail
- Removed decals for sale-ready presentation

Mechanical Repairs

- Serviced air dryer and replaced purge valve
- Replaced faded glad-hand extenders
- Verified repaired systems operated correctly

Electrical & Lighting

- Replaced passenger-side fog light
- Replaced passenger fender turn signal
- Tested repaired lights for proper operation
- Confirmed all noted lighting faults corrected

Cab & Interior

- Verified air conditioning operation
- Confirmed two keys supplied with unit
- Confirmed fire extinguisher and road kit
- Verified HVAC vents and cab equipment

Exterior & Visibility

- Installed Charter mudflaps and hangers
- Installed chrome license plate frames
- Installed chrome wheel hub cover

Add-Ons & General Service

- Installed chrome kit and related hardware
- Added premium windshield washer fluid
- Replaced missing A/C service valve cap
- Secured airlines and electrical lines

Additional Work Performed

- Verified deck plate and pogo equipment

Final Service

- Performed Clean Truck Check passed
- Tested air dryer and lighting repairs
- Returned unit to sale-ready condition

Vehicle Details

- VIN: 3AKJHTDV6LSLA9617
- Mileage: 201,281 miles at service intake
- Model: 2020 Freightliner Cascadia

Summary

U13626 received a 102 point PM inspection, interior and exterior detail, air dryer service, lighting repairs, Charter add-ons, and final system testing to support a clean, sale-ready presentation.
Eliminate downtime. If the wheels aren't turning, you're not earning.

Total Reconditioning Investment: **$3,101.87**

Source: scanned invoice packet, pages reviewed visually.

COAST COUNTIES Peterbilt Since 1949

PREVENTATIVE MAINTENANCE SERVICE & INSPECTION

Silver Level Inspection

CUSTOMER NAME: CHARTER SALES COMPANY	DATE 7-2-26	ODOMETER / ENGINE HOURS / FUEL 201,257	REPAIR ORDER # 91202
ADDRESS: 27000 ASTI RD. CLOVERDALE, CA 95425	UNIT NO. 13626	VIN # (LAST 7 DIGITS) SLA9617	VEHICLE MAKE & MODEL Freightliner Cascadia
	PHONE: 707.669.6202	DEALER NAME & CODE C506	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

√ = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:		REAR FRAME	
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	√	Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	√
Air Leaks	√	5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	√
Headlights - High & Low Beams	√	Air Lines & Glad-hands	√
Road Lights	√	Trailer Light Cord & Connectors	√
Clearance Lights / Reflectors	√	Pintle - Hook / Eye Mounting & Condition	√
Turn Lights	√	Inner & Outer Hub Seals Leaks	√
Brake Lights	√	Spring Shackles & Hanger Brackets	√
Emergency Flasher	√	Spring Leaves / Bushings / Shocks / Air Bags	√
Backup / Load Lights	√	Radius Rods / Torque Arms	√
License Plates, Permits & Mounting	√	**TIRES & WHEELS:**	
Mud Flaps / Serviceable	√	Missing Valve Caps / Tighten Stem Locks	√
Fuel Tank Mounting / Filler Cap in Place	√	Cracks or Loose Wheel Lugs	√
Fuel Crossover Line (Droop, Damage) If equipped	√	Tire Pressure (Record Below)	√
Exhaust System-Condition, Leaks & Mounting Bolts	√	Remaining Tread (Record Below)	√
INITIAL DRIVE IN:			
Clutch Pedal Free Travel	N/A		
Parking Brake - Brakes applied upon activation of control	√		
Glass for Cracks or Chips	√		
Steering Wheel Free Play & Column Mounting	√		
Door Window Operation	√		
Interior Lights	√		
Cranking System Operation	√		
Gauges / Warning Lights - Illumination / Operational:	√		
Maintain Low Idle	√		
Oil Pressure	√		
Low Air Pressure Warning Devices	√		
Air Cleaner Restriction Gauge	√		
Electronic Warning Module / A&B Cluster Lights On/Off	√		
Governed Air Pressure: 120 PSI - KpA	√		
Air Pressure Drop-Brakes Not Applied: 0 (PSI - KpA/min.)	√	**CHASSIS LUBE - BEGIN:**	
Air Pressure Drop-Brakes Applied: 5 (PSI - KpA/min.)	√	Lubricate Door Hinges & Latches	√
Windshield Wiper / Washer Condition & Operation	√	Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	√
Horns (Electric & Air)	√	**UNDER VEHICLE:**	
Mirrors / Heated / Motorized Operation	√	Rear Axle Leaks & Lubricant Level	√
Drain Water from Air Tanks	√	Rear Axle Breathers - Clear	√
Air Tank Check Value	√	Drive Lines - U-Joints & Slip Yokes	√
Emergency Operation of Spring Brakes	√	Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	√
Tractor Protection Valve Breakaway Test	√	Adjust Brakes - Check Auto Slack Adjusters	√
Fire Extinguisher Charge	√	Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY	
Flare Kit / Reflectors - Readily Accessible	√		
BATTERIES:			
Hold-Down & Box-Mounting Bolts	√		
Signs of Over-Charging - Visual Inspection	√		

Sealed Type - Condition:

Color of Charge Indicator for Each Battery

1.) 2.) 3.) 4.)

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle Driver Side:	PSI: 100	
	32nd's: 8	
Front Tandem Driver Side:	PSI: 100	PSI: 100
	32nd's: 23	32nd's: 23
Rear Tandem Driver Side	PSI: 100	PSI: 100
	32nd's: 17	32nd's: 17
Front Axle Pass. Side:	PSI: 100	
	32nd's: 8	
Front Tandem Pass. Side:	PSI: 100	PSI: 100
	32nd's: 23	32nd's: 23
Rear Tandem Pass. Side:	PSI: 100	PSI: 100
	32nd's: 17	32nd's: 17

Air Pressure Adjusted to Front Tires: 100 Rear Tires: 100

Circle one for each:

Front Axle L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Axle R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

UNDER VEHICLE (continued):		DRIVER'S COMMENTS:
Drum Condition - Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY		
Front Axle L: good		
Front Axle R: good		
Front Tandem L: good		
Front Tandem R: good		
Rear Tandem L: good		
Rear Tandem R: good		
Transmission Leaks & Lubricant Level	✓	
Engine & Transmission Mounts	✓	
Engine Oil Pan Plug - Reinstall	✓	**CHARTER REQUIREMENTS:**
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	✓	One Spare Key N/A
Steering Shaft Splines & Joint(s)	✓	Top-off all Fluids ✓
Pitman Arm	✓	A/C Works ✓
Drag Link	✓	Air Blows Out of all Vents ✓
Steering Arms	✓	Clean RH View Window ✓
Tie Rod Arms	✓	Chrome Kit ✓
Tie Rod Ends	✓	Order Clean Idle Stickers if not there ✓
Radius Rods / Torque Arms	✓	Repair all Air Leaks ✓
Spring Shackles & Hanger Brackets	✓	Replace Red & Yellow Brake Knob if faded ✓
King Pin Wear	✓	New Charter Flaps w/ Straight Hangers ✓
Spring Leaves / Shocks / Air Bags	✓	Operate all attached equipment ✓
Front Axle Beam for Cracks or Obvious Welded Repairs	✓	
Wheel Bearing Play	✓	
Front Hub Lubricant Level / Leaks	✓	
ENGINE COMPARTMENT:		
Engine Oil Level	✓	
Cranking System: Visual Inspection Loose Connections	✓	
Cab, Chassis Grounds	✓	
Steering Gear - Fluid Level	✓	
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	✓	
Drive Belt(s) Condition	✓	
Drive Belt(s) Adjustment	✓	
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	✓	
Fan Assembly & Idler Pulley	✓	
Fan Clutch & Over-Ride Operation	✓	
Radiator - Exterior Condition	✓	
Radiator Mounting	✓	
Hose Condition & Connections	✓	
Air Conditioning Compressor / Condenser Mounts / Leaks	✓	
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec		
SCA's OK_____ Undercharged_____ Overcharged_____		
Coolant Level	✓	
Coolant Protection (Freeze Point): -34 ° (degrees Fahrenheit / Celcius)	✓	
Pressure Test / Check Leaks	✓	
Air Cleaning Mounting / Interference	✓	
Contaminent Accumulation	✓	
Vacuator Valve - Operation & Condition	✓	

FOR DEALERSHIP USE ONLY

☐ This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection

VIN # SLA9617

(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: Juan F. Perez

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

APPROVED BY:_____

CUSTOMER SIGNATURE REQUIRED HERE

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

This inspection complies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: July 13, 2026 3:52 PM
Print Date: July 13, 2026 3:52 PM

VIN	3AKJHTDV6LSLA9617
Vehicle Make	Freightliner
Model	Cascadia
Series	
Model Year	2020
Unit Number	U13626

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine/CPC	Detroit DD13 CPC302T	471928S0663474	App_2109	J1939 (High) /15765 (CAN)
Transmission	Detroit DT12 TCM01T	N/A	19/20/01 000 020 0504481809-001 DTNA NAMT191402 2019-05-17	J1939 (High) /15765 (CAN)
Brakes	WABCO mBSP - Modular Braking System Platform 6S/4M	114300	N/A	J1939 (High) /15765 (CAN)
Instrumentation Control Unit	Freightliner Instrumentation Control Unit	N/A	N/A	J1939 (High)
HVAC-Front Control Unit	Freightliner HVAC Front	N/A	N/A	J1939 (High)
Single SAM	Freightliner Single SAM	N/A	N/A	J1939 (High) /15765 (CAN)
Headway Controller	DTNA Detroit Assurance Front Radar-RDF	N/A	DETROIT_ASSURANCE_2	J1939 (High)
HVAC Parked	Freightliner HVAC Parked	N/A	N/A	J1939 (High)
HVAC Auxiliary	Freightliner HVAC Auxiliary Control Unit	N/A	N/A	J1939 (High)
Telematics	Freightliner Telematics	N/A	N/A	J1939 (High)
Multipurpose Camera	Freightliner Multipurpose Camera	N/A	N/A	J1939 (High)
Short Range Radar	Freightliner Short Range Radar	N/A	N/A	J1939 (High)
Forward Road Image Processor	DTNA Detroit Assurance Video Radar Decision Unit-VRDU	N/A	DETROIT_ASSURANCE_2	J1939 (High)

Driver Door Control Module	Freightliner Driver Door Control Module	N/A	N/A	J1939 (High)
Passenger Door Control Module	Freightliner Passenger Door Control Module	N/A	N/A	J1939 (High)
Aftertreatment Control Module	Detroit DD13 ACM21T	N/A	acm_0x0250	J1939 (High) /15765 (CAN)
Motor Control Module	Detroit DD13 MCM21T	N/A	mcm_0x06ED	J1939 (High) /15765 (CAN)
Switch Hub Module	Freightliner Switch Hub Module	N/A	N/A	J1939 (High)
Central Gateway	DTNA Central Gateway	0000640940	17/46/00 020409 0004486727001 0 3	J1939 (High) /15765 (CAN)
Chassis Module	Freightliner Chassis Module	N/A	N/A	J1939 (High)
Expansion Module	Freightliner Expansion Module	N/A	N/A	J1939 (High)

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	6.10 mpg
Battery Potential	14.20 volts
Total Idle Hrs	3,892.70 hrs
Idle Shutdown	5.00 min
Road Speed Limit	78.00 mph
PTO Status	Off/Disabled
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	601 rpm
Exhaust System High Temperature Lamp Command	Not Available
ABS Control Status, Trailer	Not Available
Engine Odometer	201,281.55 mi
Fuel	25%
Diesel Exhaust Fluid	80%

Description	Parameter Value
Idle Fuel Used	1,515.60 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	10,987.00 hrs
Cruise Spd Limit	80.00 mph
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Not Available
ABS Control Status	Not Available
Odometer	201,281.55 mi
Instrument Cluster Odometer	201,281.55 mi
Coolant	Normal

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: July 13, 2026 3:52 PM
Print Date: July 13, 2026 3:52 PM

Vehicle Issues

No Active Faults

Faults

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____

Date _____