Coast Counties

Peterbilt

Retail A

PREVENTIVE MAINTENANCE SERVICE & INSPECTION

A - Service Inspection

Bronze

CUSTOMER / FLEET NAME	DATE	ODOMETER / ENGINE HOURS / FUEL	REPAIR ORDER #
Chester Sales	11-3-26	424,788	91955
ADDRESS	**UNIT NO.**	**VIN # (LAST 7 DIGITS)**	**VEHICLE MAKE & MODEL**
27000 Asti Rd	13709	F415473	Ken T680
CITY, STATE / PROVINCE, ZIP / POSTAL CODE	**PHONE**	**DEALER NAME & CODE**	
Cloverdale, CA 95425	707-669-6202	C506	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:
✓ = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:	A
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	✓
Air Leaks	✓
Headlights - High & Low Beams	✓
Road Lights	✓
Clearance Lights / Reflectors	✓
Turn Lights	✓
Brake Lights	✓
Emergency Flasher	✓
Backup / Load Lights	✓
License Plates, Permits & Mounting	✓
Mud Flaps / Serviceable	✓
Fuel Tank Mounting / Filler Cap in Place	✓
Fuel Crossover Line (Droop, Damage) If equipped	✓
Fuel Leaks	✓
INITIAL DRIVE IN:	**A**
Clutch Pedal Free Travel	✓
Glass for Cracks or Chips	✓
Cranking System Operation	✓
Windshield Wiper / Washer Condition & Operation	✓
Horns (Electric & Air)	✓
Air Cleaner Restriction Gauge	✓
Mirrors / Heated / Motorized Operation	✓
Drain Water from Air Tanks	✓
Emergency Operation of Spring Brakes	✓
Tractor Protection Valve Breakaway Test	✓
BATTERIES:	**A**
Batteries & Battery Cable Condition	✓
REAR FRAME:	**A**
5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	✓
Air Lines & Glad-hands	✓
Trailer Light Cord & Connectors	✓
Pintle - Hook / Eye Mounting & Condition	✓
TIRES & WHEELS:	**A**
Missing Valve Caps / Tighten Stem Locks	✓
Cracks Or Loose Wheel Lugs	✓
Tandem Mating / Tire Clearance	✓
Irregular Wear / Air Leaks	✓
Tire Pressure (Record Below)	✓
Remaining Tread (Record Below)	✓

ENGINE OIL CHANGE / CHASSIS LUBE - BEGIN:	A
Lubricate Door Hinges & Latches	✓
Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	✓
UNDER VEHICLE:	**A**
Rear Axle Breathers - Clear	✓
Adjust Brakes - Check Auto Slack Adjusters	✓
Rear Axle Leaks & Lubricant Level	✓
Drive Lines - U-Joints & Slip Yokes	✓

Drum Condition: Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY

Check 1 Box per column.

	Front Axle		Front Tandem		Rear Tandem	
	Left	Right	Left	Right	Left	Right
GOOD →	☑ ✓	☑ ✓	☑ ✓	☑ ✓	☐	☐
FAIR →	☐	☐	☐	☐	☐	☐
BAD →	☐	☐	☐	☐	☐	☐

Transmission Leaks & Lubricant Level	✓
ENGINE COMPARTMENT:	**A**
Check for Leaks: Engine Oil / Fuel	✓
Engine Oil Level	✓
Drive Belt(s) Condition	✓
Check Water Pump - Leaks	✓
Hose Condition & Connections	✓
Cooling: Check Supplemental Coolant Additive/Conditioner to Mfg Spec ☑ SCA's OK ☐ Undercharged ☐ Overcharged	✓
Coolant Level	✓
Coolant Protection (Freeze Point): -34 ° (degrees Fahrenheit / Celsius)	✓

DOT INSPECTION EXPIRATION DATE:
DAY / MONTH / YEAR

OTHER - INSPECTIONS EXPIRATION DATE:
DAY / MONTH / YEAR

DRIVER'S COMMENTS:

TECHNICIAN'S COMMENTS:

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle	Front Tandem	Rear Tandem
100 PSI / 17 32nd's	100 PSI / 17 32nd's	PSI / 32nd's
	100 PSI / 17 32nd's	PSI / 32nd's
100 PSI / 17 32nd's	100 PSI / 17 32nd's	PSI / 32nd's
	100 PSI / 17 32nd's	PSI / 32nd's

Air Pressure Adjusted to: 100 (Front Tires) / 100 (Rear Tires)

FOR OFFICE USE ONLY

☑ **THIS INSPECTION HAS BEEN COMPLETED**

VIN # F415473 (Last 7 Digits Required)

INSPECTED BY: Juan F. Perez

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC and PACCAR Inc., their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component or system.

APPROVED BY: _____

CUSTOMER SIGNATURE REQUIRED HERE

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: November 11, 2026 9:00 AM
Print Date: November 11, 2026 9:00 AM

VIN	3WKYAP8XXLF415473
Vehicle Make	Kenworth
Model	T680
Series	
Model Year	2020
Unit Number	U13709

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	PACCAR MX 13 EPA 17	Y209706	PC4_H1520P201A HP201A-10082 NA08b MY2019 EPA17 CMPNENT 37 CMPNENT 38 2312664	J1939 (High) /15765 (CAN)
Transmission	Eaton Advantage Series	P1295359	5570065 E265.e005	J1939 (High)
Brakes	WABCO E Series ABS E8 4S/4M	004020163439	2460030312 1.83.1.37 E801	J1939 (High) /15765 (CAN)
Cab Controller - Primary	PACCAR CECU3 500K	N/A	P30-1041	J1939 (High) /15765 (CAN)
Shift Console - Primary	PACCAR Right Hand Stalk Switch	N/A	S01926B00_D01	J1939 (High)
VECU	PACCAR VECU	N/A	2320818	J1939 (High) /15765 (CAN)

LENOX
MOBILE TRUCK REPAIR

JPRO ® DIAGNOSTIC REPORT

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: November 11, 2026 9:00 AM
Print Date: November 11, 2026 9:00 AM

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	6.60 mpg
Battery Potential	13.50 volts
Total Idle Hrs	3,168.40 hrs
Idle Shutdown	Not Available
Road Speed Limit	Not Available
PTO Status	Not Available
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	649 rpm
Exhaust System High Temperature Lamp Command	Off
ABS Control Status, Trailer	Not Available
Engine Odometer	424,812.21 mi
Fuel	27%
Diesel Exhaust Fluid	37%

Description	Parameter Value
Idle Fuel Used	2,316.00 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	11,406.60 hrs
Cruise Spd Limit	Not Available
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Off
ABS Control Status	Off
Odometer	424,812.21 mi
Instrument Cluster Odometer	424,812.21 mi
Coolant	Normal

Vehicle Issues

No Active Faults

Faults

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____

Date _____