Truck Service Summary – Unit U13517

2020 Kenworth T880

Inspection & Preparation

- Passed clean truck check
- Completed multi point PM inspection
- Checked lights, fluids, HVAC and equipment
- Greased chassis and saved ECM report

Mechanical Repairs

- Replaced leaking exhaust manifold assembly
- Replaced engine air cleaner filter
- Removed wheel lock; installed new lug nut

Electrical & Lighting

- Verified all lights during inspection
- Replaced turn signal bulb
- Repaired turn-signal terminal connection
- Installed coiled ABS electrical cable

Cab & Interior

- Replaced driver-side door check
- Confirmed A/C operation
- Confirmed airflow from all HVAC vents
- Cut additional key for final setup

Exterior & Visibility

- Completed wash/detail with decal removal
- Polished truck aluminum
- Repaired loose quarter fender hardware
- Installed chrome license-plate frames

Add-Ons & General Service

- Installed chrome hub cover kit
- Installed chrome pogo stick
- Replaced trailer air lines and glad-hands
- Added windshield washer fluid

Additional Work Performed

- Replaced exhaust stack and broken clamp
- Completed air dryer service
-

Final Service

- Rechecked air system - no leaks found
- Returned unit to sale-ready condition

Cooling System

- Drained coolant during manifold repair
- Refilled coolant after repair
- Added OAT coolant as needed
- Reconnected coolant and EGR cooler lines

Summary

U13517 received clean truck inspection, 90-day prep, exhaust/manifold repairs, air system service, lighting and cab repairs, interior and exterior detail, aluminum polish, and final regen/leak verification for a sale-ready presentation.
Eliminate downtime. If the wheels aren't turning, you're not earning.

Total Reconditioning Investment: **$8,957.32**

COAST COUNTIES Peterbilt Since 1949

PREVENTATIVE MAINTENANCE SERVICE & INSPECTION

Silver Level Inspection

CUSTOMER NAME: CHARTER SALES COMPANY	DATE 3/12/26	ODOMETER / ENGINE HOURS / FUEL 761,071	REPAIR ORDER # 90470
ADDRESS: 27000 ASTI RD. CLOVERDALE, CA 95425	UNIT NO. U13517	VIN # (LAST 7 DIGITS) CJ426254	VEHICLE MAKE & MODEL KW T880
	PHONE: 707.669.6202	DEALER NAME & CODE CCTE Windsor CS06	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

V = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:		REAR FRAME	
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	V	Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	V
Air Leaks	V	5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	V
Headlights - High & Low Beams	V	Air Lines & Glad-hands	V
Road Lights	V	Trailer Light Cord & Connectors	V
Clearance Lights / Reflectors	V	Pintle - Hook / Eye Mounting & Condition	N
Turn Lights	V	Inner & Outer Hub Seals Leaks	V
Brake Lights	V	Spring Shackles & Hanger Brackets	V
Emergency Flasher	V	Spring Leaves / Bushings / Shocks / Air Bags	V
Backup / Load Lights	V	Radius Rods / Torque Arms	V
License Plates, Permits & Mounting	V	**TIRES & WHEELS:**	
Mud Flaps / Serviceable	V	Missing Valve Caps / Tighten Stem Locks	V
Fuel Tank Mounting / Filler Cap in Place	V	Cracks or Loose Wheel Lugs	V
Fuel Crossover Line (Droop, Damage) If equipped	V	Tire Pressure (Record Below)	V
Exhaust System-Condition, Leaks & Mounting Bolts	V	Remaining Tread (Record Below)	V
INITIAL DRIVE IN:			
Clutch Pedal Free Travel	N		
Parking Brake - Brakes applied upon activation of control	V		
Glass for Cracks or Chips	V		
Steering Wheel Free Play & Column Mounting	V		
Door Window Operation	V		
Interior Lights	V		
Cranking System Operation	V		
Gauges / Warning Lights - Illumination / Operational:	V		
Maintain Low Idle	V		
Oil Pressure	V		
Low Air Pressure Warning Devices	V		
Air Cleaner Restriction Gauge	V		
Electronic Warning Module / A&B Cluster Lights On/Off	V		
Governed Air Pressure: 100-120 (PSI - KpA)	V	**CHASSIS LUBE - BEGIN:**	
Air Pressure Drop-Brakes Not Applied: 4 (PSI - KpA/min.)	V	Lubricate Door Hinges & Latches	V
Air Pressure Drop-Brakes Applied: 4 (PSI - KpA/min.)	V	Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	V
Windshield Wiper / Washer Condition & Operation	V	**UNDER VEHICLE:**	
Horns (Electric & Air)	V	Rear Axle Leaks & Lubricant Level	V
Mirrors / Heated / Motorized Operation	V	Rear Axle Breathers - Clear	N
Drain Water from Air Tanks	V	Drive Lines - U-Joints & Slip Yokes	V
Air Tank Check Value	V	Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	V
Emergency Operation of Spring Brakes	V	Adjust Brakes - Check Auto Slack Adjusters	V
Tractor Protection Valve Breakaway Test	V	Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY	
Fire Extinguisher Charge	V		
Flare Kit / Reflectors - Readily Accessible	V		
BATTERIES:			
Hold-Down & Box-Mounting Bolts	V		
Signs of Over-Charging - Visual Inspection	V		

Sealed Type - Condition:

Color of Charge Indicator for Each Battery

1.) 2.) 3.) 4.)

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle Driver Side:	PSI: 95			
	32nd's: 15			
Front Tandem Driver Side:	PSI: 90	PSI: 90		
	32nd's: 20	32nd's: 20		
Rear Tandem Driver Side	PSI: 90	PSI: 90		
	32nd's: 20	32nd's: 20		
Front Axle Pass. Side:	PSI: 95			
	32nd's: 15			
Front Tandem Pass. Side:	PSI: 90	PSI: 90		
	32nd's: 20	32nd's: 20		
Rear Tandem Pass. Side:	PSI: 90	PSI: 90		
	32nd's: 20	32nd's: 20		

Air Pressure Adjusted to Front Tires: 95 Rear Tires: 90

Circle one for each:

Front Axle L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Axle R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

UNDER VEHICLE (continued):	
Drum Condition - Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY	
Front Axle L: G	
Front Axle R: G	
Front Tandem L: G	
Front Tandem R: G	
Rear Tandem L: G	
Rear Tandem R: G	
Transmission Leaks & Lubricant Level	✓
Engine & Transmission Mounts	✓
Engine Oil Pan Plug - Reinstall	✓
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	✓
Steering Shaft Splines & Joint(s)	✓
Pitman Arm	✓
Drag Link	✓
Steering Arms	✓
Tie Rod Arms	✓
Tie Rod Ends	✓
Radius Rods / Torque Arms	✓
Spring Shackles & Hanger Brackets	✓
King Pin Wear	✓
Spring Leaves / Shocks / Air Bags	✓
Front Axle Beam for Cracks or Obvious Welded Repairs	✓
Wheel Bearing Play	✓
Front Hub Lubricant Level / Leaks	✓
ENGINE COMPARTMENT:	
Engine Oil Level	✓
Cranking System: Visual Inspection Loose Connections	✓
Cab, Chassis Grounds	✓
Steering Gear - Fluid Level	✓
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	✓
Drive Belt(s) Condition	✓
Drive Belt(s) Adjustment	✓
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	✓
Fan Assembly & Idler Pulley	✓
Fan Clutch & Over-Ride Operation	✓
Radiator - Exterior Condition	✓
Radiator Mounting	✓
Hose Condition & Connections	✓
Air Conditioning Compressor / Condenser Mounts / Leaks	✓
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec	
SCA's OK ✓ Undercharged ____ Overcharged ____	✓
Coolant Level	✓
Coolant Protection (Freeze Point): -30 ° (degrees Fahrenheit / Celcius)	✓
Pressure Test / Check Leaks	✓
Air Cleaning Mounting / Interference	✓
Contaminent Accumulation	✓
Vacuator Valve - Operation & Condition	✓

DRIVER'S COMMENTS:

CHARTER REQUIREMENTS:	
One Spare Key	✓
Top-off all Fluids	✓
A/C Works	✓
Air Blows Out of all Vents	✓
Clean RH View Window	✓
Chrome Kit	✓
Order Clean Idle Stickers if not there	✓
Repair all Air Leaks	✓
Replace Red & Yellow Brake Knob if faded	✓
New Charter Flaps w/ Straight Hangers	✓
Operate all attached equipment	✓

FOR DEALERSHIP USE ONLY

☐ **This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection**

VIN # LJ4262S4
(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: Jesus Ortiz

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

APPROVED BY: _____
CUSTOMER SIGNATURE REQUIRED HERE

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

This inspection complies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: April 17, 2026 12:15 PM
Print Date: April 17, 2026 12:15 PM

VIN	1XKZDP9X1LJ426254
Vehicle Make	Kenworth
Model	T880
Series	
Model Year	2020
Unit Number	U13517

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	PACCAR MX 13 EPA 17	Y219602	PC4_H1520P201A HP201A-10082 NA08b MY2019 EPA17 CMPNENT 37 CMPNENT 38 2312664	J1939 (High) /15765 (CAN)
Transmission	Eaton Advantage Series	K1358150	5570065 E265.e005	J1939 (High)
Brakes	Bendix EC-80 ESP ABS	6234190375	Z091290	J1939 (High) /15765 (CAN)
VECU	PACCAR VECU	N/A	2320818	J1939 (High) /15765 (CAN)
Cab Controller - Primary	PACCAR CECU3 500K	N/A	P30-1041	J1939 (High) /15765 (CAN)
Shift Console - Primary	PACCAR Right Hand Stalk Switch	N/A	S01926B00_D01	J1939 (High)

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: April 17, 2026 12:15 PM
Print Date: April 17, 2026 12:15 PM

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	6.10 mpg
Battery Potential	12.80 volts
Total Idle Hrs	5,379.80 hrs
Idle Shutdown	Not Available
Road Speed Limit	Not Available
PTO Status	Not Available
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	0 rpm
Exhaust System High Temperature Lamp Command	Off
ABS Control Status, Trailer	Off
Engine Odometer	261,358.02 mi
Fuel	30%
Diesel Exhaust Fluid	89%

Description	Parameter Value
Idle Fuel Used	4,311.70 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	11,308.00 hrs
Cruise Spd Limit	Not Available
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Off
ABS Control Status	Off
Odometer	261,358.02 mi
Instrument Cluster Odometer	261,358.02 mi
Coolant	Normal

Vehicle Issues

No Active Issues Found

Faults

Status	Component	Description	Lookup Code	FMI	Count

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____ Date _____