Truck Service Summary – Unit U13518

2020 Kenworth T880

Inspection & Preparation

- Completed multi point PM inspection
- Performed clean-truck check and passed
- Checked lights, fluids, A/C and equipment
- Greased chassis and saved ECM report

Mechanical Repairs

- Replaced clutch assembly and hardware
- Replaced front carrier bearing assembly
- Replaced two torque rods
- Repaired A/C with compressor and TXV

Electrical & Lighting

- Corrected headlight harness lock issue
- Replaced sealed 14-way connector
- Verified all lights during inspection
-

Cab & Interior

- Confirmed Air blowing from all HVAC vents
- Confirmed two keys and safety items
- Verified cab equipment operation

Exterior & Visibility

- Completed interior & exterior detail/decal removal
- Polished aluminum exterior components
- Replaced quarter fender

Add-Ons & General Service

- Installed Charter mudflaps/hardware
- Added chrome hub covers and frames
- Zip-tied air/ELC lines and checked deck
- Replaced loose turn-signal switch kit

Additional Work Performed

- Repaired air leak with new tubing
- Replaced receiver/dryer and hose clamp
- Replaced drive tire during service

Final Service

- Completed final sale-ready presentation
- Verified inspection items after repairs

Vehicle Details

- VIN: 1XKZDP9XXLJ426253
- Mileage: 245,695 miles at service intake

Summary

U13518 received multi point inspection/prep, clutch repair, A/C repair, electrical connector work, air leak repair, torque rods, carrier bearing, Charter add-ons, detailing/polish, and tire service to support a clean, sale-ready presentation.

Eliminate downtime. If the wheels aren't turning, you're not earning.

Total Reconditioning Investment: **$11,778.04**

Source: scanned invoice packet, all 12 pages reviewed visually.

COAST COUNTIES Peterbilt Since 1949

PREVENTATIVE MAINTENANCE SERVICE & INSPECTION

Silver Level Inspection

CUSTOMER NAME: CHARTER SALES COMPANY	DATE 3/31/26	ODOMETER / ENGINE HOURS / FUEL	REPAIR ORDER # 90471
ADDRESS: 27000 ASTI RD. CLOVERDALE, CA 95425	UNIT NO. 013518	VIN # (LAST 7 DIGITS)	VEHICLE MAKE & MODEL
	PHONE: 707.669.6202	DEALER NAME & CODE	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

√ = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:		REAR FRAME	
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	X	Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	√
Air Leaks	X	5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	√
Headlights - High & Low Beams	X	Air Lines & Glad-hands	√
Road Lights	√	Trailer Light Cord & Connectors	√
Clearance Lights / Reflectors	√	Pintle - Hook / Eye Mounting & Condition	√
Turn Lights	√	Inner & Outer Hub Seals Leaks	√
Brake Lights	√	Spring Shackles & Hanger Brackets	√
Emergency Flasher	√	Spring Leaves / Bushings / Shocks / Air Bags	√
Backup / Load Lights	√	Radius Rods / Torque Arms	X
License Plates, Permits & Mounting	√	**TIRES & WHEELS:**	
Mud Flaps / Serviceable	√	Missing Valve Caps / Tighten Stem Locks	√
Fuel Tank Mounting / Filler Cap in Place	√	Cracks or Loose Wheel Lugs	√
Fuel Crossover Line (Droop, Damage) If equipped	√	Tire Pressure (Record Below)	√
Exhaust System-Condition, Leaks & Mounting Bolts	√	Remaining Tread (Record Below)	
INITIAL DRIVE IN:			
Clutch Pedal Free Travel	√		
Parking Brake - Brakes applied upon activation of control	√		
Glass for Cracks or Chips	√		
Steering Wheel Free Play & Column Mounting	√		
Door Window Operation	√		
Interior Lights	√		
Cranking System Operation	√		
Gauges / Warning Lights - Illumination / Operational:			
Maintain Low Idle	√		
Oil Pressure	√		
Low Air Pressure Warning Devices	√		
Air Cleaner Restriction Gauge	√		
Electronic Warning Module / A&B Cluster Lights On/Off	√		
Governed Air Pressure: _____ PSI - KpA	√		
Air Pressure Drop-Brakes Not Applied: 1 (PSI - KpA/min.)	√	**CHASSIS LUBE - BEGIN:**	
Air Pressure Drop-Brakes Applied: 0 (PSI - KpA/min.)	√	Lubricate Door Hinges & Latches	√
Windshield Wiper / Washer Condition & Operation	√	Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	√
Horns (Electric & Air)	√	**UNDER VEHICLE:**	
Mirrors / Heated / Motorized Operation	√	Rear Axle Leaks & Lubricant Level	√
Drain Water from Air Tanks	√	Rear Axle Breathers - Clear	√
Air Tank Check Value	√	Drive Lines - U-Joints & Slip Yokes	X
Emergency Operation of Spring Brakes	√	Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	√
Tractor Protection Valve Breakaway Test	√	Adjust Brakes - Check Auto Slack Adjusters	√
Fire Extinguisher Charge	√	Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY	
Flare Kit / Reflectors - Readily Accessible	√		
BATTERIES:			
Hold-Down & Box-Mounting Bolts	√		
Signs of Over-Charging - Visual Inspection	√		
Sealed Type - Condition:			
Color of Charge Indicator for Each Battery			
1.) 2.) 3.) 4.)			

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle Driver Side:	PSI: 100	
	32nd's: 17	
Front Tandem Driver Side:	PSI: 110	PSI: 110
	32nd's: 12	32nd's: 12
Rear Tandem Driver Side	PSI: 110	PSI: 110
	32nd's: 13	32nd's: 13
Front Axle Pass. Side:	PSI: 100	
	32nd's: 15	
Front Tandem Pass. Side:	PSI: 110	PSI: 110
	32nd's: 13	32nd's:
Rear Tandem Pass. Side:	PSI: 110	PSI: 110
	32nd's: 13	32nd's: 14

Air Pressure Adjusted to Front Tires: _____ Rear Tires: _____

Circle one for each:

Front Axle L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Axle R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

UNDER VEHICLE (continued):	
Drum Condition - Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY	
Front Axle L: fair	
Front Axle R: fair	
Front Tandem L: fair	
Front Tandem R: fair	
Rear Tandem L: fair	
Rear Tandem R: fair	
Transmission Leaks & Lubricant Level	✓
Engine & Transmission Mounts	✓
Engine Oil Pan Plug - Reinstall	✓
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	✓
Steering Shaft Splines & Joint(s)	✓
Pitman Arm	✓
Drag Link	✓
Steering Arms	✓
Tie Rod Arms	✓
Tie Rod Ends	✓
Radius Rods / Torque Arms	✓
Spring Shackles & Hanger Brackets	✓
King Pin Wear	✓
Spring Leaves / Shocks / Air Bags	✓
Front Axle Beam for Cracks or Obvious Welded Repairs	✓
Wheel Bearing Play	✓
Front Hub Lubricant Level / Leaks	✓
ENGINE COMPARTMENT:	
Engine Oil Level	✓
Cranking System: Visual Inspection Loose Connections	✓
Cab, Chassis Grounds	✓
Steering Gear - Fluid Level	✓
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	✓
Drive Belt(s) Condition	✓
Drive Belt(s) Adjustment	✓
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	✓
Fan Assembly & Idler Pulley	✓
Fan Clutch & Over-Ride Operation	✓
Radiator - Exterior Condition	✓
Radiator Mounting	✓
Hose Condition & Connections	✓
Air Conditioning Compressor / Condenser Mounts / Leaks	✓
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec	
SCA's OK_____ Undercharged_____ Overcharged_____	
Coolant Level	✓
Coolant Protection (Freeze Point): -32 ° (degrees Fahrenheit / Celcius)	✓
Pressure Test / Check Leaks	✓
Air Cleaning Mounting / Interference	✓
Contaminent Accumulation	
Vacuator Valve - Operation & Condition	

DRIVER'S COMMENTS:

CHARTER REQUIREMENTS:	
One Spare Key	✓
Top-off all Fluids	✓
A/C Works	⊗
Air Blows Out of all Vents	✓
Clean RH View Window N/A	
Chrome Kit	✓
Order Clean Idle Stickers if not there	✓
Repair all Air Leaks	✓
Replace Red & Yellow Brake Knob if faded	✓
New Charter Flaps w/ Straight Hangers	✓
Operate all attached equipment	✓

FOR DEALERSHIP USE ONLY

☐ **This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection**

VIN # _____

(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: Miguel Arreola

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

APPROVED BY: _____

CUSTOMER SIGNATURE REQUIRED HERE

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

This inspection complies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: April 07, 2026 8:49 AM
Print Date: April 07, 2026 8:49 AM

VIN	1XKZDP9XXLJ426253
Vehicle Make	Kenworth
Model	T880
Series	
Model Year	2020
Unit Number	U13518

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	PACCAR MX 13 EPA 17	Y219601	PC4_H1520P201A HP201A-10082 NA08b MY2019 EPA17 CMPNENT 37 CMPNENT 38 2312664	J1939 (High) /15765 (CAN)
Transmission	Eaton Advantage Series	K1358151	5570065 E265.e005	J1939 (High)
Brakes	Bendix EC-80 ESP ABS	6234191535	Z091290	J1939 (High) /15765 (CAN)
Cab Controller - Primary	PACCAR CECU3 500K	N/A	P30-1041	J1939 (High) /15765 (CAN)
VECU	PACCAR VECU	N/A	2320818	J1939 (High) /15765 (CAN)
Shift Console - Primary	PACCAR Right Hand Stalk Switch	N/A	S01926B00_D01	J1939 (High)

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: April 07, 2026 8:49 AM
Print Date: April 07, 2026 8:49 AM

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	6.10 mpg
Battery Potential	13.10 volts
Total Idle Hrs	5,702.80 hrs
Idle Shutdown	Not Available
Road Speed Limit	Not Available
PTO Status	Not Available
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	0 rpm
Exhaust System High Temperature Lamp Command	Off
ABS Control Status, Trailer	Off
Engine Odometer	245,722.04 mi
Fuel	39%
Diesel Exhaust Fluid	36%

Description	Parameter Value
Idle Fuel Used	4,661.30 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	11,680.80 hrs
Cruise Spd Limit	Not Available
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Off
ABS Control Status	Off
Odometer	245,722.04 mi
Instrument Cluster Odometer	245,722.04 mi
Coolant	Normal

Vehicle Issues

No Active Faults

Faults

Status	Component	Description	Lookup Code	FMI	Count

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____ Date _____