Truck Service Summary - Unit U13684

2020 Peterbilt 567

Inspection & Preparation

- Completed PM inspection and diagnostic checks
- Performed Clean Truck Check and passed
- Completed interior and exterior detail and removed decals

Mechanical Repairs

- Replaced leaking EGR flex pipe and gasket
- Replaced oil pan gasket and resealed oil pan
- Serviced air dryer and replaced torque rods
- Resealed power-steering reservoir clamp and cap

Electrical & Lighting

- Diagnosed active fault codes and DEF pressure system
- Repaired door-harness connection during diagnostics
- Replaced windshield-washer pump/bottle assembly
- No additional lighting repairs noted

Cab & Interior

- Replaced passenger-side door check assembly
- Replaced faded brake knobs and visor clips
- Replaced right-side HVAC/cab air filters
- Added extra key and cab trim/hardware items

Exterior & Visibility

- Replaced right hood-lock strut and cowl seal
- Installed license-plate frame and Charter mudflaps
- Replaced glad hand/pogo-stick components
-

Add-Ons & General Service

- Replaced primary and secondary fuel filters
- Replaced hydraulic oil filter
- Installed missing flare kit and valve-stem caps
- Set road-speed governor to 70 MPH

Additional Work Performed

- Replaced DEF/crankcase ventilation related components
- Replaced pressure sensor, hoses and filter components
- Installed battery-box strut and interior visor clips
-

Final Service

- Verified repairs after diagnostic and service work
- Completed final inspection-related corrections
- Returned unit to sale-ready condition

Vehicle Details

- VIN: 1XPCDP9X8LD638230
- Mileage: 350,388 miles at service intake

Summary

U13684 received diagnostic and PM inspections, emissions/DEF-related repairs, EGR flex pipe and oil-pan leak repairs, air-system and suspension service, cab and visibility corrections, filter service, exterior detailing, and final compliance work to support a clean, sale-ready truck.

Total Reconditioning Investment: **$9,373.06**

COAST COUNTIES Peterbilt Since 1949

PREVENTATIVE MAINTENANCE SERVICE & INSPECTION

Silver Level Inspection

CUSTOMER NAME: CHARTER SALES COMPANY	DATE 9-8-26	ODOMETER / ENGINE HOURS / FUEL 350,388	REPAIR ORDER # 91604
ADDRESS: 27000 ASTI RD. CLOVERDALE, CA 95425	UNIT NO. U13684	VIN # (LAST 7 DIGITS) LD638230	VEHICLE MAKE & MODEL Peterbilt 567
	PHONE: 707.669.6202	DEALER NAME & CODE Coast Counties Peterbilt C506	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

√ = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:		REAR FRAME	
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	√	Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	√
Air Leaks	√	5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	√
Headlights - High & Low Beams	√	Air Lines & Glad-hands	√
Road Lights	√	Trailer Light Cord & Connectors	√
Clearance Lights / Reflectors	√	Pintle - Hook / Eye Mounting & Condition	√
Turn Lights	√	Inner & Outer Hub Seals Leaks	√
Brake Lights	√	Spring Shackles & Hanger Brackets	√
Emergency Flasher	√	Spring Leaves / Bushings / Shocks / Air Bags	√
Backup / Load Lights	√	Radius Rods / Torque Arms	√
License Plates, Permits & Mounting	√	**TIRES & WHEELS:**	
Mud Flaps / Serviceable	√	Missing Valve Caps / Tighten Stem Locks	√
Fuel Tank Mounting / Filler Cap in Place	√	Cracks or Loose Wheel Lugs	√
Fuel Crossover Line (Droop, Damage) If equipped	√	Tire Pressure (Record Below)	√
Exhaust System-Condition, Leaks & Mounting Bolts	√	Remaining Tread (Record Below)	√
INITIAL DRIVE IN:		**TIRE INSPECTION**	
Clutch Pedal Free Travel	√	**Enter Air Pressure Before Adjustment**	
Parking Brake - Brakes applied upon activation of control	√	Front Axle Driver Side: PSI: 107.3	
Glass for Cracks or Chips	√	32nd's: 18	
Steering Wheel Free Play & Column Mounting	√	Front Tandem Driver Side: PSI: 84 PSI: 86	
Door Window Operation	√	32nd's: 6 32nd's: 5	
Interior Lights	√	Rear Tandem Driver Side PSI: 84 PSI: 95	
Cranking System Operation	√	32nd's: 17 32nd's: 17	
Gauges / Warning Lights - Illumination / Operational:	√	Front Axle Pass. Side: PSI: 110.8	
Maintain Low Idle	√	32nd's: 17	
Oil Pressure	√	Front Tandem Pass. Side: PSI: 86 PSI: 85	
Low Air Pressure Warning Devices	√	32nd's: 7 32nd's: 13	
Air Cleaner Restriction Gauge	√	Rear Tandem Pass. Side: PSI: 84 PSI: 96	
Electronic Warning Module / A&B Cluster Lights On/Off	√	32nd's: 17 32nd's: 19	
Governed Air Pressure: _____ PSI - KpA	√	Air Pressure Adjusted to Front Tires: 110 Rear Tires: 95	
Air Pressure Drop-Brakes Not Applied: _____ (PSI - KpA/min.)	√	**CHASSIS LUBE - BEGIN:**	
Air Pressure Drop-Brakes Applied: _____ (PSI - KpA/min.)	√	Lubricate Door Hinges & Latches	√
Windshield Wiper / Washer Condition & Operation	√	Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	√
Horns (Electric & Air)	√	**UNDER VEHICLE:**	
Mirrors / Heated / Motorized Operation	√	Rear Axle Leaks & Lubricant Level	√
Drain Water from Air Tanks	√	Rear Axle Breathers - Clear	√
Air Tank Check Value	√	Drive Lines - U-Joints & Slip Yokes	√
Emergency Operation of Spring Brakes	√	Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	√
Tractor Protection Valve Breakaway Test	√	Adjust Brakes - Check Auto Slack Adjusters	√
Fire Extinguisher Charge	√	Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY	
Flare Kit / Reflectors - Readily Accessible	√		
BATTERIES:			
Hold-Down & Box-Mounting Bolts	√		
Signs of Over-Charging - Visual Inspection	√		

Sealed Type - Condition:

Color of Charge Indicator for Each Battery

1.) Green 2.) Green 3.) Green 4.)

Circle one for each:

Front Axle L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Axle R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

UNDER VEHICLE (continued):	
Drum Condition - Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY	
Front Axle L: NA	
Front Axle R: NA	
Front Tandem L: Fair	
Front Tandem R: Fair	
Rear Tandem L: Fair	
Rear Tandem R: Fair	
Transmission Leaks & Lubricant Level	✓
Engine & Transmission Mounts	✓
Engine Oil Pan Plug - Reinstall	✓
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	✓
Steering Shaft Splines & Joint(s)	✓
Pitman Arm	✓
Drag Link	✓
Steering Arms	✓
Tie Rod Arms	✓
Tie Rod Ends	✓
Radius Rods / Torque Arms	✓
Spring Shackles & Hanger Brackets	✓
King Pin Wear	✓
Spring Leaves / Shocks / Air Bags	✓
Front Axle Beam for Cracks or Obvious Welded Repairs	✓
Wheel Bearing Play	✓
Front Hub Lubricant Level / Leaks	✓
ENGINE COMPARTMENT:	
Engine Oil Level	✓
Cranking System: Visual Inspection Loose Connections	✓
Cab, Chassis Grounds	✓
Steering Gear - Fluid Level	✓
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	NA
Drive Belt(s) Condition	✓
Drive Belt(s) Adjustment	✓
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	✓
Fan Assembly & Idler Pulley	✓
Fan Clutch & Over-Ride Operation	✓
Radiator - Exterior Condition	✓
Radiator Mounting	✓
Hose Condition & Connections	✓
Air Conditioning Compressor / Condenser Mounts / Leaks	✓
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec	
SCA's OK_____ Undercharged_____ Overcharged_____	
Coolant Level	✓
Coolant Protection (Freeze Point): -32 ° (degrees Fahrenheit / Celcius)	✓
Pressure Test / Check Leaks	✓
Air Cleaning Mounting / Interference	✓
Contaminent Accumulation	✓
Vacuator Valve - Operation & Condition	✓

DRIVER'S COMMENTS:

CHARTER REQUIREMENTS:	
One Spare Key	✓
Top-off all Fluids	✓
A/C Works	✓
Air Blows Out of all Vents	✓
Clean RH View Window	✓
Chrome Kit	✓
Order Clean Idle Stickers if not there	✓
Repair all Air Leaks	✓
Replace Red & Yellow Brake Knob if faded	✓
New Charter Flaps w/ Straight Hangers	✓
Operate all attached equipment	✓

FOR DEALERSHIP USE ONLY

✓ This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection

VIN # LD638230
(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: Jose Ponce

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

APPROVED BY:_____
CUSTOMER SIGNATURE REQUIRED HERE

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

This inspection complies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: September 23, 2026 9:11 AM
Print Date: September 23, 2026 9:11 AM

VIN	1XPCDP9X8LD638230
Vehicle Make	Peterbilt
Model	567
Series	
Model Year	2020
Unit Number	U13684

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	PACCAR MX 13 EPA 17	Y208297	PC4_H1520P201A HP201A-10082 NA08b MY2019 EPA17 CMPNENT 37 CMPNENT 38 2312664	J1939 (High)
Brakes	Bendix EC-80 ESP ABS	6222190717	Z091290	J1939 (High) /15765 (CAN)
Cab Controller - Primary	PACCAR CECU3 500K	N/A	P30-1041	J1939 (High) /15765 (CAN)

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: September 23, 2026 9:11 AM
Print Date: September 23, 2026 9:11 AM

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	7.20 mpg
Battery Potential	13.90 volts
Total Idle Hrs	2,042.70 hrs
Idle Shutdown	Not Available
Road Speed Limit	Not Available
PTO Status	Off/Disabled
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	650 rpm
Exhaust System High Temperature Lamp Command	Off
ABS Control Status, Trailer	Off
Engine Odometer	350,412.36 mi
Fuel	54%
Diesel Exhaust Fluid	57%

Description	Parameter Value
Idle Fuel Used	1,536.70 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	9,455.90 hrs
Cruise Spd Limit	Not Available
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Off
ABS Control Status	Off
Odometer	350,412.36 mi
Instrument Cluster Odometer	350,412.36 mi
Coolant	Normal

Vehicle Issues

No Active Fault(s) Present

Faults

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____

Date _____