COAST COUNTIES Peterbilt Since 1949

PREVENTATIVE MAINTENANCE SERVICE & INSPECTION

Silver Level Inspection

CUSTOMER NAME: CHARTER SALES COMPANY	DATE 10-30-26	ODOMETER / ENGINE HOURS / FUEL 330796, 16956	REPAIR ORDER #
ADDRESS: 27000 ASTI RD. CLOVERDALE, CA 95425	UNIT NO. U13699P	VIN # (LAST 7 DIGITS) LD687287	VEHICLE MAKE & MODEL Peterbilt 579
	PHONE: 707.669.6202	DEALER NAME & CODE	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

√ = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:		REAR FRAME	
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers		Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	√
Air Leaks	√	5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	√
Headlights - High & Low Beams	√	Air Lines & Glad-hands	√
Road Lights	√	Trailer Light Cord & Connectors	√
Clearance Lights / Reflectors	√	Pintle - Hook / Eye Mounting & Condition	√
Turn Lights	√	Inner & Outer Hub Seals Leaks	√
Brake Lights	√	Spring Shackles & Hanger Brackets	√
Emergency Flasher	√	Spring Leaves / Bushings / Shocks / Air Bags	√
Backup / Load Lights	√	Radius Rods / Torque Arms	√
License Plates, Permits & Mounting	√	**TIRES & WHEELS:**	
Mud Flaps / Serviceable	√	Missing Valve Caps / Tighten Stem Locks	√
Fuel Tank Mounting / Filler Cap in Place	√	Cracks or Loose Wheel Lugs	√
Fuel Crossover Line (Droop, Damage) If equipped	√	Tire Pressure (Record Below)	√
Exhaust System-Condition, Leaks & Mounting Bolts	√	Remaining Tread (Record Below)	√
INITIAL DRIVE IN:			
Clutch Pedal Free Travel	NA		
Parking Brake - Brakes applied upon activation of control	√		
Glass for Cracks or Chips	√		
Steering Wheel Free Play & Column Mounting	√		
Door Window Operation	√		
Interior Lights	√		
Cranking System Operation	√		
Gauges / Warning Lights - Illumination / Operational:			
Maintain Low Idle	√		
Oil Pressure	√		
Low Air Pressure Warning Devices	√		
Air Cleaner Restriction Gauge	√		
Electronic Warning Module / A&B Cluster Lights On/Off	√		
Governed Air Pressure: 120 PSI - KpA	√		
Air Pressure Drop-Brakes Not Applied: 0 (PSI - KpA/min.)	√		
Air Pressure Drop-Brakes Applied: 10 (PSI - KpA/min.)	√		
Windshield Wiper / Washer Condition & Operation	√		
Horns (Electric & Air)	√		
Mirrors / Heated / Motorized Operation	√		
Drain Water from Air Tanks	√		
Air Tank Check Value	√		
Emergency Operation of Spring Brakes	√		
Tractor Protection Valve Breakaway Test	√		
Fire Extinguisher Charge	√		
Flare Kit / Reflectors - Readily Accessible	√		
BATTERIES:			
Hold-Down & Box-Mounting Bolts	√		
Signs of Over-Charging - Visual Inspection	√		

Sealed Type - Condition:

Color of Charge Indicator for Each Battery

1.) 2.) 3.) 4.)

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle Driver Side:	PSI: 100			
	32nd's: 12			
Front Tandem Driver Side:	PSI: 105	PSI: 105		
	32nd's: 14	32nd's: 14		
Rear Tandem Driver Side	PSI: 105	PSI: 105		
	32nd's:	32nd's:		
Front Axle Pass. Side:	PSI: 105			
	32nd's: 13			
Front Tandem Pass. Side:	PSI: 105	PSI: 105		
	32nd's: 20	32nd's: 20		
Rear Tandem Pass. Side:	PSI:	PSI:		
	32nd's:	32nd's:		

Air Pressure Adjusted to Front Tires:_____ Rear Tires:_____

CHASSIS LUBE - BEGIN:	
Lubricate Door Hinges & Latches	√
Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	√
UNDER VEHICLE:	
Rear Axle Leaks & Lubricant Level	√
Rear Axle Breathers - Clear	√
Drive Lines - U-Joints & Slip Yokes	√
Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	√
Adjust Brakes - Check Auto Slack Adjusters	√

Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY

Circle one for each:

Front Axle L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Axle R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

UNDER VEHICLE (continued):	
Drum Condition - Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY	
Front Axle L: Good	
Front Axle R: Good	
Front Tandem L: Good	
Front Tandem R: Good	
Rear Tandem L:	
Rear Tandem R:	
Transmission Leaks & Lubricant Level	✓
Engine & Transmission Mounts	✓
Engine Oil Pan Plug - Reinstall	✓
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	✓
Steering Shaft Splines & Joint(s)	✓
Pitman Arm	✓
Drag Link	✓
Steering Arms	✓
Tie Rod Arms	✓
Tie Rod Ends	✓
Radius Rods / Torque Arms	✓
Spring Shackles & Hanger Brackets	✓
King Pin Wear	✓
Spring Leaves / Shocks / Air Bags	✓
Front Axle Beam for Cracks or Obvious Welded Repairs	✓
Wheel Bearing Play	✓
Front Hub Lubricant Level / Leaks	✓
ENGINE COMPARTMENT:	
Engine Oil Level	✓
Cranking System: Visual Inspection Loose Connections	✓
Cab, Chassis Grounds	✓
Steering Gear - Fluid Level	✓
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	✓
Drive Belt(s) Condition	✓
Drive Belt(s) Adjustment	✓
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	✓
Fan Assembly & Idler Pulley	✓
Fan Clutch & Over-Ride Operation	✓
Radiator - Exterior Condition	✓
Radiator Mounting	✓
Hose Condition & Connections	✓
Air Conditioning Compressor / Condenser Mounts / Leaks	✓
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec	
SCA's OK_____ Undercharged_____ Overcharged_____	
Coolant Level	✓
Coolant Protection (Freeze Point):_____° (degrees Fahrenheit / Celcius)	✓
Pressure Test / Check Leaks	✓
Air Cleaning Mounting / Interference	✓
Contaminent Accumulation	✓
Vacuator Valve - Operation & Condition	✓

DRIVER'S COMMENTS:

CHARTER REQUIREMENTS:	
One Spare Key	✓
Top off all Fluids	✓
A/C Works	✓
Air Blows Out of all Vents	✓
Clean RH View Window	N
Chrome Kit	✓
Order Clean Idle Stickers if not there	✓
Repair all Air Leaks	✓
Replace Red & Yellow Brake Knob if faded	✓
New Charter Flaps w/ Straight Hangers	N
Operate all attached equipment	✓

FOR DEALERSHIP USE ONLY

☑ This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection

VIN # L0687287

(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: Jim Perez

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

APPROVED BY:_____

CUSTOMER SIGNATURE REQUIRED HERE

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

This inspection complies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: October 28, 2026 9:59 AM
Print Date: October 28, 2026 9:59 AM

VIN	1XPBAP8XXLD687287
Vehicle Make	Peterbilt
Model	579
Series	
Model Year	2020
Unit Number	U13699P

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	PACCAR MX 13 EPA 17	Y196385	PC4_H1520P201A HP201A-10082 NA08b MY2019 EPA17 CMPNENT 37 CMPNENT 38 2312664	J1939 (High) /15765 (CAN)
Transmission	PACCAR TX-12	Z0051416	2399316 274.26.0 2149627 E003.e002 2390050 422.2 5538105 6 8888884 0.0	J1939 (High)
Brakes	Bendix EC-80 ATC ABS	2Y44180811	Z091288	J1939 (High) /15765 (CAN)
VECU	PACCAR VECU	N/A	2320818	J1939 (High) /15765 (CAN)
Cab Controller - Primary	PACCAR CECU3 500K	N/A	P30-1041	J1939 (High) /15765 (CAN)
Shift Console - Primary	PACCAR Right Hand Stalk Switch	N/A	S01926B00_D01	J1939 (High)

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: October 28, 2026 9:59 AM
Print Date: October 28, 2026 9:59 AM

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	6.70 mpg
Battery Potential	13.80 volts
Total Idle Hrs	7,616.80 hrs
Idle Shutdown	Not Available
Road Speed Limit	Not Available
PTO Status	Off/Disabled
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	651 rpm
Exhaust System High Temperature Lamp Command	Off
ABS Control Status, Trailer	Off
Engine Odometer	330,796.22 mi
Fuel	40%
Diesel Exhaust Fluid	91%

Description	Parameter Value
Idle Fuel Used	5,102.40 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	16,953.90 hrs
Cruise Spd Limit	Not Available
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Off
ABS Control Status	Off
Odometer	330,796.22 mi
Instrument Cluster Odometer	330,796.22 mi
Coolant	Normal

Vehicle Issues

No Active Fault(s) Present

Faults

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____

Date _____