Truck Service Summary - Unit U13675

2020 Peterbilt 579

Inspection & Preparation

- Completed Charter PM inspection
- Greased chassis and checked/topped fluids
- Completed full interior and exterior detail and decal removal
- Verified lights, horn, keys, fire extinguisher and road flare kit

Mechanical Repairs

- Replaced crankcase ventilation filter and cleared faults
- Replaced both fuel filters and serviced air dryer
- Replaced cracked exhaust bellow and gaskets
- Replaced both rear drive torque rods

Electrical & Lighting

- Replaced two front clearance/marker lamps
- Repaired inoperative license plate light
- Removed aftermarket dash/OBD jumper harnesses
- Replaced rear tail-light grommets and reflectors

Cab & Interior

- Replaced both damaged door lock rods
- Replaced driver seat tilt handle
- Replaced dirty cabin and intake air filters
- Secured loose Bluetooth microphone

Exterior & Visibility

- Replaced both windshield wiper blades
- Installed Charter mudflaps and reflector plates
- Removed roof-fairing brackets
- Replaced missing valve-stem caps and aired tires

Add-Ons & General Service

- Installed chrome hub cover
- Cut and supplied two additional keys
- Set maximum road speed/RPM parameters
- Replaced worn cowl tray seal

Additional Work Performed

- Replaced broken fifth-wheel slider bulkhead fitting/airline
- Installed rear crossmember reflectors
- Verified repaired lighting operation

Final Service

- Cleared engine fault codes after repair
- Verified truck systems during final inspection
- Completed sale-ready exterior preparation

Summary

U13675 received a work-ready inspection, full exterior detail, engine fault diagnosis and crankcase ventilation repair, fuel and air-dryer service, suspension and exhaust repairs, lighting and visibility repairs, cab hardware and filter replacements, Charter add-ons, and final sale-ready preparation.

Total Reconditioning Investment: **$6,010.68**

Source: scanned invoice packet, pages reviewed visually.

COAST COUNTIES Peterbilt Since 1949

PREVENTATIVE MAINTENANCE SERVICE & INSPECTION

Silver Level Inspection

CUSTOMER NAME: CHARTER SALES COMPANY	DATE 9-23-26	ODOMETER / ENGINE HOURS / FUEL 244,137	REPAIR ORDER # 91679
ADDRESS: 27000 ASTI RD. CLOVERDALE, CA 95425	UNIT NO. 13675	VIN # (LAST 7 DIGITS) D686480	VEHICLE MAKE & MODEL Pete 579
	PHONE: 707.669.6202	DEALER NAME & CODE C506	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

V = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:		REAR FRAME	
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	✓	Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	✓
Air Leaks	✓	5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	✓
Headlights - High & Low Beams	✓	Air Lines & Glad-hands	✓
Road Lights	✓	Trailer Light Cord & Connectors	✓
Clearance Lights / Reflectors	✓	Pintle - Hook / Eye Mounting & Condition	✓
Turn Lights	✓	Inner & Outer Hub Seals Leaks	✓
Brake Lights	✓	Spring Shackles & Hanger Brackets	✓
Emergency Flasher	✓	Spring Leaves / Bushings / Shocks / Air Bags	✓
Backup / Load Lights	✓	Radius Rods / Torque Arms	✓
License Plates, Permits & Mounting	✓	**TIRES & WHEELS:**	
Mud Flaps / Serviceable	✓	Missing Valve Caps / Tighten Stem Locks	✓
Fuel Tank Mounting / Filler Cap in Place	✓	Cracks or Loose Wheel Lugs	✓
Fuel Crossover Line (Droop, Damage) If equipped	✓	Tire Pressure (Record Below)	✓
Exhaust System-Condition, Leaks & Mounting Bolts	✓	Remaining Tread (Record Below)	✓
INITIAL DRIVE IN:			
Clutch Pedal Free Travel	✓		
Parking Brake - Brakes applied upon activation of control	✓		
Glass for Cracks or Chips	✓		
Steering Wheel Free Play & Column Mounting	✓		
Door Window Operation	✓		
Interior Lights	✓		
Cranking System Operation	✓		
Gauges / Warning Lights - Illumination / Operational:	✓		
Maintain Low Idle	✓		
Oil Pressure	✓		
Low Air Pressure Warning Devices	✓		
Air Cleaner Restriction Gauge	✓		
Electronic Warning Module / A&B Cluster Lights On/Off	✓		
Governed Air Pressure: 120 PSI - KpA	✓		
Air Pressure Drop-Brakes Not Applied: 0 (PSI - KpA/min.)	✓	**CHASSIS LUBE - BEGIN:**	
Air Pressure Drop-Brakes Applied: 5 (PSI - KpA/min.)	✓	Lubricate Door Hinges & Latches	✓
Windshield Wiper / Washer Condition & Operation	✓	Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	✓
Horns (Electric & Air)	✓	**UNDER VEHICLE:**	
Mirrors / Heated / Motorized Operation	✓	Rear Axle Leaks & Lubricant Level	✓
Drain Water from Air Tanks	✓	Rear Axle Breathers - Clear	✓
Air Tank Check Value	✓	Drive Lines - U-Joints & Slip Yokes	✓
Emergency Operation of Spring Brakes	✓	Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	✓
Tractor Protection Valve Breakaway Test	✓	Adjust Brakes - Check Auto Slack Adjusters	✓
Fire Extinguisher Charge	✓	Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY	
Flare Kit / Reflectors - Readily Accessible	✓		
BATTERIES:			
Hold-Down & Box-Mounting Bolts	✓		
Signs of Over-Charging - Visual Inspection	✓		

Sealed Type - Condition:

Color of Charge Indicator for Each Battery

1.) 2.) 3.) 4.)

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle Driver Side:	PSI: 100	
	32nd's: 17	
Front Tandem Driver Side:	PSI: 100	PSI: 100
	32nd's: 26	32nd's: 26
Rear Tandem Driver Side	PSI: 100	PSI: 100
	32nd's: 23	32nd's: 23
Front Axle Pass. Side:	PSI: 100	
	32nd's: 17	
Front Tandem Pass. Side:	PSI: 100	PSI: 100
	32nd's: 26	32nd's: 26
Rear Tandem Pass. Side:	PSI: 100	PSI: 100
	32nd's: 23	32nd's: 23

Air Pressure Adjusted to Front Tires: 100 Rear Tires: 100

Circle one for each:

Front Axle L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Axle R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

UNDER VEHICLE (continued):	
Drum Condition - Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY	
Front Axle L: Good	
Front Axle R: good	
Front Tandem L: good	
Front Tandem R: good	
Rear Tandem L: good	
Rear Tandem R: good	
Transmission Leaks & Lubricant Level	✓
Engine & Transmission Mounts	✓
Engine Oil Pan Plug - Reinstall	✓
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	✓
Steering Shaft Splines & Joint(s)	✓
Pitman Arm	✓
Drag Link	✓
Steering Arms	✓
Tie Rod Arms	✓
Tie Rod Ends	✓
Radius Rods / Torque Arms	✓
Spring Shackles & Hanger Brackets	✓
King Pin Wear	✓
Spring Leaves / Shocks / Air Bags	✓
Front Axle Beam for Cracks or Obvious Welded Repairs	✓
Wheel Bearing Play	✓
Front Hub Lubricant Level / Leaks	✓
ENGINE COMPARTMENT:	
Engine Oil Level	✓
Cranking System: Visual Inspection Loose Connections	✓
Cab, Chassis Grounds	✓
Steering Gear - Fluid Level	✓
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	✓
Drive Belt(s) Condition	✓
Drive Belt(s) Adjustment	✓
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	✓
Fan Assembly & Idler Pulley	✓
Fan Clutch & Over-Ride Operation	✓
Radiator - Exterior Condition	✓
Radiator Mounting	✓
Hose Condition & Connections	✓
Air Conditioning Compressor / Condenser Mounts / Leaks	✓
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec	
SCA's OK_____ Undercharged_____ Overcharged_____	
Coolant Level	✓
Coolant Protection (Freeze Point): -34 ° (degrees Fahrenheit / Celcius)	✓
Pressure Test / Check Leaks	✓
Air Cleaning Mounting / Interference	✓
Contaminent Accumulation	✓
Vacuator Valve - Operation & Condition	✓

DRIVER'S COMMENTS:

CHARTER REQUIREMENTS:	
One Spare Key	✓
Top-off all Fluids	✓
A/C Works	✓
Air Blows Out of all Vents	✓
Clean RH View Window	✓
Chrome Kit	✓
Order Clean Idle Stickers if not there	✓
Repair all Air Leaks	✓
Replace Red & Yellow Brake Knob if faded	✓
New Charter Flaps w/ Straight Hangers	✓
Operate all attached equipment	✓

FOR DEALERSHIP USE ONLY

☑ This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection

VIN # D6864 80

(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: [signature]

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

APPROVED BY:_____

CUSTOMER SIGNATURE REQUIRED HERE

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

This inspection complies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: September 30, 2026 3:36 PM
Print Date: September 30, 2026 3:36 PM

VIN	1XPBDP9X2LD686480
Vehicle Make	Peterbilt
Model	579
Series	
Model Year	2020
Unit Number	U13675

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	PACCAR MX 13 EPA 17	Y195356	PC4_H1520P201A HP201A-10082 NA08b MY2019 EPA17 CMPNENT 37 CMPNENT 38 2312664	J1939 (High) /15765 (CAN)
Transmission	PACCAR TX-12	Z0049130	2399316 274.26.0 2149627 E003.e002 2390050 422.2 5538105 6 8888884 0.0	J1939 (High)
Brakes	Bendix EC-80 ESP ABS	6204190725	Z091290	J1939 (High) /15765 (CAN)
VECU	PACCAR VECU	N/A	2320818	J1939 (High) /15765 (CAN)
Cab Controller - Primary	PACCAR CECU3 500K	N/A	P30-1041	J1939 (High) /15765 (CAN)
Forward Road Image Processor	Bendix AutoVue® FLC20™ Camera	N/A	BX160710	J1939 (High) /15765 (CAN)
Headway Controller	Bendix Wingman® FLR21™ Radar Sensor	190503219	BX180203	J1939 (High) /15765 (CAN)
Shift Console - Primary	PACCAR Right Hand Stalk Switch	N/A	S01926B00_D01	J1939 (High)
Web Portal Processor	Bendix SafetyDirect® Web Portal Processor	19W042C7G	SDP NA-39.8-21-10.0	J1939 (High) /15765 (CAN)

LENOX
MOBILE TRUCK REPAIR

JPRO ® DIAGNOSTIC REPORT

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: September 30, 2026 3:36 PM
Print Date: September 30, 2026 3:36 PM

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	6.80 mpg
Battery Potential	13.50 volts
Total Idle Hrs	2,671.40 hrs
Idle Shutdown	Not Available
Road Speed Limit	Not Available
PTO Status	Not Available
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	651 rpm
Exhaust System High Temperature Lamp Command	Off
ABS Control Status, Trailer	Off
Engine Odometer	151,722.17 mi
Fuel	52%
Diesel Exhaust Fluid	85%

Description	Parameter Value
Idle Fuel Used	1,754.20 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	6,259.40 hrs
Cruise Spd Limit	Not Available
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Off
ABS Control Status	Off
Odometer	151,722.17 mi
Instrument Cluster Odometer	151,722.17 mi
Coolant	Normal

Vehicle Issues

No Active Fault(s) Present

Faults

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____

Date _____