Truck Service Summary – Unit U13279

2021 Kenworth T680

Inspection & Preparation

- Completed Multi point PM inspection
- Performed Clean Truck/CARB checks and passed

Exterior & Visibility

- Replaced broken left hood latch
- Installed 4 new rear rear axle drive tires
- washed exterior

Mechanical Repairs

- Serviced rear wheel seal and adjusted bearing
- Replaced rear shocks and quarter-fender top flaps
- Replaced EGR flex pipe
- Replaced loose fifth wheel pivot pins and lubricated
- Installed axle gasket, seal kit and related hardware

Add-Ons & General Service

- Installed Charter mud flaps and add-on hardware
- Added DEF fluid
- Updated valve stems, valve caps and tire hardware

Air System

- Replaced air dryer cartridge and purge valve
- Replaced torn glad hands
- Verified air-system service components

Additional Work Performed

- Replaced air filter
- Polished aluminum for final sale presentation

Electrical & Lighting

- Replaced driver mirror/window control module
- Installed five new cab clearance lights
- Replaced missing headlight cover/liner
- Replaced all three batteries and cleared MIL faults

Final Service

- Confirmed sale-ready reconditioning complete

Cab & Interior

- Completed interior detail and cab clean-up
- Removed cab roof fairing

Summary

Inspection, mechanical repairs, rear axle tires, lighting, air-system service, detailing, and final CARB checks completed for sale-ready delivery.

Eliminate downtime. if the wheels aren't turning, you're not earning.

Total Reconditioning Investment: **$10,499.69**

COAST COUNTIES Peterbilt

Retail B

PREVENTATIVE MAINTENANCE SERVICE & INSPECTION

Silver Level Inspection

CUSTOMER NAME: CHARTER SALES COMPANY	DATE 4-17-25	ODOMETER / ENGINE HOURS / FUEL 210,261	REPAIR ORDER # 88299
ADDRESS: 27000 ASTI RD. CLOVERDALE, CA 95425	UNIT NO. U13279	VIN # (LAST 7 DIGITS) MJ470515	VEHICLE MAKE & MODEL KW T680
	PHONE: 707.669.6202	DEALER NAME & CODE CCTE C-506	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

V = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:	B
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	✓
Air Leaks	✓
Headlights - High & Low Beams	✓
Road Lights	✓
Clearance Lights / Reflectors	✓
Turn Lights	✓
Brake Lights	✓
Emergency Flasher	✓
Backup / Load Lights	✓
License Plates, Permits & Mounting	✓
Mud Flaps / Serviceable	✓
Fuel Tank Mounting / Filler Cap in Place	✓
Fuel Crossover Line (Droop, Damage) If equipped	✓
Exhaust System-Condition, Leaks & Mounting Bolts	✓

INITIAL DRIVE IN:	B
Clutch Pedal Free Travel	✓
Parking Brake - Brakes applied upon activation of control	✓
Glass for Cracks or Chips	✓
Steering Wheel Free Play & Column Mounting	✓
Door Window Operation	✓
Interior Lights	✓
Cranking System Operation	✓
Gauges / Warning Lights - Illumination / Operational:	✓
Maintain Low Idle	✓
Oil Pressure	✓
Low Air Pressure Warning Devices	✓
Air Cleaner Restriction Gauge	✓
Electronic Warning Module / A&B Cluster Lights On/Off	✓
Governed Air Pressure: 140 PSI - KpA	✓
Air Pressure Drop-Brakes Not Applied: 0 (PSI - KpA/min.)	✓
Air Pressure Drop-Brakes Applied: 0 (PSI - KpA/min.)	✓
Windshield Wiper / Washer Condition & Operation	✓
Horns (Electric & Air)	✓
Mirrors / Heated / Motorized Operation	✓
Drain Water from Air Tanks	✓
Air Tank Check Value	✓
Emergency Operation of Spring Brakes	✓
Tractor Protection Valve Breakaway Test	✓
Fire Extinguisher Charge	✓
Flare Kit / Reflectors - Readily Accessible	✓

BATTERIES:	B
Hold-Down & Box-Mounting Bolts	✓
Signs of Over-Charging - Visual Inspection	✓

Sealed Type - Condition:

Color of Charge Indicator for Each Battery

1.) 2.) 3.) 4.)

REAR FRAME	B
Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	✓
5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	✓
Air Lines & Glad-hands	✓
Trailer Light Cord & Connectors	✓
Pintle - Hook / Eye Mounting & Condition	✓
Inner & Outer Hub Seals Leaks	✓
Spring Shackles & Hanger Brackets	✓
Spring Leaves / Bushings / Shocks / Air Bags	✓
Radius Rods / Torque Arms	✓

TIRES & WHEELS:	B
Missing Valve Caps / Tighten Stem Locks	✓
Cracks or Loose Wheel Lugs	✓
Tire Pressure (Record Below)	✓
Remaining Tread (Record Below)	✓

TIRE INSPECTION

Enter Air Pressure Before Adjustment

Front Axle Driver Side:	PSI: 110	
	32nd's: 20	
Front Tandem Driver Side:	PSI: 95	PSI: 95
	32nd's: 20	32nd's: 20
Rear Tandem Driver Side	PSI: 95	PSI: 95
	32nd's: 20	32nd's: 20
Front Axle Pass. Side:	PSI: 110	
	32nd's: 20	
Front Tandem Pass. Side:	PSI: 95	PSI: 95
	32nd's: 20	32nd's: 20
Rear Tandem Pass. Side:	PSI: 95	PSI: 95
	32nd's: 20	32nd's: 20

Air Pressure Adjusted to Front Tires: 110 Rear Tires: 95

CHASSIS LUBE - BEGIN:	B
Lubricate Door Hinges & Latches	✓
Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	✓

UNDER VEHICLE:	B
Rear Axle Leaks & Lubricant Level	✓
Rear Axle Breathers - Clear	✓
Drive Lines - U-Joints & Slip Yokes	✓
Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	✓
Adjust Brakes - Check Auto Slack Adjusters	✓

Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY

Circle one for each:

Front Axle L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Axle R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Front Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem L:	1/2" or more	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

UNDER VEHICLE (continued):	B
Drum Condition - Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY	
Front Axle L: G	
Front Axle R: G	
Front Tandem L: G	
Front Tandem R: G	
Rear Tandem L: G	
Rear Tandem R: G	
Transmission Leaks & Lubricant Level	✓
Engine & Transmission Mounts	✓
Engine Oil Pan Plug - Reinstall	✓
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	✓
Steering Shaft Splines & Joint(s)	✓
Pitman Arm	✓
Drag Link	✓
Steering Arms	✓
Tie Rod Arms	✓
Tie Rod Ends	✓
Radius Rods / Torque Arms	✓
Spring Shackles & Hanger Brackets	✓
King Pin Wear	✓
Spring Leaves / Shocks / Air Bags	✓
Front Axle Beam for Cracks or Obvious Welded Repairs	✓
Wheel Bearing Play	✓
Front Hub Lubricant Level / Leaks	✓

ENGINE COMPARTMENT:	B
Engine Oil Level	✓
Cranking System: Visual Inspection Loose Connections	✓
Cab, Chassis Grounds	✓
Steering Gear - Fluid Level	✓
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	✓
Drive Belt(s) Condition	✓
Drive Belt(s) Adjustment	✓
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	✓
Fan Assembly & Idler Pulley	✓
Fan Clutch & Over-Ride Operation	✓
Radiator - Exterior Condition	✓
Radiator Mounting	✓
Hose Condition & Connections	✓
Air Conditioning Compressor / Condenser Mounts / Leaks	✓
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec	
SCA's OK ✓ Undercharged_____ Overcharged_____	
Coolant Level	✓
Coolant Protection (Freeze Point):_____° (degrees Fahrenheit / Celcius)	✓
Pressure Test / Check Leaks	✓
Air Cleaning Mounting / Interference	✓
Contaminent Accumulation	✓
Vacuator Valve - Operation & Condition	✓

DRIVER'S COMMENTS:

CHARTER REQUIREMENTS:	
One Spare Key	✓
Replace Red & Yellow Brake Knobs if Faded	✓
Top-off all Fluids	✓
A/C Works	✓
Air Blows Out of all Vents	✓
Clean RH View Window	✓
New Charter Flaps w/ Straight Hangers	✓
Operate all Attached Equipment	✓
Chrome Kit	✓
Order Clean Idle Stickers if not there	✓
Plug all Holes in Dash	✓
Plug all Holes in Frame with Painted Bolt	✓
Repair all Air Leaks	✓

FOR DEALERSHIP USE ONLY

☐ **This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection**

VIN # MJ470515
(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: [signature]

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired item, component, or system.

APPROVED BY: [signature]
CUSTOMER SIGNATURE REQUIRED HERE

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

ection complies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: March 24, 2025 2:10 PM
Print Date: March 24, 2025 2:10 PM

VIN	1XKYDP9X7MJ470515
Vehicle Make	Kenworth
Model	T680
Series	
Model Year	2021
Unit Number	U13279

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	PACCAR MX 13 EPA 17	Y245203	PC4_E1520P201A EP201A-10082 06_c MY2020 EPA17 CMPNENT 37 CMPNENT 38 2312664	J1939 (High) /15765 (CAN)
Transmission	PACCAR TX-12	Z0134534	2274296 202.78.0 2149627 E003.e002 2293676 23.10 5538105 6	J1939 (High)
Brakes	Bendix EC-80 ESP ABS	6239204873	Z091290	J1939 (High) /15765 (CAN)
VECU	PACCAR VECU	N/A	2320818	J1939 (High) /15765 (CAN)
Shift Console - Primary	PACCAR Right Hand Stalk Switch	N/A	S01926A29_D01	J1939 (High)
Headway Controller	Bendix Wingman® FLR21™ Radar Sensor	203705644	BX190303	J1939 (High) /15765 (CAN)
Cab Controller - Primary	PACCAR CECU3 500K	N/A	P30-1041	J1939 (High) /15765 (CAN)
Forward Road Image Processor	Bendix AutoVue® FLC20™ Camera	1026	BX190310	J1939 (High) /15765 (CAN)
Web Portal Processor	Bendix SafetyDirect® Web Portal Processor	20W404E8B	SDP NA-39.8-21-14.0	J1939 (High) /15765 (CAN)

JPRO ® DIAGNOSTIC REPORT

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: March 24, 2025 2:10 PM
Print Date: March 24, 2025 2:10 PM

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	6.50 mpg
Battery Potential	12.00 volts
Total Idle Hrs	1,928.10 hrs
Idle Shutdown	Not Available
Road Speed Limit	64.00 mph
PTO Status	Not Available
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	0 rpm
Exhaust System High Temperature Lamp Command	Off
ABS Control Status, Trailer	Off
Engine Odometer	214,428.89 mi
Fuel	47%
Diesel Exhaust Fluid	71%

Description	Parameter Value
Idle Fuel Used	1,397.70 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	6,295.70 hrs
Cruise Spd Limit	64.00 mph
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Off
ABS Control Status	Not Available
Odometer	214,428.89 mi
Instrument Cluster Odometer	Not Available
Coolant	Normal

Vehicle Issues

No Active Fault(s) Present

Faults

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____

Date _____