COAST COUNTIES Peterbilt Since 1949

PREVENTATIVE MAINTENANCE SERVICE & INSPECTION

Silver Level Inspection

CUSTOMER NAME: CHARTER SALES COMPANY	DATE 11/03/26	ODOMETER / ENGINE HOURS / FUEL 73,595	REPAIR ORDER # 91957
ADDRESS: 27000 ASTI RD. CLOVERDALE, CA 95425	UNIT NO. 13707	VIN # (LAST 7 DIGITS) MM743676	VEHICLE MAKE & MODEL Peterbilt 337
	PHONE: 707.669.6202	DEALER NAME & CODE CCTE C506	

COMPLETE ALL OF THE INSPECTION AND SERVICE POINTS ACCORDING TO THE SERVICE WORKED ON AND INDICATE:

√ = OK O = REPAIR REQUIRED X = REPAIR COMPLETED N = NOT APPLICABLE

CIRCLE INSPECTION:		REAR FRAME	
Physical Damage, Sheet Metal, Frame & X-members, Grill & Radiator, Wheels, Bumpers	√	Frame & X-members - Cracks / Fasteners - Loose, Broken, Missing	√
Air Leaks	X	5th Wheel Mounting & Condition / Check Adjustment / Handle Locked	√
Headlights - High & Low Beams	√	Air Lines & Glad-hands	√
Road Lights	√	Trailer Light Cord & Connectors	√
Clearance Lights / Reflectors	√	Pintle - Hook / Eye Mounting & Condition	√
Turn Lights	√	Inner & Outer Hub Seals Leaks	√
Brake Lights	√	Spring Shackles & Hanger Brackets	√
Emergency Flasher	√	Spring Leaves / Bushings / Shocks / Air Bags	√
Backup / Load Lights	√	Radius Rods / Torque Arms	√
License Plates, Permits & Mounting	√	**TIRES & WHEELS:**	
Mud Flaps / Serviceable	√	Missing Valve Caps / Tighten Stem Locks	√
Fuel Tank Mounting / Filler Cap in Place	√	Cracks or Loose Wheel Lugs	√
Fuel Crossover Line (Droop, Damage) If equipped	√	Tire Pressure (Record Below)	√
Exhaust System-Condition, Leaks & Mounting Bolts	√	Remaining Tread (Record Below)	√
INITIAL DRIVE IN:		**TIRE INSPECTION**	
Clutch Pedal Free Travel	√	**Enter Air Pressure Before Adjustment**	
Parking Brake - Brakes applied upon activation of control	√	Front Axle Driver Side: PSI: 110 / 32nd's: 15	
Glass for Cracks or Chips	√		
Steering Wheel Free Play & Column Mounting	√	Front Tandem Driver Side: ~~PSI:~~ ~~32nd's:~~ / PSI: ~~32nd's:~~	
Door Window Operation	√		
Interior Lights	√	Rear Tandem Driver Side: PSI: 110 / 32nd's: 20 — PSI: 110 / 32nd's: 22	
Cranking System Operation	√		
Gauges / Warning Lights - Illumination / Operational:		Front Axle Pass. Side: PSI: 110 / 32nd's: 14	
Maintain Low Idle	√		
Oil Pressure	√	Front Tandem Pass. Side: ~~PSI:~~ ~~32nd's:~~ / PSI: ~~32nd's:~~	
Low Air Pressure Warning Devices	√		
Air Cleaner Restriction Gauge	√	Rear Tandem Pass. Side: PSI: 110 / 32nd's: 17 — PSI: 110 / 32nd's: 20	
Electronic Warning Module / A&B Cluster Lights On/Off	√		
Governed Air Pressure: 115 PSI - KpA	√	Air Pressure Adjusted to Front Tires: _____ Rear Tires: _____	
Air Pressure Drop-Brakes Not Applied: 0 (PSI - KpA/min.)	√	**CHASSIS LUBE - BEGIN:**	
Air Pressure Drop-Brakes Applied: 0 (PSI - KpA/min.)	√	Lubricate Door Hinges & Latches	√
Windshield Wiper / Washer Condition & Operation	√	Chassis Lubrication / 5th Wheel / Drive Line / Fan Hub	√
Horns (Electric & Air)	√	**UNDER VEHICLE:**	
Mirrors / Heated / Motorized Operation	√	Rear Axle Leaks & Lubricant Level	√
Drain Water from Air Tanks	√	Rear Axle Breathers - Clear	√
Air Tank Check Value	√	Drive Lines - U-Joints & Slip Yokes	√
Emergency Operation of Spring Brakes	√	Brake Hoses for Cracks, Chafing, any damage extending thru Outer Ply	√
Tractor Protection Valve Breakaway Test	√	Adjust Brakes - Check Auto Slack Adjusters	√
Fire Extinguisher Charge	√	Brakes: Lining Remaining - Estimate of thickness - NO DISASSEMBLY	
Flare Kit / Reflectors - Readily Accessible	√		
BATTERIES:			
Hold-Down & Box-Mounting Bolts	√		
Signs of Over-Charging - Visual Inspection	√		
Sealed Type - Condition:			

Color of Charge Indicator for Each Battery

1.) green 2.) green 3.) green 4.) green

Circle one for each:

Front Axle L:	~~1/2" or more~~	1/4" to 1/2"	Less than 1/4"
Front Axle R:	1/2" or more	~~1/4" to 1/2"~~	~~Less than 1/4"~~
Front Tandem L:	~~1/2" or more~~	~~1/4" to 1/2"~~	~~Less than 1/4"~~
Front Tandem R:	~~1/2" or more~~	1/4" to 1/2"	~~Less than 1/4"~~
Rear Tandem L:	~~1/2" or more~~	1/4" to 1/2"	Less than 1/4"
Rear Tandem R:	1/2" or more	1/4" to 1/2"	Less than 1/4"

This Inspection complies with the DOT Federal Annual Inspection requirements

UNDER VEHICLE (continued):	
Drum Condition - Visual Inspection: (Good, Fair, Bad) - NO DISASSEMBLY	
Front Axle L: Good	
Front Axle R: Good	
Front Tandem L: X	
Front Tandem R: X	
Rear Tandem L: Good	
Rear Tandem R: Good	
Transmission Leaks & Lubricant Level	✓
Engine & Transmission Mounts	✓
Engine Oil Pan Plug - Reinstall	✓
Steering Gear - Cracks & Leaks, Mounting Brackets Loose Fasteners	✓
Steering Shaft Splines & Joint(s)	✓
Pitman Arm	✓
Drag Link	✓
Steering Arms	✓
Tie Rod Arms	✓
Tie Rod Ends	✓
Radius Rods / Torque Arms	✓
Spring Shackles & Hanger Brackets	✓
King Pin Wear	✓
Spring Leaves / Shocks / Air Bags	✓
Front Axle Beam for Cracks or Obvious Welded Repairs	✓
Wheel Bearing Play	✓
Front Hub Lubricant Level / Leaks	✓
ENGINE COMPARTMENT:	
Engine Oil Level	✓
Cranking System: Visual Inspection Loose Connections	✓
Cab, Chassis Grounds	✓
Steering Gear - Fluid Level	✓
Check Hydraulic Brake Fluid Level (Medium Duty - If Applicable)	✓
Drive Belt(s) Condition	✓
Drive Belt(s) Adjustment	✓
Air Comparessor & Pulley, Mtg Brackets; Broken, Cracked, Loose Parts	✓
Fan Assembly & Idler Pulley	✓
Fan Clutch & Over-Ride Operation	✓
Radiator - Exterior Condition	✓
Radiator Mounting	✓
Hose Condition & Connections	✓
Air Conditioning Compressor / Condenser Mounts / Leaks	✓
Cooling: Check Supplemental Coolant Additive / Condition to Mfg Spec	
SCA's OK X Undercharged_____ Overcharged_____	
Coolant Level	✓
Coolant Protection (Freeze Point):_____° (degrees Fahrenheit / Celcius)	✓
Pressure Test / Check Leaks	✓
Air Cleaning Mounting / Interference	✓
Contaminent Accumulation	✓
Vacuator Valve - Operation & Condition	✓

DRIVER'S COMMENTS:

CHARTER REQUIREMENTS:	
One Spare Key	
Top-off all Fluids	
A/C Works	✓
Air Blows Out of all Vents	✓
Clean RH View Window	✓
Chrome Kit	✓
Order Clean Idle Stickers if not there	✓
Repair all Air Leaks	✓
Replace Red & Yellow Brake Knob if faded	✓
New Charter Flaps w/ Straight Hangers	✓
Operate all attached equipment	✓

FOR DEALERSHIP USE ONLY

☐ **This inspection has been completed and complies with FMCSR49CFR, 396.17-23 DOT Annual Inspection**

VIN # MM743676

(Last 7 Digits Required for Annual Inspection)

INSPECTED BY: _____

I acknowledge that all items noted on this form as requiring repair(s) have been explained to me. I further accept responsibility for all items indicated on this form requiring repair, that were not repaired at my direction, and shall indemnify and hold harmless the Dealer, Peterbilt Motors Company, PCC, and PACCAR Inc, their officers, directors, and employees, from and against any and all claims, suits, damages, costs, losses, and expenses, including attorney's fees, in any manner resulting from or arising out of the failure of an unrepaired part, component, or system.

APPROVED BY: _____

CUSTOMER SIGNATURE REQUIRED HERE

OTHER - INSPECTIONS EXPIRATION DATE:

California BIT 90 Days

This inspection complies with the DOT Federal Annual Inspection requirements

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: November 11, 2026 11:33 AM
Print Date: November 11, 2026 11:33 AM

VIN	2NP2HM6X2MM743676
Vehicle Make	Peterbilt
Model	337
Series	
Model Year	2021
Unit Number	U13707

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	Cummins B6.7	74640570	04384413 22592732 080422210856 22702070 G1 BGU 02030108	J1939 (High)
Transmission	Allison 1000/2000 5th Gen	BK6882A100275390	L18BCD_PC_868 B18200017D23E	J1939 (High) /15765 (CAN)
Brakes	Bendix EC-80 ATC ABS	2Y28192771	Z091288	J1939 (High) /15765 (CAN)
Shift Console - Primary	PACCAR Right Hand Stalk Switch	N/A	250_04 1501 206	J1939 (High)
Cab Controller - Primary	PACCAR CECU3	N/A	N/A	J1939 (High)

JPRO ® DIAGNOSTIC REPORT

LENOX
MOBILE TRUCK REPAIR

Lenox Mobile Truck Repair LLC.
327 Pepperwood Drive Cloverdale, CA 95425

Connection Date: November 11, 2026 11:33 AM
Print Date: November 11, 2026 11:33 AM

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	10.60 mpg
Battery Potential	12.70 volts
Total Idle Hrs	397.00 hrs
Idle Shutdown	5.00 min
Road Speed Limit	80.00 mph
PTO Status	Enable
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	0 rpm
Exhaust System High Temperature Lamp Command	Off
ABS Control Status, Trailer	Not Available
Engine Odometer	73,619.52 mi
Fuel	22%
Diesel Exhaust Fluid	33%

Description	Parameter Value
Idle Fuel Used	214.50 gal
DPF Soot Level	Low
DPF Derate	Low
Total Engine Run Time	1,944.50 hrs
Cruise Spd Limit	64.00 mph
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Off
ABS Control Status	Not Available
Odometer	73,619.52 mi
Instrument Cluster Odometer	73,619.52 mi
Coolant	Normal

Vehicle Issues

No Active Faults

Faults

Status	Component	Description	Lookup Code	FMI	Count

The buyer acknowledges that no guarantees are made as to actual hours/miles/kilometers. The inspection report reflects what can be visually observed.

Sign _____

Date _____